

Date: 07/04/2022
 Vehicle No: SLZ2202S
 Model: TESLA MODEL 3 STANDARD RANGE
 Chassis: LRW3F7FA5MC384458
 Reg.Year: 2021

Third Party Insurer: AIG
 Third Party Veh No: GBG7894E
 Date of Accident: 07/04/2022
 Estimator: KIT
 Surveyor:

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	REAR DOOR LH	1		REPAIR
			SUB TOTAL	\$0.00
			LESS 10%	\$0.00
			PARTS TOTAL	\$0.00

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST ACCIDENT AREAS & ETC.

rr \$200.00 X

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT ACCIDENT AREAS & ETC.

\$300.00 2400

LABOUR TOTAL \$500.00

KIT TOTAL \$500.00

Not withair
 Repair After Rain
 1 day

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: