

Company Reg No: 202136904Z

Tel : 6341 6789 Fax: 6341 6778
E-mail:hdperfectautowork@gmail.com



DATE : 11.04.2022

✓ SS222NH2K1011814.

CLAIM DETAIL : PARTS				
S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT BUMPER <i>Delhd</i>	1	\$ 1,658.00	\$ 1,658.00
2	FRONT BUMPER TOWING COVER <i>Delhd</i>	1	\$ 45.00	\$ 45.00
3	FRONT BUMPER FOG LAMP <i>LH cndd</i>	2	\$ 586.00	\$ 1,172.00
4	FRONT BUMPER FOG LAMP COVER <i>RA cut</i>	2	\$ 486.00	\$ 972.00
5	FRONT BUMPER LOWER GRILLE <i>Delhd</i>	1	\$ 384.00	\$ 384.00
6	FRONT BUMPER INNER LOWER GARNISH <i>Delhd</i>	1	\$ 364.00	\$ 364.00
7	FRONT BUMPER SIDE RETAINER <i>mm</i>	2	\$ 185.30	\$ 370.60
8	FRONT BUMPER REINFORCEMENT <i>Delhd</i>	1	\$ 710.30	\$ 710.30
9	FRONT BUMPER SPONGE <i>cndd.</i>	1	\$ 488.00	\$ 488.00
10	FRONT FENDER <i>LH Buckeled</i>	2	\$ 1,125.60	\$ 2,251.20
11	FRONT FENDER INNER COWLING <i>mm</i>	2	\$ 389.60	\$ 779.20
12	FRONT HEADLAMP <i>lt</i>	2	\$ 1,842.00	\$ 3,684.00
13	FRONT HEADLAMP PANEL <i>LH Buckeled</i>	2	\$ 298.00	\$ 596.00
14	FRONT HEADLAMP LOWER BRACKET. <i>mm</i>	2	\$ 205.00	\$ 410.00
15	FRONT GRILLE C/W CHROME <i>cndd</i>	1	\$ 782.00	\$ 782.00
16	FRONT GRILLE LOGO <i>mm</i>	1	\$ 96.00	\$ 96.00
17	BONNET <i>Delhd</i>	1	\$ 1,754.00	\$ 1,754.00
18	BONNET HINGE <i>mm</i>	2	\$ 86.00	\$ 172.00
19	BONNET INNER LOCK <i>Delhd</i>	1	\$ 320.00	\$ 320.00
20	BONNET INSULATOR <i>mm</i>	1	\$ 367.00	\$ 367.00
21	FRONT WIPER PANEL GARNISH <i>mm</i>	1	\$ 486.00	\$ 486.00
22	FRONT WINDSCREEN GLASS <i>lt</i>	1	\$ 1,837.90	\$ 1,837.90
23	FRONT SUPPORT PANEL <i>cndd</i>	1	\$ 1,178.60	\$ 1,178.60
24	FRONT SUPPORT PANEL TOP GARNISH <i>Delhd</i>	1	\$ 186.00	\$ 186.00
25	HORN <i>mm</i>	2	\$ 154.00	\$ 308.00
26	OUTSIDE TEMPERATURE SENOSR <i>mm</i>	1	\$ 94.30	\$ 94.30

TO : AXA MOTOR CLAIMS DEPTS
 VEHICLE NO : SMU1872D
 MODEL : SEAT TOLEDO
 DATE OF ACCIDENT : 03.04.2022
 TIME OF ACCIDENT : 17:20HRS

27	TURBO INTERCOOLER <i>Dented</i>	1	\$ 867.30	\$ 867.30
28	AIR DUCT <i>new</i>	1	\$ 86.00	\$ 86.00
29	RADIATOR <i>Dented</i>	1	\$ 1,649.20	\$ 1,649.20
30	RADIATOR FAN COWLING <i>3 new</i>	1	\$ 487.20	\$ 487.20
31	RADIATOR FAN MOTOR <i>lit</i>	1	\$ 359.40	\$ 359.40
32	AIRCON CONDENSER SIDE AIR GUARD <i>del</i>	2	\$ 86.00	\$ 172.00
33	AIRCON CONDENSER <i>Warpped</i>	1	\$ 1,438.00	\$ 1,438.00

18662.70
 16796.43

TOTAL PRICE \$ 26,525.20
 LESS 10% \$ 2,652.52
SUB TOTAL PRICE \$ 23,872.68

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	FRONT NUMBER PLATE <i>Dented</i>	1	\$ 80.00	\$ 80.00
2	FRONT BUMPER CLIP (SET) <i>new</i>	1	\$ 80.00	\$ 80.00
3	FRONT BUMPER LOWER GRILLE CLIP (SET) <i>new</i>	1	\$ 80.00	\$ 80.00
4	FRONT BUMPER INNER LOWER GARNISH CLIP (SET) <i>new</i>	1	\$ 80.00	\$ 80.00
5	FRONT FENDER INNER COWLING CLIP (SET) <i>new</i>	1	\$ 80.00	\$ 80.00
6	BONNET SEALANT <i>new</i>	1	\$ 150.00	\$ 150.00
7	BONNET INSULATOR CLIP (SET) <i>new</i>	1	\$ 80.00	\$ 80.00
8	FRONT SUPPORT PANEL TOP GARNISH CLIP (SET) <i>new</i>	1	\$ 60.00	\$ 60.00
9	RADIATOR COOLANT <i>new</i>	1	\$ 180.00	\$ 180.00

TOTAL \$ 920.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (FRONT)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 2,200.00	1000
2	TO SPRAY PAINT AFFECTED AREA	\$ 2,000.00	600.
3	TUFF COAT	\$ 350.00	30
4	WIRING CHECK	\$ 180.00	30
5	REMOVE AND REFIX CUSHION SEAT/ UPHOLSTRY AND ROOF LINNING TO FACILITATE REPAIR	\$ 380.00	X
6	REFOCUS HEADLAMP BEAM	\$ 80.00	X
7	REMOVE AND REFIX AIRCON CONDENSOR AND REFILL AIRCON GAS	\$ 120.00	60

TO : AXA MOTOR CLAIMS DEPTS
VEHICLE NO : SMU1872D
MODEL : SEAT TOLEDO
DATE OF ACCIDENT : 03.04.2022
TIME OF ACCIDENT : 17:20HRS

8	REMOVE AND REFIX RADIATOR AND CONDUCT PRESSURE TEST	\$ 80.00	60
9	REMOVE AND REFIX TURBO COOLER	\$ 80.00	50
10	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 650.00	X

1830

TOTAL \$6,120.00

TOTAL PARTS COST : \$ 24,792.68
TOTAL LABOUR COST : \$ 6,120.00
TOTAL REPAIR COST : \$ 30,912.68

Adrian
2/5 13/10/22,
08 Days.

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.
PARTS PRICES ARE SUBJECT TO CHANGES.

total: 1880643

YOURS FAITHFULLY,

4/5: 1151K

IRENE

SERVICE ADVISOR
IRENE
HP : 8297 9787

15K

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: