

ASS. REC. BY:

REF:

AG2/ 22003499/K943

C

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD/TP/WS/TP RES/OD RES/EVA/INV/MY

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____ 241B

Policy No. _____

Claims No. C10014733/JM

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 843k

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 09 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SFV 5955A Yr Regn: 10, 14

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or _____

Make: Mer B180 C.C. 1595

Colour: M. Black A/C: Insured / Std / NI / NA

Sp. Reading: 116598 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WDD 2482422 J 271905

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/55R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front

R/Bal. 7 mm

L/Bal. 7 mm

D.O.A. 13/4/22

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear N/S & Frt

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

1 UTA return 825,729.00

1913 01 Rep 814,2001 Cumbr Ured 813177.70, 48%.

Date/Time, File Pass to?

1) 03/16 March ☐ : Prell. ReportDate/Time, File Return to? ☐ : Final Report

2)

Report Format :

Lump Sum / I.B.T. (\$) TP 14200

Days Of Repair: 9

Resurvey No. of Trip: 2

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

S + RS. \$

Fees

Others

TOTAL

Ready Auto Care Pte Ltd - We Care For All Your Car Needs

Blk 10 # 03-06 AMK Auto Point, Ang Mo Kio Ind Park 2A, Ang Mo Kio Ave 5. Singapore 568047

Tel : 64810304 Fax : 64815587

Reg No : 200600989K

Not Notified
11 Sep @ 14,200h
Returning After Repair
9 days

Budgetdirect

Motorcar Claim Department

Attn Officer In Charge

Estimate Repair

Date : 14/04/2022

Accident Involving SFV5955A & SLQ8936R On 13/4/2022 Along Changi Flyover

(1/2)

Item	Descriptions	Amount	
1	Front Bumper 1250	Per \$ 1,485.00	✓
2	LH Headlamp	CM \$ 2,340.00	✓
3	Radiator Grill	Ad/len \$ CM 792.00	✓
4	Radiator Grill Logo With Module	\$ 432.00	✓
5	Lower Grill	\$ Nil 102.60	✓
6	LH Inner Parking Sensor 220	Shen \$ 261.00	✓
7	LH Outer Parking Sensor 220	\$ Shen 234.00	✓
8	Front Bumper Reinforcement	\$ By 288.00	✓
9	Front Bumper Sponge	\$ CM 120.00	✓
10	Intercooler	\$ Per 774.00	✓
11	Aircon Condenser	\$ Su 306.00	✓
12	Radiator Assy	\$ Su 441.00	x
13	Support Panel Assy	\$ R 594.00	✓
14	Air Guide	\$ Nil 79.20	✓
15	Tail Gate	\$ By 1,800.00	✓
16	RL Reflector Lamp	\$ CM 396.00	✓
17	RL Tail Lamp	\$ CM 414.00	✓
18	Rear Windscreen Moulding	nn \$ Per 180.00	car x
19	Tail Gater Inner Trim Panel	\$ Su 895.00	✓
20	Rear Bumper	CM \$ 1,404.00	✓
21	Rear Bumper Step Garnish	\$ Per 248.40	✓
22	Rear Bumper Chrome RR & RL @\$153 X 2	nn \$ 306.00	✓
23	Rear Left Inner Parking Sensor 220	mm \$ 261.00	✓
24	Rear Right Inner Parking Sensor 220	Shen \$ 261.00	✓
25	Rear Bumper Lower Lib	\$ By 95.40	✓
26	Rear Bumper Retainer RR & RL @\$12.60 X 2	nil Nil \$ 25.20	✓
27	Rear Bumper Reinforcement	\$ By 432.00	✓
28	Rear End Panel	\$ By 1,260.00	✓
29	RL Seat Belt	\$ Tu 396.00	✓
30	RR Seat Belt	\$ Tu 396.00	✓
31	FR Seat Belt	\$ Su 396.00	✓
32	Airbag Control Module	\$ Su 810.00	✓
33	RH & LH Impact Sensor @\$171 x 2	\$ Su 342.00	✓
34	Radar Distance Sensor	CM \$ 1,206.00	✓

Total For Parts (Less 10%) \$ 19,772.80

To Be Continued



Accident Involving SFV5955A & SLQ8936R On 13/4/2022 Along Changi Flyover

(2/2)

<u>S/N Item (s)</u>				
1	Front Bumper Clips - 1 Set	\$	28.00	✓
2	Rear Bumper Clips - 1 Set	\$	28.00	✓
3	Front Mercedes Logo	\$	70.20	✓
4	Original Coolant	\$	30.00	✓
5	" B180" Emblem	\$	75.60	✓
6	Mercedes Logo - Rear	\$	50.40	✓
7	Rear Windscreen Sealant	\$	40.00	✓
8	Reverse Camera	\$	450.00	✓
9	Front Number Plate With Frame	\$	35.00	✓
10	Towing Service	(Bill) \$	117.70	✓
Total For S/N		\$	924.90	

<u>Labour & Misc</u>				
1	To Remove All Damaged Parts, Knock Out Dents, Jack Out Damaged Panel	\$	2,400.00	1200
2	Panel, Adjust, Replace, Reshape, Cut, Weld, Refix & Realign Body Structure	\$	1,800.00	1300
3	Spray Painting For New And Repair Parts Including Supply Of Paints Materials	\$	250.00	150
4	Computerise Reprogramming SRS, Rear Distance Sensor, Parking Sensor Memory	\$	680.00	120
5	Remove & Replace RL, RR & FR Seat Belt & Airbag Control Module	\$	450.00	120
6	Remove & Replace Impact Sensor & Radan Distance Sensor	\$	580.00	250
7	Online Coding Radar Distance Sensor	\$	100.00	✓
8	Renew Aircon Parts, Vacuum & Refill R134a Aircon Gas	\$	50.00	40
9	Check Font & Rear Wiring, Lighting System For Proper Function	\$	150.00	120
10	Remove & Refix Rear Windscreen To Facilitate Repair	\$	100.00	60
11	To Remove & Refit Rear Boot Upholstery etc To Facilitate Repair	\$	120.00	80
		\$	6,680.00	

Total For Parts & Labour \$ 27,377.70

Ready Auto Care Pte Ltd
Sulynn - 64810304

No Of Days For Repair 9 Days ✓



LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: