

SM AUTOMOTIVE

Block C, 1 Kaki Bukit Avenue 6 #01-43 Singapore 417883

Email: SM_AUTOMOTIVE@HOTMAIL.COM

Tel: (65) 6747 9241 Fax: (65) 6741 7276

RCB No.: 53231488C

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

Accident date : 13/04/2022

Estimated repair cost for vehicle no: SJG3330Y TOYOTA VIOS E AUTO

CHASSIS: MR053HY9305076253 (2008)

14/04/2022

S/N	Qty	Items	U/price	Amount
1	1	REAR BUMPER <i>Rehd</i>	\$547.90	\$547.90 <i>418</i>
2	1	REAR BUMPER SIDE RETAINER <i>Lt Dnd</i>	\$74.60	\$149.20 <i>74.60 35</i>
3	1	REAR END PANEL <i>new</i>	\$455.60	\$455.60 <i>298</i>
4	1	REAR TAILLAMP <i>Lt Cnd</i>	\$357.00	\$714.60 <i>357</i>
5	1	REAR TAILLAMP LOWER BRACKET <i>new</i>	\$63.10	\$126.20 <i>x</i>
6	1	REAR TAILLAMP INNER PANEL <i>Regr</i>	\$140.70	\$281.40 <i>x</i>
7	1	LH REAR FENDER <i>Regr</i>	\$865.10	\$865.10 <i>x</i>
8	1	LH REAR FENDER INNER COWLING <i>new</i>	\$58.60	\$58.60 <i>x</i>
9	1	FUEL FLAP <i>new</i>	\$115.30	\$115.30 <i>x</i>
10	1	REAR AXLE <i>Bent</i>	\$1,496.70	\$1,496.70 <i>x</i>
11	1	LH REAR SHOCK ABSORBER <i>Bent</i>	\$397.40	\$397.40 <i>x</i>
12	1	LH REAR WHEEL BEARING <i>Dnd</i>	\$198.20	\$198.20 <i>x</i>
13	2	REAR WINDSCREEN GLASS MOULDING <i>new</i>	\$187.30	\$187.30 <i>x</i>

290330

287747

TOTAL :	\$5,593.50
LESS 25 %	\$1,398.38
SUB-TOTAL :	\$4,195.13

S/N	Qty	ITEMS / SPECIAL NETT	U/price	Amount
1	1	REAR BUMPER CLIPS <i>new</i>	\$80.00	\$80.00 <i>30</i>
2	1	REAR BUMPER LOWER SPOILER <i>Reh d</i>	\$450.00	\$450.00 <i>✓</i>
3	1	REAR BUMPER LOWER SPOILER SEALANT <i>new</i>	\$100.00	\$100.00 <i>50</i>
4	1	REAR TAILLAMP CLIPS <i>new</i>	\$12.00	\$12.00 <i>✓</i>
5	1	REAR END PANEL SEALANT <i>new</i>	\$80.00	\$80.00 <i>+</i>
6	1	REAR WINDSCREEN GLASS SEALANT <i>new</i>	\$120.00	\$120.00 <i>60 +</i>
7	1	LH REAR SPORT RIM <i>ht</i>	\$560.00	\$560.00 <i>480</i>
8	1	LH REAR TYRE <i>new</i>	\$280.00	\$280.00 <i>+</i>

1022

TOTAL: \$1,682.00

TOTAL PARTS: \$5,877.13

Labour charges

1	LABOUR FOR PANEL BEATING	\$1,600.00 <i>400</i>
2	LABOUR FOR SPRAYPAINTING	\$1,200.00 <i>600</i>
3	WIRING CHECK	\$80.00 <i>30</i>
4	TO APPLY TUFF COATING/RUST PROOF ACCIDENT AREAS	\$300.00 <i>60</i>
5	LABOUR FOR REMOVE & REFIX REAR WINDSCREEN GLASS	\$200.00 <i>+</i>
6	LABOUR FOR REMOVE & REFIX FUEL TANK TO FACILITATE THE REPAIR	\$300.00 <i>+</i>
7	LABOUR FOR REMOVE & RENEW REAR UNDERCARRIAGE	\$300.00 <i>280</i>
8	TO CONDUCT WHEEL ALIGNMENT	\$150.00 <i>80</i>

Subtotal :- \$4,130.00

Total:- \$10,007.13

Admin
L/s 18/04/22.

05 Days

total: 4649.47

L/s: 3.7K

3.7K

05 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: