

ASS. REC. BY:

REF:

AG2/ 22003503/Ky

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 03 days Res.: Yes or NoLum Sum: 1.B.1 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SKN 9204R Yr Regn: 07 14Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Volkswagen Golf ^{A)} 1395Colour: N. Gray A/C: Insured / Std / NI / NASp. Reading: 61877 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WVW 777 AU ZFW 006514Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModl: Nil / S/Rlm / STD A/Rlm or

Tyre Size: F: _____

R: 225/45R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mm R/Bal. 4 mmL/Bal. 6 mm L/Bal. 4 mmD.O.A. 13/4/22 D.O.I. 18/5/2022

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

23/5 @ 2319-19 2449-19 = 76/22, confirmed. (5617.61) 70%

Date/Time, File Pass to?

☐ : Prell. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 3

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech Invs (\$☐ : Weekend (\$

Survey Fee:

Transportation:

S + RS. \$

Fees

Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$) 2449.199.30
Serene.

LIM YEW BOO SPRAY PAINT CO.

BLK 10, SIN MING INDUSTRIAL ESTATE, SECTOR C, #01-10 S'575645
 NO. 176, SIN MING DRIVE, #03-05, SIN MING AUTOCARE, S'PORE 575721
 Tel No. : 64534177 Fax No. : 64593724
 E-Mail : limyewboo@singnet.com.sg
 Website : www.limyewboo.com.sg
 Buss. Reg. No. : 20051400L

AUTO & GENERAL INSURANCE (SINGAPORE) PTE LTD
 190 CLEMENCEAU AVENUE
 #03-01 SINGAPORE SHOPPING CENTRE S' 239924

Attention : Motor Claim Department
 Contact : 6221 2111

Estimate : TP22/017

Date : 29/04/2022
 Vehicle Num. : SKN 9204R
 Make/Model : VOLKSWAGEN GOLF 1.4 AT 5K13G5-2014
 Chassis/Eng# : WVVZZZAUZFW006514/CXS210967
 Accident Date : 13/04/2022
 Claim No. : C10014760
 Reference : LYB/SLZ4401E/AUTOINS/tp/sl
 Policy No. :

*Not within
1-31, 6/10/22*

3 days

2449.19

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

		LIST ITEMS :	<i>1362.45</i>
1.	1	REAR BUMPER	
2.	1	REAR BUMPER LIP SPOILER	
3.	1	REAR BUMPER BEAM	
4.	1	REAR BUMPER RETAINER/LH	
5.	1	REAR BUMPER RETAINER/RH	
6.	1	REAR BUMPER RETAINER (CENTRE)	
7.	1	REAR TAILEND PANEL	
8.	1	REAR TAILEND PANEL (LOWER)	
9.	1	REAR TAILEND INNER GARNISH	
10.	1	REAR SILENCER-LEFT	
11.	1	REAR SILENCER OUTER CHROME FINISHER/ LH	

List TotalS\$:

		SPECIAL NETT ITEMS :	
1.	1	REAR TAILEND PANEL TEROSTAT SEALANT	
2.	1	REAR TAILEND INNER GARNISH CLIPS	
3.	1	REAR EMBLEM 'VW'	
4.	1	REAR EMBLEM 'GOLF'	
5.	1	REAR EMBLEM 'TSI'	
6.	1	REAR EMBLEM 'BLUEMOTION'	
7.	1	REAR NO PLATE (EMBOSS)	
8.	1	REAR NO PLATE HOLDER	
9.	1	REAR REVERSE SENSOR	

<i>Br</i>	1,477.32	<i>✓</i>
<i>Pr</i>	400.54	<i>✓</i>
<i>R</i>	588.75	<i>✓</i>
<i>Pr</i>	90.97	<i>✓</i>
<i>Pr</i>	90.97	<i>✓</i>
<i>Pr</i>	250.54	<i>✓</i>
<i>Pr</i>	300.47	<i>✓</i>
<i>Pr</i>	366.75	<i>✓</i>
<i>Pr</i>	366.75	<i>✓</i>
<i>Pr</i>	717.00	<i>✓</i>
<i>Pr</i>	388.75	<i>✓</i>
		5,038.81

108

<i>na</i>	54.20	<i>✓</i>
<i>na</i>	12.00	<i>✓</i>
<i>na</i>	180.54	<i>✓</i>
<i>na</i>	121.50	<i>✓</i>
<i>na</i>	98.60	<i>✓</i>
<i>na</i>	111.15	<i>✓</i>
<i>Pr</i>	35.00	<i>✓</i>
<i>Pr</i>	25.00	<i>✓</i>
<i>Pr</i>	250.00	<i>✓</i>

CONTINUE / ...

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

LIM YEW BOO SPRAY PAINT CO.

BLK 10, SIN MING INDUSTRIAL ESTATE, SECTOR C, #01-10 S'575645
 NO. 176, SIN MING DRIVE, #03-05, SIN MING AUTOCARE, S'PORE 575721
 Tel No. : 64534177 Fax No. : 64593724
 E-Mail : limyewboo@singnet.com.sg
 Website : www.limyewboo.com.sg
 Buss. Reg. No. : 20051400L

AUTO & GENERAL INSURANCE (SINGAPORE) PTE LTD
 190 CLEMENCEAU AVENUE
 #03-01 SINGAPORE SHOPPING CENTRE S' 239924

Attention : Motor Claim Department
 Contact : 6221 2111

Estimate : TP22/017

Date : 29/04/2022
 Vehicle Num. : SKN 9204R
 Make/Model : VOLKSWAGEN GOLF 1.4 AT 5K13G5-2014
 Chassis/Eng# : WVVZZZAUZFW006514/CXS210967
 Accident Date : 13/04/2022
 Claim No. : C10014760
 Reference : LYB/SLZ4181E/AUTOINS/tp/sl
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
10.	5	REAR BUMPER FASTENER	5.50	na 27.50 ✓
11.	5	REAR BUMPER EXTENSION FASTENER	5.50	na 27.50 X
		Special Nett Total S\$:		942.99
		LABOUR :		
		TO APPLY RUST-PROOFING ON REPAIRED/ REPLACED PANELS		na 120.00 X
		TO CHECK WATER SEEPAGE		na 60.00 X
		TO CHECK REAR WIRING FUNCTION		35.00 100
		TO REMOVE & REPLACED/ REPAIRED AFFECTED RIM		na 150.00 X
		TO REPLACE REVERSE SENSOR SET & CHECK WIRING FUNCTIONS		120.00 500
		TO REPAIR, PANEL BEAT, ALIGN ON REAR AFFECTED AREA, CUT & WELD ON REPLACED PANEL & LABOUR TO REPLACE ABOVE		800.00 2800
		TO SPRAY ON REAR BUMPER, END PANEL, SENSOR & AFFECTED REAR TAILGATE USING 2K PAINT		4500 800.00
		Labour Total S\$:		2,085.00

E. & O.E.

Total S\$: 8,066.80

=====




for LIM YEW BOO SPRAY PAINT CO.