

EROFIA MOTOR TRADING PTE LTD

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

Co. Reg No. 201202259N

Email: erofia@singnet.com.sg

ALG

Name : Lee Boon Fook (86956385)

Accident Date : 05-Mar-22

Vehicle No : JTN7027

Vehicle Model : Yamaha 135LC

Estimated Repair Costs

Qty	Description List Items	Amount S(\$)
2	Front fork tube assy <i>Sub/1m</i>	520 \$ 640.00 ✓
1	Fork under bracket <i>Sub</i>	\$ 185.00 ✓
1	Front wheel rim <i>1 1</i>	\$ 380.00 X
1	Front rim shaft <i>1 1</i>	\$ 45.00 X
1	Front rim bearing <i>1 1</i>	\$ 38.00 X
1	Handle bar <i>Sub</i>	\$ 88.00 ✓
2	Handle bar end <i>M.S / cur</i>	35 \$ 80.00 —
1	Hand grip (1 set) <i>1 1</i>	\$ 55.00 X
1	Handle bar inner bracket <i>1 1</i>	\$ 88.00 X
2	Side mirror <i>3 20</i>	\$ 110.00 —
1	Brake lever <i>cur</i>	30 \$ 42.00 —
1	Headlamp <i>one</i>	\$ 185.00 Z
1	Front signals (1 set) <i>cm</i>	60 \$ 140.00 —
1	Front signal lower garnish <i>cm</i>	88 \$ 105.00 —
1	Fairing assy (1 set) <i>3 20</i>	480 \$ 525.00 —
1	Front footrest bracket <i>3 20</i>	\$ 65.00 —
2	Front footrest rubbers <i>10.1</i>	\$ 70.00 —
1	Brake pedal <i>R</i>	\$ 45.00 X
2	Rear footrests <i>0/5 cur</i>	40 \$ 80.00 12c
2	Rear footrest brackets <i>1 1</i>	\$ 156.00 X
1	Rear signals (1 set) <i>0/5 cur</i>	65 \$ 180.00 12c
1	Exhaust assy <i>R</i>	\$ 585.00 X
1	Exhaust protector - chrome end <i>cur</i>	\$ 75.00 —
1	Exhaust protector - black <i>cur</i>	\$ 55.00 —
1	Rear handle <i>cur</i>	150 \$ 228.00 —
1	Radiator <i>PD</i>	400 \$ 580.00 —
1	Basket <i>one</i>	\$ 60.00 —
		\$ 4,885.00
	Less 10%	\$ 488.50
		\$ 4,396.50

EROFIA MOTOR TRADING PTE LTD

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

Co. Reg No. 201202259N

Email: erofia@singnet.com.sg

Name : Lee Boon Fook (86956385)

Accident Date : 05-Mar-22

Vehicle No : JTN7027

Vehicle Model : Yamaha 135LC

Estimated Repair Costs

Special Net Items

1	Number plste (1 set) <i>Ref nec</i>	\$	38.00	<i>10</i>
2	Fork oils <i>11</i>	\$	30.00	<i>X</i>
2	Fork oil seals <i>11</i>	\$	56.00	<i>X</i>
1	Steering cone (1 set) <i>nu</i>	\$	60	90.00 <i>X</i>
		\$	214.00	

S/No. Labour

1	To provide towing service (LOD) \$35.00 <i>refer LOD</i>	\$	-	
2	To check wiring and reset headlamp focusing	\$	11	80.00 <i>X</i>
3	To provide labour	\$	400.00	<i>300</i>
4	To repair body frame	\$	11	350.00 <i>X</i>
		\$	830.00	

Grand Total

\$ 5,440.50

Singapore Dollars: Five Thousand Four Hundred Forty and Cents: Fifty only



EROFIA MOTOR TRADING PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

22761
102
2484.9
2854.9
2283