

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22003515/UYA3Q2**Date:** 17/06/2023REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100416817
Claimant Vehicle No :	FBN7222H	Insured Vehicle No :	SKT8885A
Date of Loss:	13/04/2022	Nature of Claim:	TP
		Claim No:	5673438210SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBN7222H	Engine No:	NC42E1401269
Make & Model:	HONDA CB400SF, 399cc	Chassis No:	NC421901267
Reg. Date:	27/11/2018 (Man. Year: 2018)	Odometer:	45447 km
Colour:	Black		
Engine Capacity:	399 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	120/70Z R17	Rear Tyre Size:	160/60Z R17
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,049.80	8,103.10	5,946.70	42.33
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,200.00	350.00	850.00	70.83
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	15,249.80	8,453.10	6,796.70	44.57
Approved Total (Overridden) (\$\$)		6,700.00		
Nett Amount (\$\$)	15,249.80	6,700.00	8,549.80	56.06
+ Loss of Use (6.0 x S\$20.00/day) (\$\$)		120.00		
+ Other Costs (\$\$)		35.00		
Nett Liability (\$\$)		6,855.00		

INSPECTION

Date of Assignment:	18/04/2022	
Date Inspected:	18/04/2022	Inspected At: Erofia Motor Trading Pte Ltd (KAKI BUKIT) 1 KAKI BUKIT AVE 6 #02-62 Singapore 417883
Estimated Period of Repair:	4.0 days	

Adjuster: MARCUS CHUA**Manager:** Ezlyna

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER	Cracked	298.00 FL	*198.00 FL
2	2		*FORK INNER TUBES	Serviceable	1,120.00 FL	*- FL
3	2		*FORK OUTER TUBES	Serviceable	1,140.00 FL	*- FL
4	1		*FORK UNDER BRACKET	Not Necessary	385.00 FL	*- FL
5	1		*FRONT SPORT RIM	Bent / Warped	1,100.00 FL	*980.00 FL
6	2		*FRONT BRAKE DISC	Not Necessary	1,120.00 FL	*- FL
7	1		*FRONT RIM SHAFT	Serviceable	68.00 FL	*- FL
8	1		*HEADLAMP (LED)	Cracked	1,380.00 FL	*1,380.00 FL
9	1		*METER ASSY	Cracked	1,880.00 FL	*1,850.00 FL
10	1		*WINDSHIELD	Cracked	328.00 FL	*288.00 FL
11	1		*TOP COWLING	Cracked	380.00 FL	*380.00 FL
12	1		*HANDLE BAR	Bent	145.00 FL	*145.00 FL
13	1		*SET HANDLE BAR END	Cut	50.00 FL	*50.00 FL
14	1		*SET HAND GRIP	Not Necessary	60.00 FL	*- FL
15	1		*SIDE MIRRORS	N/S Broken	260.00 FL	*95.00 FL
16	1		*CLUTCH LEVER	Cut	180.00 FL	*125.00 FL
17	1		*FRONT SIGNALS	N/S Cut	390.00 FL	*85.00 FL
18	1		*FUEL TANK	Dented	1,680.00 FL	*1,350.00 FL
19	1		*FRONT FOOTREST (N/S)	Broken / Missing	190.00 FL	*60.00 FL
20	1		*FRONT FOOTREST BRACKET (N/S)	Cracked	280.00 FL	*210.00 FL
21	1		*REAR FOOTREST	Serviceable	170.00 FL	*- FL
22	1		*GEAR PEDAL	Bent	285.00 FL	*140.00 FL
23	1		*ENGINE COVER	Cut	480.00 FL	*480.00 FL
24	1		*SIDE FAIRING (FRT)	Cut	285.00 FL	*285.00 FL
25	1		*FRONT RIM BEARING	Necessary	58.00 FL	*58.00 FL
26	1		*SET NUMBER PLATE	Not Necessary	38.00 FS	*- FS
27	2		*FORK OILS	Not Necessary	30.00 FS	*- FS
28	2		*FORK OIL SEALS	Not Necessary	56.00 FS	*- FS
29	1		*SET STEERING CONE	Not Necessary	125.00 FS	*- FS
30	1		*REAR BOX	Cut	680.00 FS	*480.00 FS
31	1		*REAR BOX BRACKET	Not Necessary	180.00 FS	*- FS
32	1		*E.R.P IU	Not Necessary	180.00 FS	*- FS
33	1		*SET CRASH BAR	Cut	420.00 FS	*280.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	15,421.00	8,919.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	1,371.20	815.90
Total Parts (\$\$)	14,049.80	8,103.10

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PROVIDE TOWING SERVICE (LOD) (NPA)	New	0.00	0.00
2	TO CHECK WIRING AND RESET HEADLAMP FOCUSING	New	80.00	0.00
3	TO PROVIDE LABOUR	New	600.00	350.00
4	TO REPAIR BODY FRAME	New	520.00	0.00
Gross Labour Cost (\$)			1,200.00	350.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >