

EROFIA MOTOR TRADING PTE LTD (201202259N)

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

Email: erofia@singnet.com.sg

Name : Ng Kok Yong (96529782)

Accident Date : 12-Apr-22

Vehicle No : FBF2593L

Vehicle Model : Kymco SK60AE

Estimated Repair Costs

<u>Qty</u>	<u>Description</u>	<u>Amount S(\$)</u>
<u>List Items</u>		
1	Windshield	\$ 720.00
1	Meter assy	\$ 1,050.00
1	Front cowling	\$ 680.00
1	Front inner cowling	\$ 480.00
1	Front lower cover	\$ 120.00
1	Front fender	\$ 288.00
1	Front fork assy	\$ 2,520.00
1	Handle-bar	\$ 360.00
1	Handle-bar balancer	\$ 48.00
1	Hand grip	\$ 45.00
1	Brake lever	\$ 105.00
1	Side mirror (1 set)	\$ 312.00
1	Foot step panel	\$ 210.00
1	Foot step lower panel	\$ 330.00
1	Side stand	\$ 128.00
1	Main stand	\$ 208.00
1	Rear side cover - L/H	\$ 560.00
1	Air filter box cover	\$ 150.00
1	Drove belt cover	\$ 300.00
		<u>\$ 8,614.00</u>
	Less 10%	\$ 861.40
		<u>\$ 7,752.60</u>

Special Net Items

1	Number plate (1 set)	\$ 28.00
2	Fork oil	\$ 30.00
2	Fork oil seat	\$ 75.00
1	Steering cone (1 set)	\$ 185.00
1	Rear box	\$ 480.00
1	Rear box bracket	\$ 180.00
		<u>\$ 978.00</u>

EROFIA MOTOR TRADING PTE LTD (201202259N)

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

Email: erofia@singnet.com.sg

Name : Ng Kok Yong (96529782)

Accident Date : 12-Apr-22


Vehicle No : FBF2593L

Vehicle Model : Kymco SK60AE

Estimated Repair Costs

<u>S/No.</u>	<u>Labour</u>	
1	To provide towing service (LOD)	\$ -
2	To check wiring and reset headlamp focusing	\$ 80.00
3	To spray paint	\$ 480.00
4	To provide labour	\$ 520.00
		<u>\$ 1,080.00</u>
Grand Total		<u>\$ 9,810.60</u>

Singapore Dollars: Nine Thousand Eight Hundred Ten and Cents: Sixty only



EROFIA MOTOR TRADING PTE LTD