

TPAXA
Veron

SMZ4450S .20M July.

Hyundai Elantra 1591 CC

KMH D841CMJU508772

Front RH Fender	Distorted	689.40 ✓
Front RH Fender Inner Shield	torn new	189.40 ✓
Front RH Fender Inner Shield Clips		30(SN) ✓
Front RH Door	Distorted	1782.30 ✓
Front RH Door Lock	Damaged	247.20 ✓
Front RH Door Weatherstripe	cut	185.40 ✓
Front RH Door Frame Weatherstripe	cut	212.40 ✓
Front RH Door Hinge x 02	Best	45.9 x 2 = 91.80 ✓
Front RH Door Check	Damaged	59.40 ✓
Front RH Door Inner Trim Board	cracked	572.40 ✓
Front RH Door Inner Trim Board clips	new	30(SN) ✓
Front RH Door Glass Regulator Gear	broken	223.40 ✓
Front RH Door Glass Regulator Motor	new	388.50 ✓
Front RH Door Speaker	Cracked	241.10 ✓

4942.70

SMZ44508.

Front RH Door Inner Buffer.	aud	65.40	/
Front RH Door Wing Mirror	cut	1054.60	/
Front RH Door Wing Mirror Cover.	Pyir	195.20	x
Front RH Door Step Garnish.	New	179.40	/
Front RH Door Frame	Distorted	1799.60	/
Front RH Door Frame Weatherstripe.			
Front RH Fender Signal Lamp	Missing	67.80	/
Front RH Fender Inner Garnish.	Distorted	69.90	/
Rocker Panel RH.			
Dashboard	Not Rec	1863.50	x
Dashboard Lower Cover.	HP SW	248.90	x.
Front Windscreen Moulding	HP	121.20	x
Front Windscreen Sealant	HP SW	60(SW)	x.

5635.50

SMZ4450S.

Front RH Wheel Rim } 982.50 +

Front RH Tyre. } 280(SN) +

Front RH Lower Arm. } 345.20 +

Front RH Knuckle Arm. } 425.60 ✓

Front RH Shock Absorber } 355.20 ✓

Front RH Wheel Hub c/w Bearing. } 266.40 ✓

Sleeriy Rack and Pinion: } 1897.50 +

4552.40

8778.10 S.N: 60

7022.48.

SMZ 44508.

Panel Beating

Spray Painting.

Wiring.

To dismantle front undercarriage.

To perform wheel alignment.

To transfer door fittings.

To remove upholstery.

To remove dashboard

To remove front windscreen.

Towing Charges. 2610

~~1800~~ 1200

~~1600~~ 900

~~1000~~ 30

~~380~~ 200

~~150~~ 80

~~150~~ 80

~~150~~ 60

350 X

180 X

60. ✓

4920

20,050.60

Total: 9692.48

4/51 TTK

09 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: