



創 CHARN'S CUSTOMCRAFT

Accident Claim Repair, Corrosion Welding, Body Dent Repairs,
Spray-Painting, Mechanical Repair And Customizing of Cars

BLOCK 1010, BUKIT MERAH LANE 3, #01-105, SINGAPORE 159724

BLOCK 1009, BUKIT MERAH LANE 3, #01-82, SINGAPORE 159723

: 62717054, 62733304 FAX: 62736676 EMAIL: charns@singnet.com.sg

Bus. Reg. No. 251513/00M

DA/FIRST CAPITAL(SHB55701F)

DOA: 05/04/2022@1800

Steve (LKK) 83228813

W LC
L/S

FIRST CAPITAL INSURANCE PTE LTD

14/04/2022

ATTN: THE MOTOR CLAIMS DEPT

20/4/22, 3:00pm

MJ HL Sy

5 days

THIRD PARTY CLAIM

ESTIMATE COST OF REPAIR FOR VEHICLE NO:

SJL 4411 P - HYUNDAI ELANTRA AD 1.6 GLS AT

CHASSIS NO: KMHD841CMJU569045 (2017)

1 pc	Rear boot emblem 'S' / MK	\$ 35.40 /
1 pc	Rear boot 'ELANTRA' emblem / MK	\$ 68.80 /
1 pc	Rear taillamp RHS X MK	\$ 338.00
1 pc	Rear end panel ? X R	\$ 454.60
1 pc	Rear end panel top garnish X MK	\$ 59.80
1 pc	Rear bumper / BR	\$ 459.40 /
1 pc	Rear bumper reinforcement ? / BT	\$ 294.80 /
2 pcs	Rear bumper reinforcement top bracket @ \$4.50 ? / BR	\$ 9.00 4-50 /
8 pcs	Rear bumper clips @ \$2 / MK	\$ 16.00 /
1 pc	Rear bumper reflector RHS ? / BR	\$ 55.00 /
1 pc	Rear bumper lower spoiler / BR	\$ 250.10 /
1 pc	Rear bumper retainer RHS / BR	\$ 44.30 /
		\$ 2,085.20 1228.30
	LESS 20%	\$ 417.04 -20%
		\$ 1,668.16 982.64
1 SET	Reverse Sensor (S/NETT) Shaded	\$ 200.00 /
	Check wiring function	\$ 40.00 30
	Remove and install all cushions, seats, back rest, inner trim, garnish, roof lining and upholstery to facilitate repair.	\$ 180.00 30
	Apply rust-proofing on accident affected areas.	\$ 120.00 30
	Remove necessary parts: jacking, panel beating, repair and straighten rear inner panel, rear boot inclusive replacing the above.	\$ 600.00 400-600
	Putty and respray rear inner panel, rear end panel, rear boot and rear bumper.	\$ 600.00 400-600
	ADD 7% GST	\$ 3,408.16
		\$ 238.57
		\$ 3,646.73

1228.30

-20%

982.64

30

30

30

400-600

400-600

1490


= 2472.64

Note: The above is an estimate only. IF other parts requested during the course of repair, we will inform you accordingly.

All parts are subject to availability.

CHARN'S CUSTOMCRAFT

[Signature]



創 CHARN'S CUSTOMCRAFT

Accident Claim Repair, Corrosion Welding, Body Dent Repairs,
Spray Painting, Mechanical Repair And Customizing of Cars
BLOCK 1010, BUKIT MERAH LANE 3, #01-105, SINGAPORE 159724
BLOCK 1009, BUKIT MERAH LANE 3, #01-82, SINGAPORE 159723
TEL: 62717054, 62733304 FAX: 62736676 EMAIL: charns@singnet.com.sg
Bus. Reg. No. 251513/00M

DA/FIRST CAPITAL(SHB5570H)
DOA: 05/04/2022@1800

Supp.

Steve Chen @ 1KKauto.com

FIRST CAPITAL INSURANCE PTE LTD

14/04/2022

ATTN: THE MOTOR CLAIMS DEPT

THIRD PARTY CLAIM
ESTIMATE COST OF REPAIR FOR VEHICLE NO:
SJL 4411 P - HYUNDAI ELANTRA AD 1.6 GLS AT
CHASSIS NO: KMHD841CMJU569045 (2017)

SUPPLEMENTARY:-

1 pc	Front bumper	OR (waiting price)	\$474.40	-
1 pc	Front grille	CUT (---)	\$529.90	-
				1004.30
				-209
				803.44
1 pc	Front no. plate (s/nett)	BT	\$	35.00
	Labour to remove and replace front bumper		\$	300.00 209
	Labour to putty and respray front bumper		\$	300.00 909

CHARN'S CUSTOMCRAFT

.....

Steve (LKK)

20/4/22, 3:30pm

435
=1238.44

main -2472.64

=3,711.08

L/S-2968.86

=2950