



創 CHARN'S CUSTOMCRAFT

Accident Claim Repair, Corrosion Welding, Body Dent Repairs,
Spray Painting, Mechanical Repair And Customizing of Cars
BLOCK 1010, BUKIT MEHAI LANE 3, #01-105, SINGAPORE 159724
BLOCK 1009, BUKIT MEHAI LANE 3, #01-82, SINGAPORE 159723
TEL: 62717054, 62733304 FAX: 62736676 EMAIL: charns@singnet.com.sg
Bus. Reg. No. 25151300M

DA/FIRST CAPITAL(SHB557011)
DOA: 05/04/2022@1800

Supp.

stevechen@lkkauto.com

FIRST CAPITAL INSURANCE PTE LTD

14/04/2022

ATTN: THE MOTOR CLAIMS DEPT

THIRD PARTY CLAIM
ESTIMATE COST OF REPAIR FOR VEHICLE NO:
SJL 4411 P - HYUNDAI ELANTRA AD 1.6 GLS AT
CHASSIS NO: KMHD841CMJU569045 (2017)

SUPPLEMENTARY:-

1 pc	Front bumper	/ BR	(Warranty Price)	\$474.40	-
1 pc	Front grille	/ CUT	(Warranty Price)	\$529.90	-
				1004.30	
				-209	
				803.44	
1 pc	Front no. plate (s/nett)	BT		\$	35.00
	Labour to remove and replace front bumper			\$	300.00 209
	Labour to putty and respray front bumper			\$	300.00 709

CHARN'S CUSTOMCRAFT

Steve (LKK)
20/4/22, 3:27pm
435
= 1238.44
main - 2472.64
= 3,711.08

L/S - 2968.86
= 2950

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

1438.44