

# MCS Garage

TP SMRT.  
Denise.

10 Kaki Bukit Road 2 #03-25, First East Centre Singapore 471868

Tel: 9270 0917 / 6538 4322

Vehicle number: SGX8363R

Vehicle Made & Model: HONDA SHUTTLE

| Qty               | List Items  | Amount \$            |
|-------------------|---|----------------------|
| 1                 | Tailgate <i>Dented</i>                              | 1,860.90 <i>1193</i> |
| 1 set             | Tailgate glass moulding <i>new</i>                  | 121.60 ✓             |
| 1                 | Tailgate emblem "SHUTTLE" <i>new</i>                | 86.90 ✓              |
| 1                 | Tailgate inner lock                                 | 280.60 +             |
| 1                 | Tailgate outer garnish <i>new</i>                   | 461.90 ✓             |
| 1                 | Tailgate inner board <i>new</i>                     | 481.90 +             |
| 1                 | Tailgate w/strip <i>new</i>                         | 210.30 +             |
| 1                 | Tailgate inner pull pocket <i>new</i>               | 89.90 +              |
| 1                 | Rear bumper <i>new</i>                              | 1,381.10 +           |
| 1                 | Rear bumper chrome moulding <i>new</i>              | 241.60 ✓             |
| 1                 | Rear bumper tow cover <i>new</i>                    | 48.90 +              |
| 2                 | Rear bumper side retainers - L/R @ 58.60 <i>new</i> | 117.20 +             |
| 1                 | Rear end panel <i>new</i>                           | 680.90 +             |
| 1                 | Rear end panel trim <i>new</i>                      | 221.30 +             |
| <b>Sub-total</b>  |   | 6,285.00             |
| <b>Less 20%</b>   |   | 1,257.00             |
| <b>Total List</b> |   | 5,028.00             |

## Special Nett Items

|                           |  |                 |
|---------------------------|--|-----------------|
| 1 set                     | Tailgate glass sealant <i>new</i>      | 80.00 <i>60</i> |
| 1 set                     | Tailgate outer garnish clip <i>new</i> | 80.00 +         |
| 1 set                     | Rear bumper clip <i>new</i>            | 45.00 <i>30</i> |
| 1 set                     | Rear reverse sensor <i>new</i>         | 280.00 +        |
| <b>Total Special Nett</b> |  | 485.00          |

Vehicle number: SGX8363R

Vehicle Made & Model: HONDA SHUTTLE

**Labour charges**

|   |                 |      |
|---|-----------------|------|
| To check rear electrical wiring                         | 50.00           | X 30 |
| To remove, refix rear interior trims to assist repair   | 120.00          | X    |
| To remove, refix tailgate glass                         | 180.00          | 120  |
| To remove, refix rear reverse sensor / Camera           | 80.00           | 50   |
| To respray undercoating                                 | 60.00           | X    |
| To respray painting and etc                             | 1,080.00        | 400  |
| Panel beating, cut, weld remove & replacing above parts | 900.00          | 250  |
| <b>Total Labour</b>                                     | <b>2,470.00</b> |      |

850  
Total: 2254.48  
H/S: 1.8K

**ESTIMATE PARTS AND LABOUR GRAND TOTAL \$ 7,983.00**

03 Days.

1.8K

**LKK Auto Consultants** hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: