

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/0295/2022/JT
DATE : 13-Apr-22
WIP : 19745

VEHICLE NOT IN WORKSHOP. SURVEY TBC

YOUR INSURED VEH NO : XE 4647 Y

ALLIANZ INSURANCE Singapore Pte. Ltd.

12 MARINA VIEW

#14-01 ASIA SQUARE TOWER 2

SINGAPORE 018961

Attn: Motor Claims Dept

Tel: 65 6297 8802

Hi Steve

9 days exclude 1 Sunday & 1 PH

19 Aug 22 Johnny Boo

OWNER'S NAME : MR CHOW JI FENG
ADDRESS : BLK 666B JURONG WEST ST 65
#08-211
SINGAPORE 642666
TELEPHONE : HP +65 91170427
TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 7210054905
VEHICLE NO : **SNA 932 P**
MODEL CODE : AUDI A3 SB 1.5 TFSI
MODEL YEAR : 31/5/2021
ENGINE NO : DFY 272063
CHASSIS NO : WAUZZZGYXMA101623
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 12-Apr-22
PLACE OF ACCIDENT : BENOI ROAD & GUL CIRCLE

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SNA 932 P

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR.	S/N \$	360.00	\$ 360.00
2	TO REMOVE AND TRANSFER REAR LID'S CONVENIENCE LOCK SYSTEM, WIRE HARNESS FOR TAIL LIGHTS AND REAR LID WIPER ASSY.	S/N \$	480.00	\$ 480.00
3	TO RENEW REAR WINDSCREEN TO FACILITATE RENEWAL OF REAR LID.	S/N \$	480.00	\$ 480.00
4	TO INSTALL SOLAR FILM FOR REAR WINDSCREEN.	S/N \$	400.00	\$ 400.00
5	TO CARRY OUT WATER SEEPAGE FOR REAR WINDSCREEN	S/N \$	200.00	\$ 200.00
6	TO DISLodge AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT. INSPECT FOR DAMAGE AND RENEW WHERE NECESSARY.	S/N \$	1,400.00	\$ 480.00
SUB TOTAL LABOUR CHARGES		:	\$ 3,320.00	\$ 2,400.00

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SNA 932 P

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
	<i>c/f</i>			\$ 2,400.00
7	TO DISMANTLE AND RENEW REAR BUMPER AND REAR LID. TO CUT OUT AND WELD REAR END PANELLING. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	4,200.00	\$ 3,500.00
8	TO RESPRAY REAR BUMPER, REAR LID HINGES, REAR END PANELLING AND SPARE WHEEL HOUSING.	\$	4,000.00	\$ 2,200.00
9	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	\$ 192.00
10	TO RE-APPLY PAINT COATING ON ACCIDENT AFFECTED AREA.	S/N	PRICE TBC	Owner withdraw
TOTAL LABOUR CHARGES		:	\$ 11,712.00	\$ 8,292.00

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNA 932 P

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	REAR BUMPER	1	\$ 1,914.00	\$	1,914.00
2	REAR BUMPER FIXING PARTS	1	\$ 329.00		
3	REAR BUMPER LOCKING MECHANISM - LH / RH	2	\$ 32.00		
4	REAR BUMPER TRIM - LH / RH	2	\$ 144.00		
5	REAR PARKING AID SENSOR SUPPORT - LH / RH OUTER	2	\$ 56.00		
6	REAR BUMPER SPOILER	1	\$ 226.00	\$	225.50
7	REAR LIGHT REFLECTOR - LH / RH	2	\$ 74.00		
8	TAIL LIGHT OUTER - LH / RH	2	\$ 2,098.00		
9	TAIL LIGHT TRIM OUTER - LH / RH	2	\$ 68.00		
10	TAIL LIGHT INNER - LH / RH	2	\$ 1,552.00		
11	TAIL LIGHT INNER TRIM - LH / RH	2	\$ 60.00		
12	LICENCE PLATE LIGHT	2	\$ 209.00		
13	REAR BUMPER REINFORCEMENT BEAM	1	\$ 599.00		
14	REAR BUMPER BRACKET - LH / RH	2	\$ 63.00		
15	REAR BUMPER GUIDE SECTION- LH / RH	2	\$ 124.00	\$	58.50
16	REAR PARKING AID SENSOR - INNER	2	\$ 530.00		
17	REAR PARKING AID SENSOR SEAL RING	4	\$ 32.00		
18	REAR LID	1	\$ 2,922.00	\$	2,922.00
19	REAR LID ATTACHMENT PARTS	1	\$ 535.00		
20	REAR LID HINGE - LH / RH	2	\$ 330.00		
SUB TOTAL SPARE PARTS		:	\$ 11,897.00	\$	5,120.00

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNA 932 P

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
		<i>c/f</i>		<i>\$</i>	<i>5,120.00</i>
21	REAR LID LOCK	1	\$ 244.00		
22	REAR LID LOCK FLAP COVER CAP	1	\$ 6.00		
23	REAR LID LOCK ACTUATOR	1	\$ 215.00	<i>\$</i>	<i>214.50</i>
24	REAR LID LOCK STRIKER	1	\$ 102.00		
25	REAR LID SEAL	1	\$ 176.00		
26	REAR LID CLIP	2	\$ 4.00	<i>\$</i>	<i>3.20</i>
27	REAR CAMERA CONTROL UNIT	1	\$ 1,441.00		
28	REAR PACKING ADHESIVE	1	\$ 21.00	<i>\$</i>	<i>20.90</i>
29	AUDI EMBLEM	1	\$ 144.00	<i>\$</i>	<i>143.50</i>
30	"A3" EMBLEM	1	\$ 104.00	<i>\$</i>	<i>103.50</i>
31	REAR WINDSCREEN	1	\$ 726.00	<i>\$</i>	<i>726.00</i>
32	PRIMER	1	\$ 22.00	<i>\$</i>	<i>21.70</i>
33	REAR SPOILER - LH / RH	2	\$ 340.00	<i>\$</i>	<i>340.00</i>
34	REAR SPOILER ADHESIVE TAPES	2	\$ 275.00	<i>\$</i>	<i>137.50</i>
35	REAR LID TOP SPOILER FOAM STRIPS	1	\$ 114.00	<i>\$</i>	<i>114.00</i>
36	REAR LID TOP SPOILER ATTACHMENT PARTS	1	\$ 143.00		
37	REAR END PANEL	1	\$ 460.00	<i>\$</i>	<i>459.50</i>
38	REAR END PANEL REINFORCEMENT	1	\$ 1,407.00		
39	REAR END PANEL CONNECTING PLATE - LH / RH	2	\$ 92.00		
40	REAR END PANEL TRIM	1	\$ 171.00		
SUB TOTAL SPARE PARTS		:	\$ 6,207.00	<i>\$</i>	<i>7,404.30</i>

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNA 932 P

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
		<i>c/f</i>		<i>\$ 7,404.30</i>
41	REAR LID TRIM PANEL - LOWER	1	\$ 533.00	
42	ARYLIC SEALANT	S/N	\$ 180.00	<i>\$ 180.00</i>
43	CAVITY WAX	S/N	\$ 140.00	<i>\$ 140.00</i>
44	STONE CHIP	S/N	\$ 180.00	<i>\$ 180.00</i>
45	METAL FILLER POWDER	S/N	\$ 280.00	<i>\$ 280.00</i>
46	REAR WINDSCREEN SEALANT	S/N	\$ 200.00	<i>\$ 200.00</i>
47	REAR NO PLATE	S/N	\$ 100.00	
48	SUNDRIES		\$ 400.00	<i>\$ 24.00</i>
TOTAL SPARE PARTS		:	\$ 20,117.00	<i>\$ 8,408.30</i>
TOTAL LABOUR CHARGES		:	\$ 11,712.00	<i>\$ 8,292.00</i>
GRAND TOTAL		:	\$ 31,829.00	<i>\$ 16,700.30</i>

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED
 SPARE PARTS ARE SPECIAL NETT.
 bl-/21/07/22

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT