

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
 WORKSHOP : UBI ROAD 1
 CONTACT NO : 6366 2323
 FAX NO : 6841 1183
 REFERENCE : PA/TP/0295/2022/JT
 DATE : 13-Apr-22
 WIP : 19745

VEHICLE NOT IN WORKSHOP. SURVEY TBC

YOUR INSURED VEH NO : XE 4647 Y

ALLIANZ INSURANCE Singapore Pte. Ltd.

12 MARINA VIEW

#14-01 ASIA SQUARE TOWER 2

SINGAPORE 018961

Attn: Motor Claims Dept

Tel: 65 6297 8802

OWNER'S NAME : MR CHOW JI FENG
 ADDRESS : BLK 666B JURONG WEST ST 65
 #08-211
 SINGAPORE 642666
 TELEPHONE : HP +65 91170427
 TYPE OF CLAIM : THIRD PARTY CLAIM
 POLICY NO : 7210054905
 VEHICLE NO : SNA 932 P
 MODEL CODE : AUDI A3 SB 1.5 TFSI
 MODEL YEAR : 31/5/2021
 ENGINE NO : DFY 272063
 CHASSIS NO : WAUZZZGYXMA101623
 MILEAGE : -
 DATE IN : -
 ESTIMATED BY : JOHNNY BOO / ALLAN WU
 ACCIDENT DATE : 12-Apr-22
 PLACE OF ACCIDENT : BENOI ROAD & GUL CIRCLE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SNA 932 P

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR.	S/N \$ 360.00 /	
2	TO REMOVE AND TRANSFER REAR LID'S CONVENIENCE LOCK SYSTEM, WIRE HARNESS FOR TAIL LIGHTS AND REAR LID WIPER ASSY.	S/N \$ 480.00 /	
3	TO RENEW REAR WINDSCREEN TO FACILITATE RENEWAL OF REAR LID.	S/N \$ 480.00 /	
4	TO INSTALL SOLAR FILM FOR REAR WINDSCREEN.	S/N \$ 400.00 /	
5	TO CARRY OUT WATER SEEPAGE FOR REAR WINDSCREEN.	S/N \$ 200.00 /	
6	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT. INSPECT FOR DAMAGE AND RENEW WHERE NECESSARY.	S/N \$ 1,400.00	480 ✓
SUB TOTAL LABOUR CHARGES		: \$ 3,320.00	

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SNA 932 P

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
7	TO DISMANTLE AND RENEW REAR BUMPER AND REAR LID. TO CUT OUT AND WELD REAR END PANELLING. RE- ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 4,200.00	1400 3500
8	TO RESPRAY REAR BUMPER, REAR LID HINGES, REAR END PANELLING AND SPARE WHEEL HOUSING.	\$ 4,000.00	1500 2200
9	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	/ 192
10	TO RE-APPLY PAINT COATING ON ACCIDENT AFFECTED AREA.	S/N PRICE TBC	? X
TOTAL LABOUR CHARGES		: \$ 11,712.00	



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNA 932 P

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	REAR BUMPER ✓ <i>DN</i>	1	\$	1,914.00 ✓
2	REAR BUMPER FIXING PARTS X NN	1	\$	329.00
3	REAR BUMPER LOCKING MECHANISM - LH / RH ? X NN	2	\$	32.00
4	REAR BUMPER TRIM - LH / RH X NN	2	\$	144.00
5	REAR PARKING AID SENSOR SUPPORT - LH / RH OUTER X	2	\$ NN	56.00
6	REAR BUMPER SPOILER X CUT	1	\$	226.00 ✓225.5
7	REAR LIGHT REFLECTOR - LH / RH X NN	2	\$	74.00
8	TAIL LIGHT OUTER - LH / RH ? X NN	2	\$	2,098.00
9	TAIL LIGHT TRIM OUTER - LH / RH X NN	2	\$	68.00
10	TAIL LIGHT INNER - LH / RH ? X NN	2	\$	1,552.00
11	TAIL LIGHT INNER TRIM - LH / RH X NN	2	\$	60.00
12	LICENCE PLATE LIGHT ? X NN	2	\$	209.00
13	REAR BUMPER REINFORCEMENT BEAM ? X NN	1	\$	599.00
14	REAR BUMPER BRACKET - LH / RH ? X NN	2	\$	63.00
15	REAR BUMPER GUIDE SECTION- LH / RH ? BR	1	\$	124.00 58.50 ✓
16	REAR PARKING AID SENSOR - INNER ? X NN	2	\$	530.00
17	REAR PARKING AID SENSOR SEAL RING X NN	4	\$	32.00
18	REAR LID ✓ <i>DN</i>	1	\$	2,922.00 2922
19	REAR LID ATTACHMENT PARTS X NN	1	\$	535.00
20	REAR LID HINGE - LH / RH X NN	2	\$	330.00
SUB TOTAL SPARE PARTS			\$	11,897.00

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNA 932 P

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
21	REAR LID LOCK X NN	1	\$ 244.00	
22	REAR LID LOCK FLAP COVER CAP X NN	1	\$ 6.00	
23	REAR LID LOCK ACTUATOR X CRU	1	\$ 215.00	✓ 214.5
24	REAR LID LOCK STRIKER X NN	1	\$ 102.00	
25	REAR LID SEAL ? X NN	1	\$ 176.00	
26	REAR LID CLIP / ne	2	\$ 4.00	✓ 3.2
27	REAR CAMERA CONTROL UNIT ? X NN	1	\$ 1,441.00	
28	REAR PACKING ADHESIVE / ne	1	\$ 21.00	✓ 20.9
29	AUDI EMBLEM / ne	1	\$ 144.00	✓ 143.5
30	"A3" EMBLEM / ne	1	\$ 104.00	✓ 103.5
31	REAR WINDSCREEN / ne	1	\$ 726.00	✓ 726
32	PRIMER / ne	1	\$ 22.00	✓ 21.7
33	REAR SPOILER - LH / RH / ne	2	\$ 340.00	✓ 340
34	REAR SPOILER ADHESIVE TAPES / ne	2	\$ 275.00	✓ 137.5
35	REAR LID TOP SPOILER FOAM STRIPS / ne	1	\$ 114.00	✓ 114
36	REAR LID TOP SPOILER ATTACHMENT PARTS / ne	1	\$ X NN 143.00	
37	REAR END PANEL ? DD	1	\$ 460.00	✓ 459.5
38	REAR END PANEL REINFORCEMENT ? X NN	1	\$ 1,407.00	
39	REAR END PANEL CONNECTING PLATE - LH / RH ? X NN	2	\$ 92.00	
40	REAR END PANEL TRIM ? X NN	1	\$ 171.00	
SUB TOTAL SPARE PARTS			\$ 6,207.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNA 932 P

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
41	REAR LID TRIM PANEL - LOWER X NN	1	\$ 533.00	
42	ARYLIC SEALANT ? NEC	S/N	\$ 180.00	✓
43	CAVITY WAX ? NEC	S/N	\$ 140.00	✓
44	STONE CHIP ? NEC	S/N	\$ 180.00	✓
45	METAL FILLER POWDER ? NEC	S/N	\$ 280.00	✓
46	REAR WINDSCREEN SEALANT ✓ ne	S/N	\$ 200.00	✓
47	REAR NO PLATE X NN	S/N	\$ 100.00	
48	SUNDRIES ? NEC		\$ 400.00	24 ✓
TOTAL SPARE PARTS		:	\$ 20,117.00	
TOTAL LABOUR CHARGES		:	\$ 11,712.00	
GRAND TOTAL		:	\$ 31,829.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

STER (LKK)
19/3/12, 3:00pm

W AL
PIP
L AL Y
9 F dys

PLEASE NOTE :

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT