

SLP 52956 2017 June

Honda Shuttle 1496cc

TPAXA

Xiao Tong

GK81003783

Front Bumper Behind 1050.50 ✓

Front Bumper Clips. n 30(SN). ✓

Front Bumper Side Holder LH. Dented 35. ✓

Front Bumper Reinforcement. Dented 420.50. ✓

Front Bumper Fog Lamp LH. and 265.40 ✓

Front Bumper Fog Lamp Cover LH. Behind 65.20 ✓

Front Bumper Fog Lamp Top Garnish LH. Behind 48.50. ✓

Front Bumper Fog Lamp Chrome Garnish LH. 55.40. X

Front Bumper Lower Grille. n 152.50. X

Front Grille. 363.30 X

Front Grille Clips. 2 X n

20(SN) X

SLP 5295 G.

Headlyp LH ^{Crk'd} 2128.70 ✓
Headlyp lower Bracket LH. ^{x4} 48.40. X.
_{nr}

Air Guide LH. ^{Del'd} 35.90 ✓

Air Guide Clips. ^{nr} 10(SN) ✓

4050.50 S.N. 40
3240.40

Panel Beatz
Spray Painting
Wiring.
To spray full coat

~~420~~ 400
860 ~~520~~ 400
~~50~~ 30.
~~150~~ 30.
total: 4140.40

L/S: 3.3K.
03 Days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

3 300
03 days