

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Your Ref: DMPC1600117H Date: 25th Aug 2022

Our Ref: CS1/ICS22003538/Dny3e2

M/s ECICS LTD

10 Eunos Road 8 Singapore Post Centre #09-04A Singapore 408600 (The Motor Claims Department)

Dear Sir / Madam,

EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: YL 2902A INSURED VEHICLE: SGG 3241G ACCIDENT DATE: 27/05/2016

We thank you for your instruction on 18/04/2022.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of YL 2902A from M/s PAR Automotive Consultancy.
- b) Survey report by Autoprobe Consultants with colour photographs.
- c) Final Repair Bill of YL 2902A from M/s TwinCar Automotive Pte Ltd.
- d) Singapore Accident Statement of Vehicles YL 2902A and SGG 3241G.
- e) Colour damaged vehicle photographs of YL 2902A.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number : YL 2902A

Make & Model : Mitsubishi FM657MSRDEC

Chassis Number : FM657MB00427

Year of Registration : 2002

- 2. We recommend that the repairs of the entire damage require about <u>8 (Eight)</u> working days to complete.
- 3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.