



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2205505

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 07/09/2022
Reference CC6/CTI22003552/Uea3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. SLQ 2292D
Insured Veh. SMX 9840C
Claim No. SNM22D202618/C02
Policy No. DMPCSNW00161252100
Accident Date 16/04/2022
Inspection Date 19/04/2022

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CC6/CTI22003552/Uea3q2 Date: 07/09/2022 Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SMX 9840C	Veh. Inspected	SLQ 2292D	
Policy No.	DMPCSNW00161252100	Coverage (\$)	0.00	
Claim No.	SNM22D202618/C02	Excess (\$)	0.00	
Assign From		Assign Date	19/04/2022	
2. Vehicle Particulars & Condition				
Make & Model	NISSAN X-TRAIL (A)	c.c	1997	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	JN1JANT32Z0003278	Colour	BLACK	
Odometer	35765 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/60 R18	DUNLOP	6 mm	
L/H Front Tyre	225/60 R18	DUNLOP	6 mm	
R/H Rear Tyre	225/60 R18	DUNLOP	6 mm	
L/H Rear Tyre	225/60 R18	DUNLOP	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	16/04/2022	Inspection Date	19/04/2022	
Survey held at	LEE BROTHERS AUTOMOTIVE PTE LTD 1 KAKI BUKIT AVENUE 6 #02-47 AUTOBAY SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLQ 2292D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	TAILGATE (N)	WARPED / CRACKED	4,650.00	4,650.00
1	TAILGATE WINDSHIELD MOULDING (N)	NECESSARY	1,386.00	75.00
1	TAILGATE LOGO (N)	NOT NECESSARY	86.60	-
1	TAILGATE EMBLEM "X-TRAIL" (N)	NECESSARY	89.60	89.60
2	TAILGATE LAMPS-RH/LH @\$311.50 (N)	NOT NECESSARY	623.00	-
1	TAILGATE CHROME MOULDING (N)	NOT NECESSARY	192.60	-
1	TAILGATE OUTER PULL SWITCH (N)	NOT NECESSARY	182.30	-
1	TAILGATE INNER LOCK (N)	DENTED / SHORTED	613.90	613.70
1	TAILGATE W/STRIP (N)	NOT NECESSARY	161.30	-
2	TAILGATE DAMPER-RH/LH @\$685.50 (N)	NOT NECESSARY	1,371.00	-
2	TAILGATE STOPPER @\$12.60 (N)	NOT NECESSARY	25.20	-
1	REAR BUMPER (N)	DEFORMED	693.10	693.10
2	REAR BUMPER REFLECTOR-RH/LH @\$86.90 (N)	NOT NECESSARY	173.80	-
1	REAR BUMPER CTR COVER (N)	TWISTED	89.90	89.90
1	REAR BUMPER REINFORCEMENT (N)	DENTED	659.10	589.20
2	REAR BUMPER REINFORCEMENT STAYS @\$135.00 (N)	BENT	270.00	270.00
2	REAR BUMPER SIDE RETAINERS-RH/LH @\$81.50 (N)	BENT	163.00	163.00
1	REAR END PANEL (N)	DENTED / BENT	559.00	559.00
1	REAR END PANEL GARNISH (N)	NOT NECESSARY	210.30	-
	LESS 10% DISCOUNT		-1,219.97	-779.25
			10,979.73	7,013.25
<u>SPECIAL NETT ITEMS</u>				
1	SET REAR BUMPER CLIP (SN)	NECESSARY	45.00	45.00
1	SET REAR REVERSE SENSOR (SN)	SHORTED	280.00	200.00
1	SET TAILGATE GLASS SEALANT (SN)	NECESSARY	80.00	40.00
1	SET TAILGATE GLASS FOAM TAPE (SN)	NECESSARY	65.00	40.00
1	SET TAILGATE REVERSE CAMERA (SN)	NOT NECESSARY	550.00	-
			1,020.00	325.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	TO REMOVE & REPLACE TAILGATE GLASS.		180.00	120.00
	TO TRANSFER & REINSTALL TAILGATE COMPONENTS TO NEW TAILGATE.		180.00	80.00
	TO CHECK REAR ELECTRICAL WIRING.		50.00	20.00
	TO REMOVE AND REPLACE REVERSE CAMERA & SENSORS.		100.00	50.00
	TO TUFF KOTE.		80.00	30.00
	TO PUTTY, SPRAY PAINT & POLISH AFFECTED PARTS.		1,200.00	600.00
	TO PANEL BEAT, CUT, WELD, REMOVE & REPLACE DAMAGED PARTS.		1,200.00	900.00
			2,990.00	1,800.00
GRAND TOTAL			14,989.73	9,138.25
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				7,300.00

Report Ref No. CC6/CTI22003552/Uea3q2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLQ 2292D

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLQ 2292D

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

