

ASS. REC. BY:

REF: CT21

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 850,601k

IDAC Accident Report: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: 10 days

Res.: Yes or No

Lum Sum: 20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Date / Time

Action / Instruction

1 Got BT

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech Invs (\$ _____)☐ : Weekend (\$ _____)

) Fin. 25

) Others

TOTAL

Veh No: S11D 9443EYr Regn: 05, 19

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toy Prius

c.c

1788Colour M.P. white / Red

A/C: Insured / Std / NI / NA

Sp. Reading 281048

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: STD KB 3FU 90.3 080 508Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD A/Rlm or

Tyre Size: F: _____

R: _____

195/65R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Sailun

Front

Rear

R/Bal. 8 mmR/Bal. 8 mmL/Bal. 8 mmL/Bal. 8 mmD.O.A. 14/4/22D.O.I. 18/4/2022

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Report Format :

Lump Sum / I.B.I. (\$ _____)

Not Authorized
11 Sep 8

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD9443E

AAD2204-

Vehicle No.:

Chassis No.:

Co UEN:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

18 APR 2022

SHD9443E

JTDKB3FU903080508

200303878K

TOYOTA

PRIUS

14/04/2022

SLC9265K/CHINA

24/05/2019

PART		LIST	
1	COVER, REAR BUMPER	\$	R ₁ 442.60 ✓
1	REINFORCEMENT SUB-ASSY, REAR BUMPER	\$	R ₁ 332.70 ✓
1	COVER, REAR BUMPER, LOWER	\$	R ₁ 15.40 ✓
1	GUARD, REAR BUMPER, CENTER	\$	R ₁ 576.30 ✓
1	RETAINER, REAR BUMPER SIDE, LH	\$	R ₁ 116.50 ✓
1	RETAINER, REAR BUMPER SIDE, RH	\$	R ₁ 117.70 ✓
1	FILLER, REAR BUMPER EXTENSION, RH	\$	R ₁ 123.70 ✓
1	FILLER, REAR BUMPER EXTENSION, LH	\$	R ₁ 123.70 ?
1	PANEL SUB-ASSY, BACK DOOR	\$	R ₁ 1,147.80 ✓
1	GARNISH SUB-ASSY, BACK DOOR, OUTSIDE	\$	R ₁ 925.60 ✓
1	BOARD ASSY, BACK DOOR TRIM	\$	R ₁ 259.20 ?
1	WEATHERSTRIP, BACK DOOR	\$	R ₁ 372.30 X
1	BOARD, BACK DOOR TRIM	\$	R ₁ 225.20 X
1	LENS & BODY, REAR COMBINATION LAMP, RH (UPPER)	\$	R ₁ 451.80 ?
1	LENS AND BODY, REAR LAMP, RH (LOWER)	\$	R ₁ 502.00 ?
1	LENS & BODY, REAR COMBINATION LAMP, LH (UPPER)	\$	R ₁ 443.30 ?
1	LENS AND BODY, REAR LAMP, LH (LOWER)	\$	R ₁ 502.00 ?
1	BOX, DECK FLOOR, RH	\$	R ₁ 313.60 X
1	BOX, DECK FLOOR, LH	\$	R ₁ 313.00 X
1	BOARD, REAR FLOOR, NO.1	\$	R ₁ 519.00 ?
1	BOX, DECK FLOOR, REAR	\$	R ₁ 105.80 ?
1	PANEL ASSY, DECK TRIM SIDE, LH	\$	R ₁ 355.90 X
1	COVER, FLOOR UNDER, NO.1 LH	\$	R ₁ 175.10 ?
1	COVER, FLOOR UNDER, NO.2 RH	\$	R ₁ 241.90 ?
1	COVER, REAR FLOOR CTR	\$	R ₁ 229.90 ✓
1	COVER, DECK TRIM, REAR	\$	R ₁ 126.70 ?
1	PAN, REAR FLOOR	\$	R ₁ 583.40 ?

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

AAD2204-**SHD9443E**

1	PANEL SUB-ASSY, BODY LOWER BACK	\$	As	650.30	✓
1	LOCK ASSY, BACK DOOR, W/COURTESY LAMP SWITCH	\$	R	467.00	X
1	SWITCH ASSY, BACK DOOR OPENER	\$	SL	179.10	X
1	SEAL, REAR BUMPER SIDE, LH	\$	SL	88.50	X
1	STAY ASSY, BACK DOOR, LH	\$	SL	242.50	X
1	STAY ASSY, BACK DOOR, RH	\$	SL	242.50	X
1	HINGE ASSY, BACK DOOR, LH	\$	R	61.00	X
1	HINGE ASSY, BACK DOOR, RH	\$	R	61.00	X
1	REAR TAILGATE TOYOTA LOGO	\$	SL	47.90	✓
1	REAR TAILGATE WORDING 'PRIUS'	\$	SL	54.60	✓
1	REAR TAILGATE WORDING 'HYBRID'	\$	SL	54.60	✓
1	COVER, FRONT BUMPER	\$	As	516.00	✓
1	BRACKET, FRONT BUMPER EXTENSION MOUNTING	\$		103.40	?
1	REINFORCEMENT SUB-ASSY, FRONT BUMPER	\$	As	716.60	✓
1	REINFORCEMENT, FRONT BUMPER, NO.2	\$		246.10	?
1	ABSORBER, FRONT BUMPER, LOWER	\$	CM	132.70	✓
1	ABSORBER, FRONT BUMPER ENERGY	\$		79.60	?
1	SUPPORT, FRONT BUMPER SIDE, RH	\$	DIS	80.10	✓
1	SUPPORT, FRONT BUMPER SIDE, LH	\$	SL	82.30	X
1	EXTENSION, FRONT BUMPER, RH	\$		120.10	?
1	EXTENSION, FRONT BUMPER, LH	\$	SL	120.10	X
1	COVER, FRONT BUMPER HOLE, RH	\$	SL	29.30	✓
1	COVER, FRONT BUMPER HOLE, LH	\$	SL	29.30	✓
1	UNIT ASSY, HEADLAMP, LH	\$		2,637.60	?
1	UNIT ASSY, HEADLAMP, RH	\$	CM	2,637.60	✓
1	GRILLE SUB-ASSY, RADIATOR	\$	CM	346.00	✓
1	GRILLE, RADIATOR, LOWER NO.1	\$		170.10	?
1	EMBLEM ASSY, RADIATOR GRILLE	\$	SL	90.80	✓
1	FENDER SUB-ASSY, FRONT RH	\$	SL	977.80	✓
1	LINER, FRONT FENDER, RH	\$	SL	206.70	X
1	EMBLEM, SIDE PANEL	\$	SL	54.60	✓
1	FENDER SUB-ASSY, FRONT LH	\$	R	977.80	X
1	LINER, FRONT FENDER, LH	\$	SL	202.50	X
1	EMBLEM, SIDE PANEL	\$	SL	54.60	X
1	SUPPORT, RADIATOR, UPPER RH	\$	SL	78.90	✓
1	SUPPORT, RADIATOR, UPPER LH	\$	R	78.90	X
1	SUPPORT SUB-ASSY, RADIATOR, UPPER	\$		377.10	?

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

AAD2204-**SHD9443E**

- 1 SUPPORT SUB-ASSY, RADIATOR, LOWER
- 1 SUPPORT SUB-ASSY, RADIATOR, LH
- 1 SUPPORT SUB-ASSY, RADIATOR, RH
- 1 HOOD SUB-ASSY
- 1 HINGE ASSY, HOOD, LH
- 1 HINGE ASSY, HOOD, RH
- 1 BRACE, HOOD LOCK SUPPORT
- 1 INSULATOR, HOOD
- 1 LOCK ASSY, HOOD
- 1 SEAL, HOOD TO FRONT END PANEL
- 1 JAR ASSY, WINDSHIELD WASHER
- 1 CONDENSER ASSY, COOLER
- 1 CLEANER ASSY, AIR
- 1 BRACKET, HEADLAMP, LH
- 1 BRACKET, HEADLAMP, RH
- 1 BRACKET, FRONT BUMPER SIDE, LH
- 1 BRACKET, FRONT BUMPER SIDE, RH
- 1 COVER, RADIATOR SUPPORT OPENING

\$	R	409.90	X
\$		245.10	?
\$		245.10	?
\$	Bu	983.10	✓
\$	DIT	58.90	✓
\$	DIT	58.90	✓
\$		78.30	?
\$	CM	410.90	—
\$	DIT	135.00	✓
\$	Ru	51.60	—
\$		219.10	?
\$		1,783.20	?
\$		1,147.00	?
\$	Ru	34.80	X
\$		34.80	?
\$	Ru	59.30	X
\$	Ru	59.30	X
\$	DIT	235.30	✓
TOTAL	\$	29,187.30	
25%	\$	7,296.83	
	\$	21,890.48	

Special Nett

- 1SET PARKING AID
- 1SET REAR BUMPER CLIP
- 2 WINDSCREEN SEALANT
- 1 WINDSCREEN MOULDING
- 1 WINDSCREEN INNER SPONGE SEAL
- 1 REAR TAILGATE STICKER "Trans-Cab"
- 1 REAR TAILGATE STICKER "6555-3333"
- 1 REAR BUMPER PROTECTOR
- 2 SEAM SEALANT
- 1SET REAR BUMPER RETAINER CLIP
- 1 REAR NUMBER PLATE WITH HOLDER
- 1SET TAILLAMP LOWER CLIP
- 1SET TAILLAMP UPPER CLIP
- 1 END PANEL TRIM CLIP

\$	CPT	700.00	2205n
\$	Ru	95.00	605n
\$	Ru	150.00	805n
\$	Ru	200.00	—
\$	Ru	130.00	305n
\$	Ru	80.00	305n
\$	Ru	80.00	305n
\$	NSP	180.00	X
\$	nn	250.00	X
\$	nn Ru	85.00	605n X
\$	Del	140.00	455n
\$	nn	55.00	X
\$	nn	55.00	X
\$	nn	65.00	X

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

AAD2204-

SHD9443E

1 REAR SPOILER CLIP	\$	nn	70.00	60X
1SET BUMPER CLIP FRT	\$	nn	95.00	60sn
1 FRONT NUMBER PLATE WITH MOULDING	\$	Ry	200.00	45sn
1SET CLIP, FRONT FENDER LINER	\$	nn	85.00	X
1SET FRNT BUMPER RETAINER CLIP	\$	nn	85.00	X
1 HOOD INSULATOR CLIP	\$	nn	55.00	✓
TOTAL		\$	2,855.00	
TOTAL PARTS		\$	24,745.48	

LABOUR

To Remove And Refit Rear Big and Small W/Screen Glass To Facilitate Bodywork Repair.	\$		300.00	180l
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$		380.00	80l
To transfer of luggage floor panel fittings, attachment and perform water seepage test.	\$	nn	380.00	X
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	nn	2,200.00	1400l
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	nn	380.00	X
To transfer of Tailgate fittings, attachments and perform water seepage test.	\$	nn	180.00	60l
To remove and refit electrical wiring, battery and other necessary items to facilitate bodywork repair.	\$	nn	480.00	7
To transfer of Fender fittings, attachments and perform water seepage test.	\$	nn	480.00	X
To dismantle and refit aircon assy and attachment, vacuum and charge-in-gas.	\$		380.00	100l

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

AAD2204-

SHD9443E

Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	380.00	?
To check steering geometry and computer wheel alignment	\$	220.00	220.00 X
To Rust-Proofing and apply undercoat Of The Affected Areas.	\$	250.00	90%
Towing Fees	\$	150.00	50%
Putty And Spray Painting Of The Affected Portion.	\$	2,200.00	1760%
To reinstall rear bumper parking sensor.	\$	170.00	50%
To Check Electrical Lighting Concerned.	\$	170.00	40%
To transfer of luggage floor panel fittings, attachment and perform water seepage test.	\$	380.00	220.00 X
To transfer of tire, rim and on wheel balancing.	\$	220.00	220.00 X
To replace, refix and top up coolant for radiator	\$	170.00	?
To lift-up / out engine with gear box and refit.	\$	440.00	220.00 X
To remove and refit radiator support cross-member and other necessary items to enable bodywork repair.	\$	380.00	220.00 X
To conduct and perform a comprehensive vehicle diagnostic check and reset vehicle warning indicators.	\$	380.00	220.00 X
TOTAL	\$	10,290.00	

Over All Total \$ 35,035.48**LKK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

(PART-BY-PART) Repair Days**25 DAYS****10 days**

Acknowledged by Repairer

Signature:

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 15/04/2022 20:59 (SGT)
Date of Accident 14/04/2022 15:10 (SGT)
Exact Location of Accident Singapore
Additional Location Information PIE TOWARDS TUAS BEFORE KALLANG BAHRU EXIT
Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SHD9443E

INSURED/POLICYHOLDER

Is company? Yes
Name Of Registered Owner TRANS-CAB SERVICES PTE LTD
Company Reg No 2XXXXX878K
Email Address claims@transcab.com.sg
Mobile Phone No (Phone) +65-62876666
Alternative Phone No (Office) +65-62876666

VEHICLE PARTICULARS

Manufacturer Toyota
Model Prius
Variant -
Exact purpose for which vehicle was being used at time of accident Private hire
Are you claiming under your own insurance policy for repair to your vehicle? No - Claiming third party
Vehicle Category Taxi
Transmission Auto
CC 1767

INSURANCE COMPANY

Name of Insurance Company AXA Insurance Pte Ltd
Type of Coverage ThirdParty
Fleet Policy Yes
Policy Number VFX/P2413997
Cover Note Number -

DRIVER

Name of Driver CHEW CHOO GUAN
NRIC No SXXXX683Z

Date Of Birth	17/02/1960
Occupation	Outdoor
Date Of Driving Pass	03/07/1980
Driving experience	41 YEARS AND 9 MONTHS
Gender	Male
Mobile Number	(Phone) +65-91639162
Alt. Phone Number	-
Email Address	Claims@transcab.com.sg
Address	HDB Sims Vista, 52 Sims Place #02-134
Address complement	-
Postcode	380052
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Hirer
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Chain Collision
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	5
Was anybody injured in the Accident?	Yes
Was any injured conveyed to hospital by ambulance?	Yes
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	2
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

PASSENGER 1

Name	MOHAN RAI - 97776018
Gender	Male

DETAILS OF POLICE ACTION

Was the accident reported to the police?	Yes
Police Station Name	Mountbatten Neighbourhood Police Post
Police Station Phone No	(Phone) +65-18003449999
Alt. Police Station Phone No	(Fax) +65-64474185
Police Station Address	Blk 60 Dakota Crescent #01-213/ 215 Singapore 390060
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

REFER TO POLICE REPORT ATTACHED

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No
Was there any audio recorded?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLC9265K
Vehicle Manufacturer	Honda

Vehicle Model	Vezel
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	-
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SKU3431D
Vehicle Manufacturer	Kia
Vehicle Model	Niro
Vehicle Variant	-
Vehicle Colour	White
Vehicle Category	Private car
Name of Driver	ARCHER FONG JUN HAN
NRIC No	SXXXX703G
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number	UNKNOWN
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	Red
Vehicle Category	Private car
Name of Driver	-
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

DETAILS OF OTHER VEHICLE PROPERTY 4

Vehicle Registration Number	UNKNOWN
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	White
Vehicle Category	Private car
Name of Driver	-
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-

Nature Of Damage -
Details of property damaged in accident -
No. Of Passenger (Including Driver) -

INJURED PERSONS DETAILS


INJURED 1

Name of injured person	CHEW CHOO GUAN
Gender	Male
Phone No	(Phone) +65-91639162
Address	-
Address Complement	-
Post Code	-
Approximate Age Years Old	-
Injuries Sustained	-
Injured person in which vehicle?	-
Were seat belts worn?	SHD9443E
Was this injured conveyed to hospital by ambulance?	Yes
	No

INJURED 2

Name of injured person	MOHAN RAI - PASSENGER
Gender	Male
Phone No	(Phone) +65-97776018
Address	-
Address Complement	-
Post Code	-
Approximate Age Years Old	-
Injuries Sustained	-
Injured person in which vehicle?	SHD9443E
Were seat belts worn?	Yes
Was this injured conveyed to hospital by ambulance?	Yes

ACCIDENT DIAGRAM



Veh A: SHD9443E
Veh B: SLC9265K
Veh C: SKU3431D
Veh D: unknown (Red)
Veh E: unknown (white)

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

VERIFIED BY AJAX MARS (ARC)
REPORTING OFFICER
ANG QI HAO, VICTOR

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



**SINGAPORE
POLICE FORCE**



T/20220415/2068

1 of 3

Report No. T/20220415/2068

Police Station Of Origin:
Mountbatten NPP
60 Dakota Crescent #01-213 SINGAPORE
390060
Tel No: 1800-3449999

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made:
15/04/2022 18:31

Vide Report No.:
T/20220414/2121

Station Diary No.:
16

Informant's Particulars

Name of Informant: CHEW CHOO GUAN		Address: APT BLK 52 SIMS PLACE #02-134 SINGAPORE 380052	
ID Type / ID No.: NRIC NO / S1423683Z		Contact No.: Home/Office: Mobile: 91639162	
Nationality: SINGAPORE CITIZEN		Email:	
Sex: Male	Age: 62	Date of Birth: 17/02/1960	Type of Informant: Driver
Race: Chinese		Language:	Institution / School Name:
Occupation: Taxi driver		Driving Licence Information: Class: 3,4,5 Date of Expiry:	

General Information of the Accident

Type of Accident:	Injury Conveyed By Ambulance	Drink Drive: No	Date/Time of Accident: 14/04/2022 15:10	Type of Location: Straight Road
Location: PAN-ISLAND EXPRESSWAY				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: Dual Carriage Way		Traffic Control: Not Controlled	Traffic Volume: Moderate	
Type of Collision: Chain Collision		Anyone conveyed by ambulance: Yes		

Details of Vehicle Involved

Vehicle No.	Type				Condition	No of Passenger
SHD9443E	Car				Slightly Damaged	1
SKU3431D	Car				Slightly Damaged	1
SLC9265K	Car					3


Details of Person Involved

Any Pedestrian Involved: No		Use of Pedestrian Crossing: NA
No. of Pedestrians Injured: NIL		



**SINGAPORE
POLICE FORCE**

Police Station Of Origin
Mountbatten NPP
60 Dakota Crescent #01-213 SINGAPORE
390060
Tel No 1800-3449999



T/202204152008

2 of 1

Report No. T/202204152008

CONTINUATION OF REPORT

Driver			
Name	CHEW CHOO GUAN	ID No.	S1423583Z
Related Vehicle	SHD9443E (Car)	Contact No.	91639162
Hospital/Clinic	SIMS DRIVE MEDICAL CLINIC	Class of Driving Licence & Expiry Date	Class: 3,4,5 Date of Expiry: NIL
Date Treatment	14/04/2022	Date Discharge	14/04/2022
No. of Days granted Medical Leave	03	Degree of Injury	NIL
Driver			
Name	ARCHER FONG JUN HAN	ID No.	S9843703G
Related Vehicle	SKU3431D (Car)	Contact No.	NIL
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

Vide T/20220414/2121, I am making amendments to my taxi plate number, the correct plate number is SHD9443E.

On the 14/04/2022 at about 1510hrs, I was driving along Lane 1 at Pan Island Expressway before Kallang Bahru Exit 12.

While driving, one car (SKU3431D) that was driving in front of me suddenly jammed brake as such I applied brakes as well and managed to stop without colliding onto the front car. However, one car (SLC9265K) that was behind me did not stop on time and collided onto the rear of my car and the impact caused my car to move forward and hit onto the car in front of me.