

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

JOURNEY MOTORS
43 SPRINGSIDE WALK
SINGAPORE 786628

Contact : 98575910, 93793389

TP Chirn.
Veron.

TAX INVOICE

Repair Code : CLM15499

Date in : 30/03/2022

Vehicle Num. : SMG5249B

Model : HONDA SHUTTLE HYBRID 1.5 AUTO

Chassis/Eng# : GP72000649/LEB7100991

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
FRONT LH DOOR <i>Dented</i>	1	1275.40	✓ 1,275.40
FRONT LH DOOR BLACK TAPE - SET <i>new</i>	1	35.80	✓ 35.80
FRONT LH DOOR GLASS OUTER MOULDING <i>new</i>	1	75.60	✓ 75.60
FRONT LH DOOR SIDE MIRROR <i>Dented</i>	1	573.20	✓ 573.20
FRONT LH DOOR SIDE MIRROR COVER <i>Replaced</i>	1	47.30	✓ 47.30
FRONT LH FENDER <i>Repaired</i>	1	1010.90	✓ 1,010.90
FRONT LH FENDER INNER SHIELD <i>new</i>	1	93.70	✓ 93.70
Subtotal before discount			3,111.90
Percentage discount 20%			622.38
Sub-total 1			2,489.52
FRONT LH DOOR INNER INSULATOR MAT <i>new</i>	1	250.00	✓ 250.00
FRONT LH FENDER INNER SHIELD CLIPS - SET <i>new</i>	1	50.00	✓ 50.00
Subtotal before discount			300.00
Percentage discount 0%			0.00
Sub-total 2			300.00
Parts-total			2,789.52

LABOUR

To transfer door glass, regulator gear, motor, railing, channel, trim board, mechanism lock and handle.

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

60 ~~80.00~~
500 ~~700.00~~

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

JOURNEY MOTORS
43 SPRINGSIDE WALK
SINGAPORE 786628

Contact : 98575910, 93793389

TAX INVOICE

Repair Code : CLM15499

Date in : 30/03/2022

Vehicle Num. : SMG5249B

Model : HONDA SHUTTLE HYBRID 1.5 AUTO

Chassis/Eng# : GP72000649/LEB7100991

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

To apply anti-rust chemical on repaired and replaced panel.

880

200 500.00

20 50.00

Labour Total

1,330.00

Parts & Labour Total

4,119.52

Adm Li
2/5 09/05/22

*** This is a computer-generated document which requires no signature.***

page 2

04 days

total: 2425.36

2/5 1.8K ✓

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: