

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No.: 6287 6666 Fax No.: 6257 1330

CO./GST Reg. No. 201019626G

SHD9889C

*Not Authorised
February 84 paint*

AAD2204-

~~8,506.48~~

\$ 5053.45

Vehicle No.:

Chassis No.:

Co UEN:

Vehicle Make:

Vehicle Model:

Date of Accident:

Third Party Insurer:

Date of Registration:

19 APR 2022

SHD9889C

JTDKB3FU003091476

200303878K

TOYOTA

PRIUS GEN 4

16/04/2022

SMK 4055 / Auto & General

11/09/2020

PART	LIST	
1 COVER, FRONT BUMPER	\$ R 521.00	✓
1 COVER, FRONT BUMPER HOLE, LH	\$ R 30.20	✓
1 ABSORBER, FRONT BUMPER ENERGY	\$ CM 80.20	✓
1 REINFORCEMENT SUB-ASSY, FRONT BUMPER	\$ R 716.60	X
1 MOULDING, FRONT BUMPER SIDE, LH	\$ my oil 95.60	✓
1 BRACKET, FRONT BUMPER SIDE, LH	\$ D.Y 59.30	✓
1 HOOD SUB-ASSY	\$ R 983.10	X
1 HINGE ASSY, HOOD, LH	\$ R 58.90	X
1 HINGE ASSY, HOOD, RH	\$ R 58.90	X
1 GRILLE SUB-ASSY, RADIATOR	\$ D.Y 422.50	✓
1 GRILLE, RADIATOR, LOWER NO.1	\$ R 178.60	X
1 EMBLEM ASSY, RADIATOR GRILLE	\$ R 105.80	✓
1 LINER, FRONT FENDER, LH	\$ R 210.30	X
1 FENDER SUB-ASSY, FRONT LH	\$ R 977.80	✓
1 FRONT FENDER EMBLEM LH	\$ R 54.60	✓
1 UNIT ASSY, HEADLAMP, LH	\$ my oil 2,637.60	✓
1 RIM	\$ R 1,900.10	X
TOTAL	\$ 9,091.10	
25%	\$ 2,828.00	
	\$ 8,484.00	

Special Nett

1 FRT FENDER CLIP	\$ R 65.00	X
1 BONNET INSULATOR CLIP	\$ R 65.00	X
1 FRONT NUMBER PLATE WITH HOLDER	\$ R 200.00	4512
1SET FRONT FENDER LINER CLIP	\$ R 75.00	X
1SET FRONT BUMPER CLIP	\$ R 90.00	6012

REF: AGG/ 22.00.311 - 11

Trans-cab Auto Services Pte Ltd

AAD2204-

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD9889C

TOTAL \$ 495.00

TOTAL PARTS \$ 9,530.50

LABOUR

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	1,600.00	500
	\$	nn 380.00	X
To Rust-Proofing and apply undercoat Of The Affected Areas.	\$	240.00	300
To check steering geometry and computer wheel alignment	\$	nn 220.00	X
Putty And Spray Painting Of The Affected Portion.	\$	1,600.00	6600
To transfer of tire, rim and on wheel balancing.	\$	nn 170.00	X
To Check Electrical Lighting Concerned.	\$	170.00	200

TOTAL \$ 4,380.00

Over All Total \$ 13,359.00

(PART-BY-PART) Repair Days

20 days

3 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Report Format :

Imp Sum / I.B.I: (\$

Interview (\$

Tech Invs (\$

Weekend (\$

) Parts

) Others

TOTAL