



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

SOMPO INSURANCE SINGAPORE PL

50 RAFFLES PLACE #03-03

SINGAPORE LAND TOWERSINGAPORE 048623

Ref: CS/SMO22003575/Aqy3

Date: 19/04/2022

Code: SMO

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBG 9730G	Veh. Inspected	SBS 3087G
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD2201175/THE	Excess (\$)	0.00
Assign From	GRACE TEO	Assign Date	19/04/2022

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	06/04/2022	Inspection Date	19/04/2022
Survey held at	SBS TRANSIT LTD (Branch) BUKIT BATOK ST 23 SINGAPORE 659519		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--