

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22003578/KQY3N2**Date:** 24/05/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNA00049832100

Claimant Vehicle No : SMK4345S **Insured Vehicle No :** GBL2192D

Date of Loss: 17/04/2022 Nature of Claim: TP Claim No: SNM22D202636/C02/LEEPG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMK4345S**

Make & Model: RENAULT GRAND SCENIC IV, 1.5 (A) Engine No: K9KF649D059614

Reg. Date: 10/04/2019 (Man. Year: 2019) Chassis No: VF1RFA00X62476795

Colour: Metallic Black Odometer: 186494 km

Engine Capacity: 1461 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/55R20 Rear Tyre Size: 195/55R20

Front Left Side: Goodyear 9 mm Rear Left Side: Goodyear 7 mm

Front Right Side: Goodyear 9 mm Rear Right Side: Goodyear 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,292.37	2,642.08	2,650.29	50.08
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,670.00	860.00	1,810.00	67.79
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	7,962.37	3,502.08	4,460.29	56.02
Approved Total (Overridden) (\$\$)		2,800.00		
(\$\$)	7,962.37	2,800.00	5,162.37	64.83
+ GST 7.00/7.00% (\$\$)	557.37	196.00	361.37	64.83
Nett Amount (\$\$)	8,519.74	2,996.00	5,523.74	64.83

INSPECTION

Date of Assignment: 19/04/2022

Date Inspected: 19/04/2022 Inspected At: Munich Autocare Pte Ltd (HQ)
60 Jalan Lam Huat, #07-43
Singapore 737869

Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 24 May 2022)	
Parts:	N/A	RENAULT GRAND SCENIC IV 1.5 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMK4345S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT HEADLAMP RH	Broken	1,071.00 F	*1,071.00 FL
2	1		*FRONT BUMPER SIDE BRACKET RH	Distorted	192.84 F	*192.84 FL
3	1		*FRONT BUMPER INNER BRACKET RH	Serviceable	192.84 F	*- FL
4	1		*FRONT HEADLAMP BRACKET	Serviceable	192.84 F	*- FL
5	1		*FRONT BUMPER	Buckled	1,748.76 F	*1,289.00 FL
6	1		*FRONT PARKING SENSOR RH	Serviceable	291.60 F	*- FL
7	1		*FRONT BLIND SPORT SENSOR RH	Serviceable	457.92 F	*- FL
8	1		*FRONT FOGLAMP MOULDING (CHROME)	Cracked	313.68 F	*172.40 FL
9	1		*FRONT FOGLAMP COVER	Cut	313.68 F	*210.40 FL
10	1		*FRONT BUMPER LOWER LIP	Serviceable	517.21 F	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$)	5,292.37	2,935.64
- List Item Discount on L Items 0.00/10.00% (\$)	0.00	293.56
Total Parts (\$)	5,292.37	2,642.08

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO WELDING REALIGN FRONT BUMPER,FRONT FENDER RH.FRONT PARKING & BLIND SPORT SENSOR,AND ALL NECESSARY ETC	New	1,200.00	400.00
2	TO REPLACE ALL SENSOR WIRE HARDNESS FOR PROPER FUNCTION INCLUDING ADJUSTMENT OF HEADLAMP	New	120.00	20.00
3	TUFF KOTE AND SPRAY ANTI PROOFING	New	150.00	0.00
4	TO RESPRAY FRONT ACCIDENT PORTION,BUMPER LOWER LIP,FENDER RH	New	1,200.00	440.00
Gross Labour Cost (\$\$)			2,670.00	860.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >