



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
17 UBI ROAD 4
SINGAPORE 408611, Tel no.: 6631 1188



TOYOTA

Longpac clear

TP/DS

ESTIMATE

Account Details		Account No.	Customer Details	
THIRD PARTY CLAIM	<i>Liability Check</i>	S1000020 / TPCLAIM	Ms Teh Poh Hoon	
		Document No. 0	205 Serangoon Central #10-136 Singapore 550205	
		Document Date 18/04/2022	Mobile: 96556606	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2019	ACR50R	GFXSK E1	15/10/2020	SMV6753B	0	21743	69DS/SMV6753B
Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On		
JTEGD56M607173969	2AZ1B14921	60	Raymond Seah L M	--/--/----	0.00 --/--/----	0.00	

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY-AI SUNDRIES TP VEH:GBF5447G ACC DATE:18/04/2022 TP INS: NO OF REPAIR DAYS: DATE-IN: DATE SURVEY: BY: AUTHORISED ON: -TP/DS CLAIM				✓ ✓ 30.00
2	Z	BP-SLANT SUPPLY SEALANT (NETT) FOR REAR TAILGATE AND REAR END PANEL				✓ 60 120.00
3	B	BP-ECU2 TO RESET ECU AND REPROGRAMME <i>-report</i>				✓ 180.00
4	S	BP-SUBLET TO SUPPLY AND INSTALL REAR WINDSCREEN 3M SOLAR FILM.				✓ 400.00
5	B	BP-WS R/I REAR WINDSCREEN TO FACILIATE REPAIRS.				✓ 462.00
6	B	BP-LAB2 TO CHECK WIRING AND LIGHTING. TO WATER TEST FOR LEAK.				✓ 122.40
7	B	BP-LAB2 R/I REAR REVERSE SENSOR TO FACILIATE REPAIRS AND TEST FUNCTION.				✓ 180.00
8	B	BP-LAB2 TO TRANSFER REAR TAILGATE BOARD, TOP SPOILER, REAR CAMERA, MECHANISM AND OTHER ATTACHMENT TO NEW PANEL.				✓ 360.00

For & on behalf of Borneo Motors (Singapore) Pte Ltd	Customer's Signature	Charge Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others	Less Amount Due

Customer Copy



Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
17 UBI ROAD 4
SINGAPORE 408611, Tel no.: 6631 1188

ESTIMATE

Account Details		Account No.	Customer Details	
THIRD PARTY CLAIM		S1000020 / TPCLAIM	Ms Teh Poh Hoon	
		Document No. 0	205 Serangoon Central #10-136 Singapore 550205	
		Document Date 18/04/2022	Mobile: 96556606	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2019	ACR50R	GFXSK E1	15/10/2020	SMV6753B	0	21743	69DS/SMV6753B
Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On		
JTEGD56M607173969	2AZ1B14921	60	Raymond Seah L M	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
9	B	BP-LAB2 R/I REAR CARPET, TRIMMING, REAR SEATS AND OTHER ATTACHMENT TO FACILITATE REPAIRS.				✓ 360.00
10	B	BP-LAB2 TO REPLACE REAR ACCIDENT DAMAGE PARTS. STRAIGHTEN/REALIGN ALL OTHER AFFECTED AREAS.				✓ 1440 4320.00
11	B	BP-RES2 TO SPRAY PAINT ON REAR ACCIDENT AFFECTED AREAS.				✓ 1770 3540.00
12	S	PSP PER PANE LABOUR FOR PLATINUM SHINEPRO & SHINE PER PANEL APPLICATION				✓ 183.18
13	1	T89341-42060 B6 SENSOR, ULTRASONIC, ?	1.00	392.80		? 392.80
14	2	T89348-12020 CLIP, ULTRASONIC	2.00	10.20		? 20.40
15	3	T89341-60051 B2 SENSOR, ULTRASONIC, ? } X NN	2.00	392.80		? 785.60
16	4	T89997-28010 ANTENNA, ELECTRICAL ?	1.00	203.20		? 203.20
17	5	T81551-28660 LENS & BODY, RR } free use	1.00	607.00		+ 607.00
18	6	T81561-28660 LENS & BODY, RR	1.00	607.00		+ 607.00
19	7	T81581-28300 LENS & BODY, RR } covered	1.00	784.90		✓ 784.90
20	8	T81591-28300 LENS & BODY, RR	1.00	784.90		✓ 784.90
21	9	T76801-28460 GARNISH SUB-ASSY, covered	1.00	357.50		✓ 357.50
22	0	T76817-26040 CLIP, BACK DOOR * ? X NN	2.00	3.80		? 7.60
23	1	SPZ067-0M001 REVERSE CAMERA FOR NEW WISH ? X NN	1.00	360.00		? 360.00
24	2	SPZ067-28805 BACK CAMERA WIRE HARNESS not use	1.00	33.20		+ 33.20

For & on behalf of Borneo Motors (Singapore) Pte Ltd	Customer's Signature	Charge Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others	Less Amount Due

Customer Copy

Adrian Lj
P/P 04/05/22.
06 Pys.



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
17 UBI ROAD 4
SINGAPORE 408611, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details		Account No.	Customer Details	
THIRD PARTY CLAIM		S1000020 / TPCLAIM	Ms Teh Poh Hoon	
		Document No.	205 Serangoon Central	
		0	#10-136	
		Document Date	Singapore 550205	
		18/04/2022	Mobile: 96556606	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2019	ACR50R	GFXSK E1	15/10/2020	SMV6753B	0	21743	69DS/SMV6753B
Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On		
JTEGD56M607173969	2AZ1B14921	60	Raymond Seah L M	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
25	3	T52159-28959 COVER, RR BUMPER <i>Deformed</i>	1.00	632.00		632.00
26	4	S52161-0K040 PIECE, RR BUMPER <i>Neu</i>	4.00	4.30		17.20
27	5	T52155-28080 SUPPORT, RR BUMPER <i>Neu</i>	1.00	61.20		61.20
28	6	T52156-28050 SUPPORT, RR BUMPER <i>Neu</i>	1.00	61.20		61.20
29	7	T52155-28090 SUPPORT, RR BUMPER <i>Neu</i>	1.00	42.90		42.90
30	8	T52156-28060 SUPPORT, RR BUMPER <i>Neu</i>	1.00	42.90		42.90
31	9	T52615-28051 ABSORBER, RR BUMPER ?	1.00	84.20		84.20
32	0	T52616-28021 ABSORBER, RR BUMPER ?	1.00	84.20		84.20
33	1	T58307-28110 PANEL SUB-ASSY, BODY ? } X NN	1.00	800.10		800.10
34	2	T67939-28041 C0 GARNISH, BACK DOOR ?	1.00	205.70		205.70
35	3	T67935-28090 C0 PLATE, BACK DOOR ?	1.00	297.30		297.30
36	4	T68105-28680 GLASS SUB-ASSY, BACK ?	1.00	1368.60		1368.60
37	5	T21000-20 SIKA 182010 SIKA TACK GO! (BLA ? <i>Neu</i>	2.00	108.00		216.00
38	6	T21000-22 SIKA 207. G+P ADHESIVE PRIMER ?	1.00	200.00		200.00
39	7	T67005-28D10 PANEL SUB-ASSY, BACK <i>Deformed</i>	1.00	1858.00		1858.00
40	8	T67881-28120 WEATHERSTRIP, BACK <i>not neu</i>	1.00	394.20		394.20
41	9	T76802-28070 GARNISH SUB-ASSY, ?	1.00	243.30		243.30
42	0	T69350-28161 LOCK ASSY, BACK DOOR ? } X NN	1.00	519.80		519.80
43	1	T69321-28020 COVER, BACK DOOR <i>Not neu</i>	1.00	42.00		42.00
44	2	T69430-28050 STRIKER ASSY, BACK <i>not neu</i>	1.00	43.40		43.40

For & on behalf of Borneo Motors (Singapore) Pte Ltd	Customer's Signature	Charge Summary	Total	✓
	Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others	Less	
			Amount Due	

Customer Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
17 UBI ROAD 4
SINGAPORE 408611, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details		Account No.	Customer Details	
THIRD PARTY CLAIM		S1000020 / TPCLAIM	Ms Teh Poh Hoon	
		Document No.	205 Serangoon Central	
		0	#10-136	
		Document Date	Singapore 550205	
		18/04/2022	Mobile: 96556606	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2019	ACR50R	GFXSK E1	15/10/2020	SMV6753B	0	21743	69DS/SMV6753B

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
JTEGD56M607173969	2AZ1B14921	60	Raymond Seah L M	--/--/----	0.00 --/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
45	3	T75441-28730 PLATE, LUGGAGE COMPT	1.00	46.80		✓ 46.80
46	4	T75441-28720 PLATE, BACK DOOR	1.00	60.70		✓ 60.70
47	5	T90975-02064 EMBLEM, SYMBOL	1.00	72.20		✓ 72.20
		T081920 -13022 REFLECTOR ASSY NEC	1.00	63.40		✓ 63.40
		T090541-10042 CUSHION NEC	2.00	8.00		✓ 16.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

For & on behalf of Borneo Motors (Singapore) Pte Ltd	Customer's Signature	Charge Summary	Total	22,595.58
	Please acknowledge receipt of vehicle	Parts	12,338.00	GST 7.00%
		Labour	9,674.40	1,581.69
		Sublet	583.18	Less
		Lubrication/Fluid	0.00	0.00
		Others	0.00	Amount Due

Customer Copy