

**Borneo Motors**

Inchcape

Co. Reg No. : 196700086Z

GST Reg No. : MR-8500000-9

17 UBI ROAD 4

SINGAPORE 408611, Tel no.: 6631 1188

**TOYOTA****ESTIMATE**

Account Details			Account No.		Customer Details			
MS First Capital Insurance Ltd 36 Robinson Road #16-01 City House Singapore 068877 Attn: Motor Claims Dept			S1000005 / ICFIC1		Mdm Yeo Ling May 10 Limau Terrace Singapore 465808 Mobile: 92340335			
			Document No. 0					
			Document Date 14/06/2022					
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks	
2010	NCP93R	BEPGKT G1	12/11/2010	SJZ3073P	0	21740	69DS/SJZ3073P	
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On	
MR053HY9305161433		1NZY079462	60	Raymond Seah L M	20/04/2022	8.27	22/04/2022 18.00	
L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount		
1	Z	BP-SUNDRY-MS SUNDRIES TP VEH:SHD6130C ACC DATE:14/04/2022 TP INS:1ST CAPITAL NO OF REPAIR DAYS:18 TOW-IN:14/04/2022 DATE SURVEY:19/04/2022 BY:LKK-GUO QIANG AUTHORISED ON:21/04/2022 -TP/DS CLAIM				30000.00		
2	M	BP-REC TO CONDUCT ACCIDENT REPAIR @ LIMIT \$30,000						
For & on behalf of Borneo Motors (Singapore) Pte Ltd			Customer's Signature		Charge Summary		Total 30,000.00	
			Please acknowledge receipt of vehicle		Parts	0.00	GST 7.00%	2,100.00
					Labour	30,000.00	Less	0.00
					Sublet	0.00		
					Lubrication/Fluid	0.00		
					Others	0.00	Amount Due	32,100.00

Customer Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
17 UBI ROAD 4
SINGAPORE 408611, Tel no.: 6631 1188



TOYOTA

Lini 730K

FOR YOUR REFERENCE

ESTIMATE

Account Details			Account No.		Customer Details		
MS First Capital Insurance Ltd 36 Robinson Road #16-01 City House Singapore 068877 Attn: Motor Claims Dept			S1000005 / ICFIC1		Mdm Yeo Ling May 10 Limau Terrace Singapore 465808 Mobile: 92340335		
			Document No. 0				
			Document Date 14/06/2022				
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2010	NCP93R	BEPGKT G1	12/11/2010	SJZ3073P	0	21740	69DS/SJZ3073P
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On
MR053HY9305161433		1NZY079462	60	Raymond Seah L M	20/04/2022	8.27	22/04/2022 18.00
L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount	
1	Z	BP-SUNDRY-MS SUNDRIES TP VEH:SHD6130C ACC DATE:14/04/2022 TP INS:1ST CAPITAL NO OF REPAIR DAYS:18 TOW-IN:14/04/2022 DATE SURVEY:19/04/2022 BY:LKK-GUO QIANG AUTHORISED ON:21/04/2022 -TP/DS CLAIM				✓	30.00
2	S	BP-SUBLET TO SUPPLY FRONT NUMBER PLATE WITH CASING.	0263			✓	68.00
3	S	BP-SUBLET TO RESET ECU AND REPROGRAMME				✓	180.00
4	S	BP-SUBLET TO CHECK WIRING AND LIGHTING. TO FOCUS HEADLAMP.				✓	122.40
5	S	BP-SUBLET TO REPLACE FRONT ACCIDENT DAMAGE PARTS. STRAIGHTEN/REALIGN ALL OTHER AFFECTED AREAS.				✓	2160.00
6	S	BP-SUBLET TO SPRAY PAINT ON FRONT ACCIDENT AFFECTED AREAS.				✓	1770.00
7	S	BP-SUBLET SUPPLY SEALANT (NETT) FOR REAR BOOTLID,REAR END PANEL AND SPARE TYRE PANEL.				✓	180.00
8	S	BP-SUBLET R/I REAR EXHAUST PIPE TO FACILIATE REPAIRS.				✓	720.00
For & on behalf of Borneo Motors (Singapore) Pte Ltd			Customer's Signature		Charge Summary		Total
			Please acknowledge receipt of vehicle		Parts Labour Sublet Lubrication/Fluid Others		Less
							Amount Due

Company Copy

**Borneo Motors**

Inchcape

Co. Reg No. : 196700086Z
 GST Reg No. : MR-8500000-9
 17 UBI ROAD 4
 SINGAPORE 408611, Tel no.: 6631 1188

**TOYOTA****ESTIMATE**

Account Details			Account No. S1000005 / ICFIC1		Customer Details			
MS First Capital Insurance Ltd 36 Robinson Road #16-01 City House Singapore 068877 Attn: Motor Claims Dept			Document No. 0		Mdm Yeo Ling May 10 Limau Terrace Singapore 465808 Mobile: 92340335			
			Document Date 14/06/2022					
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks	
2010	NCP93R	BEPGKT G1	12/11/2010	SJZ3073P	0	21740	69DS/SJZ3073P	
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On	
MR053HY9305161433		1NZY079462	60	Raymond Seah L M	20/04/2022	8.27	22/04/2022 18.00	
L	Cd	Job/Parts Description			Qty	Unit Price	Disc %	Amount
9	S	BP-SUBLET R/I FUEL TANK AND ATTACHMENT TO FACILITATE REPAIRS.						✓ 720.00
10	S	BP-SUBLET R/I REAR WINDSCREEN TO FACILITATE REPAIRS.						✓ 462.00
11	S	BP-SUBLET TO CONDUCT WATER LEAK TEST.						✓ 122.40
12	S	BP-SUBLET R/I REVERSE SENSOR TO FACILITATE REPAIRS AND TEST FUNCTION.						✓ 180.00
13	S	BP-SUBLET TO TRANSFER REAR BOOTLID MECHANISM TRIMMING AND OTHER ATTACHMENT						✓ 360.00
14	S	BP-SUBLET R/I REAR CARPET, TRIMMING, REAR SEATS AND OTHER ATTACHMENT TO FACILITATE REPAIRS.						✓ 720.00
15	S	BP-SUBLET TO REPLACE REAR ACCIDENT DAMAGE PARTS. STRAIGHTEN/REALIGN ALL OTHER AFFECTED AREAS.						✓ 5760.00
16	S	BP-SUBLET TO SPRAY PAINT ON REAR ACCIDENT AFFECTED AREAS.						✓ 4130.00
17	S	BP-SUBLET TO SUPPLY REAR NUMBER PLATE WITH CASING.			0263			✓ 68.00
18	1	S52119-0D996	COVER, FR BUMPER, L		1.00	525.80		525.80
19	2	S52721-0D902	MOULDING, FR BUMPER		1.00	16.30		16.30
20	3	S53112-0D120	GRILLE, RADIATOR, LW		1.00	97.20		97.20
For & on behalf of Borneo Motors (Singapore) Pte Ltd			Customer's Signature		Charge Summary		Total	
			Please acknowledge receipt of vehicle		Parts Labour Sublet Lubrication/Fluid Others		Less	
							Amount Due	

Company Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
17 UBI ROAD 4
SINGAPORE 408611, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details		Account No.		Customer Details			
MS First Capital Insurance Ltd 36 Robinson Road #16-01 City House Singapore 068877 Attn: Motor Claims Dept		S1000005 / ICFIC1		Mdm Yeo Ling May			
		Document No. 0		10 Limau Terrace			
		Document Date 14/06/2022		Singapore 465808			
				Mobile: 92340335			

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2010	NCP93R	BEPGKT G1	12/11/2010	SJZ3073P	0	21740	69DS/SJZ3073P

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
MR053HY9305161433	1NZY079462	60	Raymond Seah L M	20/04/2022 8.27	22/04/2022 18.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
21	4	S52021-0D090 REINFORCEMENT SUB-AS	1.00	423.90		423.90
22	5	S53164-0D031 BRACKET, RADIATOR SU	1.00	62.30		62.30
23	6	S53165-0D031 BRACKET, FR BUMPER S	1.00	62.30		62.30
24	7	S52617-0D050 ABSORBER, RADIATOR S	1.00	116.60		116.60
25	8	S53111-0D300 GRILLE,RADIATOR	1.00	490.50		490.50
26	9	S75301-0D010 EMBLEM SUB-ASSY, FR	1.00	71.60		71.60
27	0	S53201-0D130 SUPPORT SUB-ASSY, RA	1.00	1138.00		1138.00
28	1	S53285-0D061 SEAL RADIATOR SIDE A	1.00	28.20		28.20
29	2	S53286-0D061 SEAL,RADIATOR SIDE A	1.00	28.20		28.20
30	3	S53287-0D031 EXTENSION,RADIATOR S	1.00	47.80		47.80
31	4	S53288-0D031 EXTENSION RADIATOR	1.00	48.70		48.70
32	5	S53510-0D181 LOCK ASSY, HOOD	1.00	111.00		111.00
33	6	SPZ061-0D014 00 PRIMER SENSOR	1.00	162.66		162.66
34	7	S81550-0D330 LAMPASSY,RRCOMBINATI	1.00	291.40		291.40
35	8	S81560-0D330 LAMPASSY,RRCOMBINATI	1.00	291.40		291.40
36	9	S81910-0D010 REFLECTOR ASSY, REFL	1.00	97.90		97.90
37	0	S81920-0D010 REFLECTOR ASSY, REFL	1.00	97.90		97.90
38	1	S52159-0D983 COVER, RR BUMPER L/C	1.00	525.80		525.80
39	2	S52161-0K040 PIECE, RR BUMPER	4.00	4.30		17.20
40	3	S52575-0D070 RETAINER, RR BUMPER	1.00	109.20		109.20

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd			
	Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others	Less
			Amount Due

Company Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
17 UBI ROAD 4
SINGAPORE 408611, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details			Account No.		Customer Details			
MS First Capital Insurance Ltd 36 Robinson Road #16-01 City House Singapore 068877 Attn: Motor Claims Dept			S1000005 / ICFIC1		Mdm Yeo Ling May 10 Limau Terrace Singapore 465808 Mobile: 92340335			
			Document No. 0					
			Document Date 14/06/2022					
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks	
2010	NCP93R	BEPGKT G1	12/11/2010	SJZ3073P	0	21740	69DS/SJZ3073P	
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On	
MR053HY9305161433		1NZY079462	60	Raymond Seah L M	20/04/2022	8.27	22/04/2022 18.00	
L	Cd	Job/Parts Description			Qty	Unit Price	Disc %	Amount
41	4	S52576-0D070 RETAINER, RR BUMPER			1.00	109.20		109.20
42	5	S52155-0D030 SUPPORT, RR BUMPER S			1.00	36.90		36.90
43	6	S52156-0D030 SUPPORT, RR BUMPER S			1.00	36.90		36.90
44	7	S52591-0D080 SEAL, RR BUMPER SIDE			1.00	53.60		53.60
45	8	S52592-0D080 SEAL, RR BUMPER SIDE			1.00	53.60		53.60
46	9	S58307-0D101 PANEL SUB-ASSY, BODY			1.00	738.00		738.00
47	0	U58311-52210 PAN, RR FLOOR			1.00	739.90		739.90
48	1	S61601-0D160 PANEL SUB-ASSY, QUAR			1.00	1115.30		1115.30
49	2	S61063-0D010 TROUGH SUB-ASSY, LUG			1.00	136.10		136.10
50	3	S61602-0D180 PANEL SUB-ASSY, QUAR			1.00	1115.30		1115.30
51	4	S61064-0D010 TROUGH SUB-ASSY, LUG			1.00	136.10		136.10
52	5	T08826-08115 PANEL BONDING AD			2.00	267.20		534.40
53	6	S75573-0D050 MOULDING, BACK W/D, OS			1.00	87.20		87.20
54	7	T64813-52080 DAM, BACK WINDOW			1.00	45.70		45.70
55	8	T21000-20 SIKA 182010 SIKA TACK GO! (BLA			2.00	108.00		216.00
56	9	T21000-22 SIKA 207. G+P ADHESIVE PRIMER			1.00	200.00		200.00
57	0	S64401-0D090 PANEL SUB-ASSY, LUGG			1.00	706.10		706.10
58	1	S64461-0D050 WEATHERSTRIP, LUGGAG			1.00	205.80		205.80
59	2	S64610-0D030 LOCK ASSY, LUGGAGE C			1.00	112.90		112.90
60	3	S58387-0D010 PLATE, RR FLOOR FINI			1.00	236.40		236.40
For & on behalf of		Customer's Signature		Charge Summary		Total		
Borneo Motors (Singapore) Pte Ltd		Please acknowledge receipt of vehicle		Parts Labour Sublet Lubrication/Fluid Others		Less		
						Amount Due		

Company Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
17 UBI ROAD 4
SINGAPORE 408611, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details			Account No.		Customer Details		
MS First Capital Insurance Ltd 36 Robinson Road #16-01 City House Singapore 068877 Attn: Motor Claims Dept			S1000005 / ICFIC1		Mdm Yeo Ling May 10 Limau Terrace Singapore 465808 Mobile: 92340335		
			Document No. 0				
			Document Date 14/06/2022				
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2010	NCP93R	BEPGKT G1	12/11/2010	SJZ3073P	0	21740	69DS/SJZ3073P
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On
MR053HY9305161433		1NZY079462	60	Raymond Seah L M	20/04/2022	8.27	22/04/2022 18.00
L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount	
61	4	T90467-08186 B4 CLIP	2.00	2.90		5.80	
62	5	S64995-0D030 BOX, DECK FLOOR, RH	1.00	251.50		251.50	
63	6	S64997-0D030 BOX, DECK FLOOR, LH	1.00	201.40		201.40	
64	7	S64770-0D120 COVER ASSY, SPARE WH	1.00	134.30		134.30	
65	8	S64743-0D010 DOOR, DECK SIDE BOX,	1.00	62.60		62.60	
66	9	S64744-0D010 DOOR, DECK SIDE BOX,	1.00	47.80		47.80	
67	0	S64727-0D020 PAD, LUGGAGE COMPART	1.00	302.90		302.90	
68	1	S64711-0D080 C0 MAT, LUGGAGE COMPART	1.00	425.80		425.80	
69	2	S64719-0D030 C0 COVER,LUGGAGECOMPART	1.00	199.50		199.50	
70	3	S75442-0D070 PLATE, LUGGAGE COMPT	1.00	52.10		52.10	
71	4	S75431-02090 EMBLEM, LUGGAGE COMP	1.00	65.30		65.30	
72	5	S75444-0D070 PLATE, LUGGAGE COMPT	1.00	44.00		44.00	
73	6	S76801-0D906 GARNS/A,LUGCOMPTDOOR	1.00	200.00		200.00	
74	7	T58651-22H91 SHEET, RR FLOOR	1.00	219.90		219.90	
75	8	T90269-06017 RIVET	2.00	4.00		8.00	
76	9	S58316-0D060 EXTENSION, RR FLOOR ✓ DIS	1.00	148.70		148.70	
77	0	S58315-0D060 EXTENSION, RR FLOOR ✓ DIS	1.00	148.70		148.70	
78	1	S57615-0D901 MEMBER, RR FLOOR SID ✓ DIS	1.00	280.90		280.90	
79	2	S57616-0D901 MEMBER, RR FLOOR SID ✓ DIS	1.00	166.90		166.90	
80	3	S64722-0D040 C0 COVER, LUGGAGE COMPT ✓ CRUMP	1.00	262.70		262.70	
For & on behalf of Borneo Motors (Singapore) Pte Ltd			Customer's Signature		Charge Summary		Total
					Parts		Less
					Labour		
					Sublet		
					Lubrication/Fluid		
			Others				Amount Due

Company Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
17 UBI ROAD 4
SINGAPORE 408611, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details	Account No.	Customer Details
MS First Capital Insurance Ltd 36 Robinson Road #16-01 City House Singapore 068877 Attn: Motor Claims Dept	S1000005 / ICFIC1	Mdm Yeo Ling May 10 Limau Terrace Singapore 465808 Mobile: 92340335
	Document No. 0	
	Document Date 14/06/2022	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2010	NCP93R	BEPGKT G1	12/11/2010	SJZ3073P	0	21740	69DS/SJZ3073P
Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On		
MR053HY9305161433	1NZY079462	60	Raymond Seah L M	20/04/2022	8.27	22/04/2022	18.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
81	4	S64721-0D040 C0 COVER, LUGGAGE COMPT ✓ CRUMP	1.00	262.70		262.70
82	5	T52012-52020 ARM SUB-ASSY, FR X NN	1.00	224.50		224.50
83	6	T52011-52021 ARM SUB-ASSY, FR X NN	1.00	276.60		276.60
84	7	S17430-0M061 PIPE ASSY, EXHUAUST T ✓ BT	1.00	879.20		879.20
85	8	SPZ056-52001 MUFFLER CUTTER ✓ CUT	1.00	46.60		46.60
86	9	S88891-0D080 COVER, COOLER, NO.1 X NN	1.00	51.70		51.70
87	0	T64503-12150 ARM SUB-ASSY, LUG X NN	2.00	62.70		125.40
88	1	S62940-06030 DUCT A/S, QTR VENT repeated	1.00	144.90		144.90
89	2	S17565-0M020 SUPPORT, EXHAUST PIP ✓ NEC	2.00	24.70		49.40
90	3	S17565-0M020 SUPPORT, EXHAUST PIP ✓ NEC	1.00	24.70		24.70

For & on behalf of Borneo Motors (Singapore) Pte Ltd	Customer's Signature	Charge Summary	Total	34,544.56
	Please acknowledge receipt of vehicle	Parts 16,791.76 Labour 30.00 Sublet 17,722.80 Lubrication/Fluid 0.00 Others 0.00	GST 7.00% 2,418.12 Less 0.00 Amount Due 36,962.68	

labour 17752.8

parts 12498.46

Total: 30251.26

Repair limit: \$30k

Company Copy

Vehicle Diagnostic Report

1NZFE

SJZ3073P

Borneo Motors

Printed By: Default User(1)

20/6/2022 3:18:48 pm

Health Check Results

All Systems(1 of 1)

Enhanced

System	DTC Related Information							RoB	Calibration	Configure
	FFD	DTC	Curr Conf	Pend	Hist	Test Failed				
EMPS	No	U0100	X					-	-	No
Engine and ECT								-	30D54100	No
ABS/VSC/TRC								-	-	No
SRS Airbag								-	-	No
Combination Meter								-	-	No
Main Body								-	-	No

Vehicle Diagnostic Report

1NZFE

SJZ3073P

Borneo Motors

Printed By: Default User(1)

20/6/2022 3:19:19 pm

Health Check Results All Systems(1 of 1)

Enhanced

System	DTC Related Information						RoB	Calibration	Configure
	FFD	DTC	Curr Conf	Pend	Hist	Test Failed			
Engine and ECT							-	30D54100	No
EMPS							-	-	No
ABS/VSC/TRC							-	-	No
SRS Airbag							-	-	No
Combination Meter							-	-	No
Main Body							-	-	No