

HD Perfect Autowork Pte Ltd

Company Reg No: 202136904Z

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit
Singapore 415875

Tel : 6341 6789 Fax: 6341 6778

E-mail: hdperfectautowork@gmail.com



HD PERFECT
AUTOWORK PTE LTD

DATE : 18.04.2022

TO : EQ MOTOR CLAIMS DEPTS
VEHICLE NO : SKC1360H
MODEL : HYUNDAI ELANTRA
DATE OF ACCIDENT : 17.04.2022
TIME OF ACCIDENT : 17:15HRS

1CM14DH41CMC4243926

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT DOOR RH <i>Dented</i>	1	\$ 1,583.00	\$ 1,583.00
2	FRONT DOOR OUTER MOULDING RH <i>new</i>	1	\$ 130.00	\$ 130.00
3	FRONT DOOR GLASS FRAME BLACK STICKER RH <i>new</i>	1	\$ 160.00	\$ 160.00
4	FRONT DOOR WEATHER STRIP RH <i>new</i>	1	\$ 180.00	\$ 180.00
5	FRONT DOOR INNER LOCK RH <i>new</i>	1	\$ 435.00	\$ 435.00
6	REAR FENDER <i>Rocker Panel</i> RH <i>Dented</i>	1	\$ 966.00	\$ 966.00
7	REAR FENDER COWLING RH <i>new</i>	1	\$ 250.00	\$ 250.00
8	REAR WINDSCREEN MOULDING <i>new</i>	1	\$ 180.00	\$ 180.00
9	REAR DOOR RH <i>Distorted</i>	1	\$ 1,438.00	\$ 1,438.00
10	REAR DOOR INNER LOCK RH <i>Dented</i>	1	\$ 405.00	\$ 405.00
11	REAR DOOR GLASS REGULATOR GEAR MOTOR RH <i>Dented</i>	1	\$ 770.00	\$ 770.00
12	REAR DOOR GLASS FRAME BLACK STICKER RH <i>new</i>	1	\$ 160.00	\$ 160.00
13	REAR DOOR INNER TRIM BOARD RH <i>crushed</i>	1	\$ 850.00	\$ 850.00

TOTAL PRICE \$ 7,507.00
LESS 25% 20% \$ 1,876.75
SUB TOTAL PRICE \$ 5,630.25

SPECIAL NETT ITEMS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	FRONT DOOR TRIM BOARD CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00
2	CENTER PILLAR SEALANT RH (OUTER) <i>new</i>	1	\$ 50.00	\$ 50.00
3	SIDE SKIRT (SPECAIL TYPE) (SET) <i>Dented</i>	1	\$ 500.00	\$ 500.00
4	REAR BUMPER CLIP (SET) <i>new</i>	1	\$ 40.00	\$ 40.00
5	REAR DOOR TRIM BOARD CLIP (SET) <i>new</i>	1	\$ 30.00	\$ 30.00
6	REAR FENDER <i>Rocker Panel</i> SEALANT RH <i>NEC</i>	1	\$ 100.00	\$ 100.00
7	REAR FENDER COWLING CLIP (SET) <i>new</i>	1	\$ 30.00	\$ 30.00

TO : EQ MOTOR CLAIMS DEPTS
 VEHICLE NO : SKC1360H
 MODEL : HYUNDAI ELANTRA
 DATE OF ACCIDENT : 17.04.2022
 TIME OF ACCIDENT : 17:15HRS

8	REAR WINDSCREEN GLASS SEALANT	1	\$ 80.00	\$ 80.00
9	REAR WINDSCREE GLASS INNER SHIELD	1	\$ 60.00	\$ 60.00
10	REAR WHEEL RIM RH	1	\$ 550.00	\$ 550.00

980

TOTAL \$ 1,490.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	TO PANEL BEAT, WELD ,CUT, ADJUST, KNOCK	\$ 1,000.00	850
2	TO SPRAY PAINT	\$ 1,000.00	850
3	TUFF COAT	\$ 100.00	80
4	WIRING, BULB CHECKING	\$ 80.00	30
5	REMOVE & REFIX CUSHION SEAT/UPHOLSTERY & ROOF LINING TO FACILITATE REPAIR	\$ 150.00	80
6	REMOVE & REFIX REAR WINDSCREEN	\$ 120.00	x
7	TRANFER FRONT DOOR MECHANISM	\$ 60.00	✓
8	TRANFER REAR DOOR MECHANISM	\$ 60.00	✓
9	FOUR WHEEL ALIGNMNET	\$ 100.00	80
10	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	x

TOTAL \$ 2,850.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 7,120.25
 TOTAL LABOUR COST : \$ 2,850.00
 TOTAL REPAIR COST : \$ 9,970.25 10,345.60

Admin G
 h/s 19/04/22
 06 Days.

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS. EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.

PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR

IRENE

HP : 8297 9787

- To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total:

2/s: 6910.80

h/s: 5.5K

5.5K