

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22003587/KVY3N2**Date:** 28/04/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00110672100
Claimant Vehicle No :	EY8688Y	Insured Vehicle No :	SLP6380L
Date of Loss:	04/04/2022	Nature of Claim:	TP
		Claim No:	SNM22D202407/C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	EY8688Y	Engine No:	HIDDEN
Make & Model:	TESLA MODEL 3 STANDARD RANGE, (A)	Chassis No:	LRW3F7FA3MC384720
Reg. Date:	11/11/2021 (Man. Year: 2021)	Odometer:	7200 km
Colour:	Metallic Pearl White		
Engine Capacity:	0 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/45ZR18	Rear Tyre Size:	235/45ZR18
Front Left Side:	Michelin 9 mm	Rear Left Side:	Michelin 9 mm
Front Right Side:	Michelin 9 mm	Rear Right Side:	Michelin 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,215.51	883.18	332.33	27.34
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,390.00	495.00	895.00	64.39
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	2,605.51	1,378.18	1,227.33	47.11
+ GST 7.00/7.00% (\$\$)	182.39	96.47	85.92	47.11
Nett Amount (\$\$)	2,787.90	1,474.65	1,313.25	47.11

INSPECTION

Date of Assignment:	19/04/2022	Optima Werkz Pte Ltd (HQ)
Date Inspected:	18/04/2022 Inspected At:	10 Ang Mo Kio Industrial Park 2A, #01-05 AMK Autopoint
Estimated Period of Repair:	2.0 days	Singapore 568047

Adjuster: KENNETH KONG**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 28 Apr 2022)

Parts: 143 TESLA MODEL 3 STANDARD RANGE (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for EY8688Y)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Buckled/Cut	663.55 FL	*663.55 FL
2	2		*REAR BUMPER REVERSE SENSOR	Shorted	317.76 FL	*317.76 FL
3	2		*REAR BUMPER REVERSE SENSOR BRACKET	Serviceable	9.34 FL	*- FL
4	1		*REAR BUMPER REINFORCEMENT	Repair	271.03 FL	*- FL
5	1		*REAR BOOTLID (NPA)	Repair	0.00 FL	*- FL
6	1		*REAR BUMPER CLIPS	Not Necessary	80.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	1,341.68	981.31
- List Item Discount on L Items 10.00/10.00% (S\$)	126.17	98.13
Total Parts (S\$)	1,215.51	883.18

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES TO REMOVE,REPLACE,REFIX & READJUST REAR ACCIDENT AREAS & ETC	New	500.00	200.00
2	LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT ACCIDENT AREAS & ETC	New	500.00	220.00
3	LABOUR CHARGES TO REMOVE & REPLACE REAR BUMPER REVERSE SENSOR & ETC	New	120.00	60.00
4	TO DIAGNOSIS FAULT CODE & RESET MEMORY	New	150.00	0.00
5	TO CHECK WIRING & ELECTRICAL SYSTEM & ETC	New	120.00	15.00
Gross Labour Cost (\$)			1,390.00	495.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >