

OPTIMA WERKZ SINGAPORE

OPTIMA WERKZ PTE LTD
Co. Reg. No. 201212455W
www.ow.sg

f /OptimaWerkz

● /OptimaWerkz

Date: 14.04.2022
Vehicle No: EY8688Y
Model: TESLA MODEL 3 STANDARD RANGE
Chassis: LRW3F7FA3MC384720
Reg.Year: 2021

Third Party Insurer: CHINA TAIPING
Third Party Veh No: SLP6380L
Date of Accident: 04.04.2022
Estimator: KIT
Surveyor:

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	REAR BUMPER	1		\$663.55
2	REAR BUMPER REVERSE SENSOR	2	\$158.88	\$317.76
3	REAR BUMPER REVERSE SENSOR BRACKET	2	\$4.67	\$9.34
4	REAR BUMPER REINFORCEMENT	1		\$271.03
5	REAR BOOTLID	1		REPAIR
TOTAL				\$1,261.68
LESS 10%				-\$126.17
PARTS TOTAL				\$1,135.51

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	REAR BUMPER CLIPS	1		\$80.00
S/N TOTAL				\$80.00

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX & READJUST REAR ACCIDENT AREAS & ETC.

\$500.00

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT ACCIDENT AREAS & ETC.

\$500.00

LABOUR CHARGES TO REMOVE & REPLACE REAR BUMPER REVERSE SENSOR & ETC.

\$120.00

TO DIAGNOSIS FAULT CODE & RESET MEMORY.

\$150.00

TO CHECK WIRING & ELECTRICAL SYSTEM & ETC.

\$120.00

LABOUR TOTAL \$1,390.00

TOTAL \$2,605.51

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:

Head office
6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch
9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9910 | Fax: (+65) 6481 1093

Branch (Motor Insurance Claims)
Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1622 | Fax: (+65) 6481 1011

