

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG22003591/ENCE2

Date: 02/09/2022

REFERENCE

Insured/Claimant: SETHURAMAN ALAGAPPAN

Policy No:

Date of Loss: 14/04/2022

Nature of Claim: OD Claim No: 2892935223SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJD9032J**

Make & Model: AUDI A4, 1.8 TFSI MU Attraction (A)

Engine No: CJE111684

Reg. Date: 25/11/2015 (Man. Year: 2015)

Chassis No: WAUZZZ8K0FA173783

Colour: Grey

Odometer: 110614 km

Engine Capacity: 1798 cc

Market Value/New Car Price: S\$63,000.00

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/40 R18

Rear Tyre Size: 245/40 R18

Front Left Side: Goodyear 4 mm

Rear Left Side: Goodyear 4 mm

Front Right Side: Goodyear 4 mm

Rear Right Side: Goodyear 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	28,120.00	9,664.92	18,455.08	65.63
Miscellaneous Items	0.00	0.00	0.00	
Labour	19,122.00	7,992.00	11,130.00	58.21
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	47,242.00	17,656.92	29,585.08	62.62
- Excess (S\$)	800.00	800.00	0.00	0.00
(S\$)	46,442.00	16,856.92	29,585.08	63.70
+ GST 7.00/7.00% (S\$)	3,250.94	1,179.98	2,070.96	63.70
Nett Amount (S\$)	49,692.94	18,036.90	31,656.04	63.70

INSPECTION

Date of Assignment: 19/04/2022

Date Inspected: 19/04/2022 Inspected At:

24 Benoi Sector Singapore 629857

Repairer: Premium Automobiles Pte Ltd

Estimated Period of Repair: 12.0 days

Adjuster: CHEN TSUE YEE

Manager: HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SECTION PART RH	Dented	2,273.00 FS	*1,818.40 FS
2	1		*SILL TRIM STRIP FRONT RH	Necessary	153.00 FS	*122.40 FS
3	1		*DATA TAG-SILVER	Not Necessary	515.00 FS	*- FS
4	1		*FRONT FENDER RH	Dented	1,111.00 FS	*888.80 FS
5	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	60.00 FS	*- FS
6	1		*FRONT FENDER CLOSING ELEMENT RH	Crushed	143.00 FS	*114.00 FS
7	1		*WHEEL HOUSING LINER	Crushed	260.00 FS	*208.00 FS
8	1		*STONE CHIP GUARD	Cut	82.00 FS	*64.88 FS
9	1		*ADHESIVE TAPE	Necessary (1 PCS ONLY)	59.00 FS	*47.20 FS
10	1		*FRONT DOOR RH	Dented	4,175.00 FS	*3,340.00 FS
11	1		*FRONT DOOR OUTER SEAL RH	Necessary	229.00 FS	*182.80 FS
12	1		*BONDING AGENT	Necessary	51.00 FS	*40.48 FS
13	1		*CLEANING SOLUTION	Necessary	74.00 FS	*58.80 FS
14	1		*APPLICATOR	Not Necessary	8.00 FS	*- FS
15	1		*FRONT DOOR CATCH	Not Necessary	134.00 FS	*- FS
16	1		*FRONT DOOR HINGE UPPER /LOWER RH	Bent	167.00 FS	*133.60 FS
17	1		*DATA PLATE FOR TYRE PRESSURE	Necessary	34.00 FS	*26.96 FS
18	1		*ALUMINIUM RIM	Bent	1,420.00 FS	*1,136.00 FS
19	4		*RUBBER VALVE	Necessary	15.00 FS	*11.84 FS
20	1		*SUPPORT FRAME	Not Necessary	4,322.00 FS	*- FS
21	1		*FRONT WISHBONE FRONT RH	Not Necessary	605.00 FS	*- FS
22	1		*SUSPENSION GUIDE	Not Necessary	1,120.00 FS	*- FS
23	2		*SUSPENSION GUIDE UPPER /LOWER	Not Necessary	1,210.00 FS	*- FS
24	1		*WHEEL BEARING HOUSING	Not Necessary	1,256.00 FS	*- FS
25	1		*SWIVEL JOINT	Not Necessary	214.00 FS	*- FS
26	1		*WHEEL HUB	Not Necessary	518.00 FS	*- FS
27	1		*WHEEL BEARING ASSEMBLY	Not Necessary	651.00 FS	*- FS
28	2		*COUPLING ROD	Not Necessary	258.00 FS	*- FS
29	1		*DRIVE SHAFT	Not Necessary	2,999.00 FS	*- FS
30	1		*SUSPENSION FORKS RH	Not Necessary	263.00 FS	*- FS
31	1		*GAS SHOCK ABSORBER	Not Necessary	337.00 FS	*- FS
32	1		*TRAVK ROD	Not Necessary	109.00 FS	*- FS
33	1		*TIE ROD END	Not Necessary	195.00 FS	*- FS
34	1		*UNDERBODY TRIM FRONT RH	Not Necessary	51.00 FS	*- FS
35	1		*UNDERBODY TRIM RH	Broken	493.00 FS	*394.00 FS
36	1		*NOISE INSULATION FRONT	Not Necessary	709.00 FS	*- FS
37	1		*NOISE INSULATION REAR	Not Necessary	437.00 FS	*- FS
38	1		*FRONT TYRE RHS (50%)	Torn	350.00 FS	*175.00 FS
39	1		*ACYRLIC SEALANT	Necessary	180.00 FS	*180.00 FS
40	1		*CAVITY WAX	Necessary	140.00 FS	*140.00 FS
41	1		*STONE CHIP	Necessary	180.00 FS	*180.00 FS
42	1		*METAL FILLER POWDER	Necessary	280.00 FS	*280.00 FS
43	1		*SUNDRIES	Necessary	280.00 FS	*121.76 FS

F=Franchise part. S=SpcNett.

Total Parts (\$) **28,120.00** **9,664.92**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE ,CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS HORNS ,OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	0.00
2	TO REMOVE AND TRANSFER RHS FRONT DOORS MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES INSPECT FOR DAMAGES	New	350.00	280.00
3	TO REMOVE AND REINSTALL FRONT SEAT ASSY ,BACK REST ,AB PILLAR TRIMS ,SILL TRIMS CARPETS ELECTRONIC COMPONENTS AND FUSE TRAYS	New	1,800.00	1,800.00
4	TO REMOVE CENTER CONSOLE AND DASHBOARD ASSY FOR A-PILLAR RENEWAL INSPECT FRO DAMAGES	New	3,200.00	0.00
5	TO REMOVE AND RENEW RHS FRONT WHEEL SUSPENSION ASSY WITH SUBFRAME	New	2,400.00	0.00
6	TO DISMANTLE AND REINSTALL FRONT BUMPER .TO RENEW RHS FRONT FENDER AND RHS FRONT DOOR .TO CUT OUT AND WELD RHS A-PILLAR WITH RHS SILL PANEL .RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	6,300.00	3,000.00
7	TO RESPRAY RHS FRONT FENDER ,RHS FRONT DOOR ,HINGES ,RHS A-PILLAR ,RHS SILL PANEL AND DOOR ENTRANCE	New	4,000.00	2,200.00
8	TO RENEW RHS FRONT RIM WITH TYRE ,TO CARRY OUT PRE/POST WHEEL ALIGNMENT	New	520.00	520.00
9	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
			Gross Labour Cost (\$)	19,122.00
				7,992.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >