



Case Details

Case Reference Number :

TAX/04/22/2048

Company Type : Strides Taxi Pte Ltd

Insurance Company Name : India International Insurance Pte Ltd

Type of Repair : Accident Repair

Estimation ID : EST-18028-ID

Accident Date and Time : 17/04/2022 06:00 AM

Vehicle Registration Number : SHB1102C

Assigned By : Taxi Claims Manager Team

Vehicle Age(In Months) : -

Documents / Photographs

View Documents / Photographs

Total Documents: 0

Estimation Details

Spare Part's Cost Detail

BOM Type	Costing Type	Portion	Material Number	SMRT Recommendation							Surveyor Approval			
				Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
Standard	Main			COVER, RR BUMPER ASSY	1	423.90	423.90	25.00	317.92	Replace	1	0	Repair	R
Standard	Main			REAR BUMPER REINFORCEMENT	1	318.80	318.80	25.00	239.10	Replace	0	0	Not Give	Xan
Standard	Main			PAD, RR BUMPER, RH & LH, 1	2	3.80	7.60	25.00	5.70	Replace	0	0	Not Give	Xan
Standard	Main			PAD, RR BUMPER, RH & LH, 2	2	3.80	7.60	25.00	5.70	Replace	0	0	Not Give	Xan
Standard	Main			PAD, RR BUMPER, RH & LH, 3	2	3.80	7.60	25.00	5.70	Replace	0	0	Not Give	Xan
Standard	Main			PAD, RR BUMPER, CTR	3	2.20	6.60	25.00	4.95	Replace	3	4.95	Replace	Rec
Standard	Main			SEAL, RR BUMPER ARM, RH & LH	2	11.00	22.00	25.00	16.50	Replace	0	0	Not Give	Xan
Standard	Main			STOPPER, RR BUMPER, RH & LH	2	4.30	8.60	25.00	6.45	Replace	0	0	Not Give	Xan
Standard	Main			RETAINER, RR BUMPER, RH	1	112.70	112.70	25.00	84.53	Replace	0	0	Not Give	Xan
Standard	Main			RETAINER, RR BUMPER, LH	1	111.50	111.50	25.00	83.63	Replace	0	0	Not Give	Xan
Standard	Main			SEAL, RR BUMPER, RH	1	85.20	85.20	25.00	63.90	Replace	0	0	Not Give	Xan
Standard	Main			SEAL, RR BUMPER, LH	1	85.20	85.20	25.00	63.90	Replace	0	0	Not Give	Xan
Standard	Main			CLIPS PIECE, FRT & RR BUMPER	10	1.50	15.00	25.00	11.25	Replace	0	0	Not Give	Xan

Total Spare Part Cost 2,515.48

Surveyor Total 423.67

Lump Sum Discount (%) 20.00

Lump Sum Dis (%) 20

Final Spare Part Cost 1,634.50

Final Sur Total 338.94

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
Standard	Main			GUARD, RR BUMPER, LOWER	1	558.30	558.30	25.00	418.72	Replace	1	418.72	Replace	su
Standard	Main			COVER, GUARD RR BUMPER LOWER	1	14.80	14.80	25.00	11.10	Replace	0	0	Not Give	X11
Standard	Main			SENSOR REVERSE	1	180.00	180.00	0.00	180.00	Replace	0	0	Not Give	X11
Standard	Main			ANTENNA, ELECTRICAL KEY	1	60.30	60.30	10.00	54.27	Replace	0	0	Not Give	X11
Standard	Main			COVER, REAR FLOOR UNDER, RH	1	169.50	169.50	25.00	127.13	Replace	0	0	Not Give	X11
Standard	Main			COVER, REAR FLOOR UNDER, LH	1	234.30	234.30	25.00	175.73	Replace	0	0	Not Give	X11
Standard	Main			COVER, REAR FLOOR UNDER CENTER	1	222.60	222.60	25.00	166.95	Replace	0	0	Not Give	X11
Standard	Main			END PANEL SUB-ASSY, BODY LOWER BACK	1	629.80	629.80	25.00	472.35	Replace	0	0	Not Give	X11
Total Spare Part Cost									2,515.48		Surveyor Total		423.67	
Lump Sum Discount (%)									20.00		Lump Sum Dis (%)		20	
Final Spare Part Cost									1,634.50		Final Sur Total		338.94	

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR REAR PORTION	676.00	200	
Total:			676.00	200.00	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO RESPRAY REAR BUMPER	378.00	200	
2	Main	TO RESPRAY BUMPER BEAM	180.00	0	X11
3	Main	TO RESPRAY REAR PANEL	180.00	0	X11
Total:			738.00	200.00	

Other Cost Detail


S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
Total:			380.00	0.00	

19/04/2022, 15:52

https://vacswb.smrt.com.sg/estimation.aspx

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO WASH AND VACUUM	60.00	0 X11	
2	Main	TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	0 X11	
3	Main	TO REPLACE SUNDRY PARTS	100.00	0 X11	
4	Main	TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	0 X11	
Total:			380.00	0.00	

Summary

	Estimator Assessment(\$)	Surveyor Assessment(\$)
Total Spare Part Detail	1,634.50	338.94
Total Labour Cost	676.00	200.00
Total Spray Painting	738.00	200.00
Other	380.00	0.00
Overall Total	3,428.50	738.94
Lump Sum Repair Option	☐	☒
Lump Sum Total	3,450.00	750.00
Surveyor Approved Amount		750.00
No of Repair Days*	4	2
Remarks	-	LUMP SUM REPAIR / AFTER PAINT PHOTO
Surveyor Name		Rasul
Signature		
		Save Clear

LKK Auto Consultants hence notify the Repairer of the following:

To resurvey before/after spray painting

- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

19/04/2022

20.00 F

Transportation

insp (\$: Interview