

# Trust Autoworks

Mailing address: Blk 225 #07-579 Ang Mo Kio Ave 1 Singapore 660226  
Tel: 91082728

Ng Teck Koon  
Blk 418A Northshore Dr  
#19-605  
Singapore 821419

Vehicle No: SMW 2941 X  
Make/Model: Honda Shuttle  
Year: 2019

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Not Authorised  
L1 Pmp \$5650  
Returning After 7 days

Qty	Description	Unit Price	Amount
-----	-------------	------------	--------

## Estimate Cost Of Repair

pc	Rear tail-gate assy	1254.80	
pc	Rear tail-gate glass moulding		\$1,350.60
pc	Rear tail-gate emblem " Shuttle "		\$105.20
pc	Rear tail-gate outer chrome garnish		\$65.10
pc	Rear tail-gate inner lock		\$385.70
pc	Rear tail-gate inner trim board	photo	\$305.10
pc	Rear tail-gate pocket	crack photo	\$287.40
pcs	Rear tail-gate reflector		\$45.10
pcs	Rear tail- lamp		\$840.20
pc	Rear boot rubber		\$975.80
pc	Rear end panel	photo 638.10	\$195.70
pc	Rear end panel inner garnish	photo	\$685.70
pc	Rear end panel lower cover		\$185.90
pc	Rear bumper		\$87.10
pc	Rear bumper chrome moulding		\$965.70
pc	Rear bumper tow cover		\$225.10
pcs	Rear bumper side retainer		\$48.20
pcs	Rear bumper reflector		\$76.40
pcs	Rear bumper reflector sponge	photo	\$310.40
pc	Radio antenna		\$164.20
pcs	Rear fender inner trim board	photo 336.20	\$125.60
pc	Rear spare tyre panel	photo 1072.5	\$970.40
pc	Rear spare tool console box	photo	\$1,072.50
pc	Rear boot top cover board		\$205.60
pc	Rear exhaust silencer		\$297.10
			\$855.10
			\$10,830.90
			Less 20 %
			balance c/f
			\$8,664.72



SMP 7601 G

S Nett

1 pc Rear reverse sensor  
1 pc Rear reverse camera  
1 pc Rear tail-gate glass sealant  
20 pcs Rear bumper clip  
1 pc Rear no plate

balance b/f \$8,599.52

*in* \$200.00 X  
*in* \$300.00 X  
*in* \$55.00 *4000*  
*in* \$40.00  
*in* \$40.00 X  
\$635.00

Labour Charges

Remove/renew the above parts including knocking, welding & cutting.

\$1,200.00 *10000*

To putty and spray paint

\$1,200.00 *8000*

Check & reconnect wiring.

\$45.00 *200*

To respray anti-rust proofing treatment

\$120.00 *800*

Remove/refit rear windscreen to facilitate repair

\$120.00 *✓*

Remove/refit rear tail-gate mechanism to new door.

\$150.00 *600*

Remove/refit rear boot upholstery to facilitate repair.

\$100.00 *600*

Remove/renew rear exhaust silencer

*in* \$120.00 X  
Total \$12,289.52

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: