

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/300/2022/NK
DATE : 18-Apr-22
WIP : 19861

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.

AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120
Attn: Motor Claims Dept
Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR CHAN OI LAI
ADDRESS : BLK 762, BEDOK RESERVOIR VIEW
#09-297
SINGAPORE 470762
TELEPHONE : HP +65 91194114
TYPE OF CLAIM : OWN DAMAGE CLAIM.
POLICY NO : 2100374667-07
VEHICLE NO : SGB 3121 X
MODEL CODE : AUDI A3 SB 1.4 TF
MODEL YEAR : 28/5/2014
ENGINE NO : CXS 068159
CHASSIS NO : WAUZZZ8VXE124809
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 13-Apr-22
PLACE OF ACCIDENT : PIE TOWARDS CHANGI BEFORE TOA PAYOH EXIT

LKK Auto Cons

the Rep

•

• "on a 'no-fault' basis"

• "Supplementary item(s) must be resurveyed and

is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SGB 3121 X (FRONT)

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE,CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS,HORNS,OUTSIDE TEMPERATURE SENSOR,HEADLIGHT WASHER ASSY.	S/N \$ 360.00	X
2	TO REMOVE AND TRANSFER BOTH HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 700.00	500
3	TO REMOVE AND RENEW AIR CON CONDENSER, ADDITIONAL RADIATOR AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. TO CARRY OUT PRESSURISE, VACUUM AND REGAS.	S/N \$ 1,400.00	?
4	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET AND BOTH HEADLIGHT. TO REPAIR BOTH FRONT FENDER. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. REORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 4,900.00	1250
5	TO RESPRAY FRONT BUMPER, BONNET AND BOTH FRONT FENDERS.	\$ 3,500.00	2200
FRONT TOTAL LABOUR CHARGES		: \$ 10,860.00	

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SGB 3121 X (REAR)

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID.	S/N \$ 280.00 /	
2	TO REMOVE AND TRANSFER REAR LID'S CONVENIENCE LOCK SYSTEM AND WIRE HARNESS FOR TAIL LIGHTS AND REAR LID WIPER ASSY.	S/N \$ 480.00 /	
3	TO RENEW REAR WINDSCREEN TO FACILITATE RENEWAL OF REAR LID.	S/N \$ 480.00 /	
4	TO CARRY OUT WATER SEEPAGE FOR REAR WINDSCREEN.	S/N \$ 200.00 /50	
5	TO INSTALL SOLAR FILM FOR REAR WINDSCREEN	S/N \$ 400.00 /	
6	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT. INSPECT FOR DAMAGES AND RENEW WHERE NECESSARY.	S/N \$ 1,400.00 /	(photo)
SUB - REAR TOTAL LABOUR CHARGES		: \$ 3,240.00	

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SGB 3121 X (REAR)

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
7	TO REMOVE AND REINSTALL FUEL TANK TO FACILITATE RENEWAL OF SPARE WHEEL HOUSING.	S/N \$	600.00	?
8	TO REMOVE AND REINSTALL REAR WHEEL SUSPENSION ASSY.	S/N \$	2,400.00	?
9	TO CARRY OUT FIRST MEASUREMENT TEST ON CAR-O-LINER.	S/N \$	800.00	?
10	TO SET UP VEHICLE ON CAR-O-LINER TO FACILITATE THE REPAIR.	S/N \$	2,400.00	?
11	TO DISMANTLE AND RENEW REAR BUMPER AND REAR LID. TO CUT OUT AND WELD REAR END PANELLING AND SPARE WHEEL HOUSING. REORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	7,700.00	2500
12	TO RESPRAY REAR BUMPER, REAR LID, HINGES, REAR END PANELLING AND SPARE WHEEL HOUSING.	\$	4,000.00	1650
13	TO RENEW REAR AND FRONT EXHAUST SILENCER. TO ALIGN TO POSITION.	S/N \$	480.00	/
14	TO CARRY OUT PRE/ POST DIAGNOSTIC CHECK.	S/N \$	384.00	/
TOTAL LABOUR CHARGES (REAR)		:	\$ 22,004.00	
GRAND TOTAL LABOUR (FRONT + REAR)		:	\$ 32,864.00	

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SGB 3121 X (FRONT)

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER / ON	1	\$	2,146.00
2	FRONT BUMPER FIXING PARTS X	1	\$	195.00
3	FRONT BUMPER CLOSING ELEMENET ?	1	\$	175.00
4	FRONT BUMPER PULL STRAP- LOWER ?	4	\$	231.00
5	FRONT BUMPER GUIDE SECTION - LH / RH X	2	\$	142.00
6	FRONT BUMPER AIR GUIDE GRILLE LH / RH / OR	2	\$	244.00
7	RADIATOR GRILLE / OR	1	\$	765.00
8	RADIATOR GRILLE COVER ?	1	\$	109.00
9	REINFORCEMENT BEAM ?	1	\$	847.00
10	FRONT BUMPER FOAM FILLER PC ?	1	\$	93.00
11	FRONT BUMPER TOP COVER ?	1	\$	63.00
12	SIGNAGE STICKER " CAUTION" ?	1	\$	16.00
13	STICKER FOR "AIR CON" ?	1	\$	9.00
14	SIGNAL HORN - LOW TONE LH ?	1	\$	213.00
15	SIGNAL HORN - HIGH TONE RH ?	1	\$	213.00
16	BONNET / ON	1	\$	3,370.00
17	BONNET ATTACHEMENTS PARTS X	1	\$	172.00
18	BONNET HINGE LH / RH ?	2	\$	136.00
19	BONNET HINGE COVER LH / RH X	2	\$	92.00
20	BONNET EDGE PROTECTION / MC	1	\$	31.00
SUB - FRONT TOTAL SPARE PARTS		:	\$	9,262.00

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SGB 3121 X (FRONT)

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	BONNET CATCH HOOK ?	1	\$ 100.00	
22	BONNET STRIKER LH/ RH ?	2	\$ 246.00	
23	BONNET CATCH HOOK ?	1	\$ 71.00	
24	BONNET LID LOCK SWITCH ?	2	\$ 455.00	
25	BONNET BOWDEN CABLE CENTRE ?	1	\$ 64.00	
26	BONNET BOWDEN CABLE COVER ?	1	\$ 11.00	
27	BONNET LID LOCK CABLE ?	1	\$ 82.00	
28	BONNET GAS FILLED STRUT X	1	\$ 110.00	
29	HEADLIGHT - LH / RH / OK	(2)	\$ 5,620.00	
30	HEADLIGHT LIFT CYLINDER - LH / RH ?	2	\$ 422.00	
31	HEADLIGHT LIFT CYLINDER HOSE ?	1	\$ 204.00	
32	LOCK CARRIER ?	1	\$ 806.00	
33	AC CONDENSER ?	1	\$ 569.00	
34	ADDITIONER RADIATOR ?	1	\$ 959.00	
35	RADIATOR ?	1	\$ 1,061.00	
36	RADIATOR BRACKET ?	2	\$ 90.00	
37	RADIATOR BUSH LOWER ?	2	\$ 22.00	
38	COOLANT READY MIXTURE 1.0L ?	6	\$ 283.00	
39	RADIATOR FAN ?	1	\$ 1,464.00	
40	RADIATOR AIR GUIDE LH / RH ?	2	\$ 56.00	
SUB - FRONT TOTAL SPARE PARTS		:	\$ 16,647.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SGB 3121 X (FRONT)

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
41	RADIATOR SEAL OUTER RH ?	1	\$ 9.00	
42	RADIATOR AIR GUIDE UPPER CENTRE ?	1	\$ 14.00	
43	RADIATOR BRACKET ?	1	\$ 21.00	
44	WHEEL HOUSING LINER LH / RH X	2	\$ 366.00	
45	MULTI-SWITCH SIDE LIGHTS (BLACK) - OK	1	\$ 592.00	
FRONT TOTAL SPARE PARTS		:	\$ 26,911.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES




55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SGB 3121 X (REAR)

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	REAR BUMPER <i>BR</i>	1	\$	2,201.00
2	REAR BUMPER FIXING SETS <i>?</i>	1	\$	201.00
3	REAR BUMPER LOCKING MECHANISM <i>LH / RH</i> <i>BR</i>	<i>12</i>	\$	32.00
4	REAR BUMPER SPOILER- DOUBLE PIPE <i>BR</i>	1	\$	264.00
5	REAR REINFORCEMENT BEAM <i>?</i>	1	\$	642.00
6	REAR BUMPER BRACKET INNER/ UPPER RH <i>MIS</i>	<i>(2)</i>	\$	30.00
7	REAR BUMPER GUIDE SECTION LH / RH <i>?</i>	2	\$	150.00
8	REAR BUMPER SENSOR INNER / OUTER <i>?</i>	4		TBC
9	REAR BUMPER SENSOR SEAL <i>MC</i>	4	\$	10.00
10	REAR BUMPER WIRING SET <i>?</i>	1	\$	572.00
11	REAR LID <i>BR</i>	1	\$	3,097.00
12	REAR LID PACKING ADHESIVE <i>MC</i>	1	\$	21.00
13	REAR LID ATTACHMENTS PARTS <i>MC</i>	1	\$	308.00
14	REAR LID HINGE <i>?</i>	2		TBC
15	REAR LID SEAL <i>?</i>	1	\$	229.00
16	REAR LID LOCK <i>?</i>	1	\$	190.00
17	REAR LID LOCK COVER <i>?</i>	1	\$	8.00
18	REAR LID PUSH BUTTON <i>?</i>	1	\$	200.00
19	REAR LID LOCK STRIKER <i>?</i>	1	\$	102.00
20	REAR LID CLIPS <i>MC</i>	2	\$	4.00
SUB - REAR TOTAL SPARE PARTS			\$	8,261.00

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SGB 3121 X (REAR)

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
21	REAR WINDSCREEN ✓ <i>nc</i>	1	\$	905.00	
22	REAR WINDSCREEN PRIMER ✓ <i>nc</i>	1	\$	22.00	
23	FOAM STRIPS ✓ <i>nc</i>	1	\$	153.00	
24	REAR SPOILER FIXING PARTS ✓ <i>nc</i>	1	\$	184.00	
25	REAR LIGHT REFLECTOR LH / RH X	2	\$	92.00	
26	LED TAILLIGHT OUTER LH / RH ?	2	\$	1,948.00	
27	LED TAILLIGHT INNER LH / RH X	2	\$	1,948.00	
28	LED LICENCE PLATE LIGHT X	2	\$	128.00	
29	REAR CROSS PANEL ✓ <i>oo</i>	1	\$	258.00	
30	REAR CROSS PANEL REINFORCEMENT BEAM ✓ <i>oo</i>	1	\$ <i>(phr)</i>	1,037.00	
31	REAR CROSS PANEL CONNECTING PLATE LH / RH ✓ <i>nc</i>	2	\$	92.00	
32	BOOT FLOOR PLATE ?	1	\$	1,982.00	
33	BOOT FLOOR CROSS MEMBER REAR ?	1	\$	233.00	
34	REAR CROSS PANEL COVER <i>WV CRU</i> ?	1	\$	171.00	
35	REAR LUGGAGE COMPARTMENT FLOOR ?	1	\$	786.00	
36	REAR CROSS PANEL PLASTIC TRAY ? <i>CRU</i>	1	\$	319.00	
37	REAR SILENCER ✓ <i>oo</i>	1	\$	776.00	
38	REAR SILENCER DUAL CLIP ✓ <i>nc</i>	1	\$	65.00	
39	FRONT SILENCER ?	1	\$	530.00	
40	FRONT SILENCER DUAL CLIP ?	1	\$	66.00	
SUB - REAR TOTAL SPARE PARTS		:	\$	11,695.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
TEL: 6366 2323 FAX: 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SGB 3121 X (REAR)

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
41	EXHAUST SYSTEM RETAINER / NC	1	\$	94.00
42	CHROME EXHAUST TAIL PIPE - LH / CUT	1		TBC
43	REAR SILENCER HEAT SHIELD / DO	1	\$	180.00
44	ACYRLIC SEALER / NC	S/N	\$	180.00
45	CAVITY WAX - NC	S/N	\$	140.00
46	STONE CHIP - NC	S/N	\$	180.00
47	METAL FILLER POWDER - NC	S/N	\$	280.00
48	REAR WINDSCREEN SEALANT / NC	S/N	\$	200.00
49	FRONT NO PLATE / BT	S/N	\$	60.00
50	REAR NO PLATE - CUT	S/N	\$	60.00
51	SUNDRIES 2	1	\$	600.00
TOTAL SPARE PARTS (REAR)			:	\$ 21,930.00
TOTAL SPARE PARTS (FRONT)			:	\$ 26,911.00
TOTAL LABOUR CHARGES (FRONT + REAR)			:	\$ 32,864.00
GRAND TOTAL			:	\$ 81,705.00

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME
SURVEYED DATE
AUTHORISED DATE
EXCESS COST
LIABILITY
REMARKS

:
:
:
:
:
:

Steve (LKK)
19/4/22, 10:22a

OP - M M
EXP. 1-?
PIP
M R Y
14 41

PLEASE NOTE

:

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE
AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER
LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF
REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO
MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR
APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT