



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0305/2022/JT
DATE : 19-Apr-22
WIP : 20461

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE SURVEY 19/4/22

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR WAYNE ALEXANDER PALMER
ADDRESS : 257 HOLLAND ROAD
SINGAPORE 278606
TELEPHONE : HP +65 97468460
TYPE OF CLAIM : OWN DAMAGED CLAIM
POLICY NO : 1900003623-03
VEHICLE NO : SMH 2536 L
MODEL CODE : AUDI Q7 2.0 TFSI QU
MODEL YEAR : 17/1/2019
ENGINE NO : CYR 077756
CHASSIS NO : WAUZZZ4MXKD009618
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 16-Apr-22
PLACE OF ACCIDENT : U-TURN OF HOLLAND ROAD (OPPOSITE
TAN BOON CHONG AVE)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMH 2536 L

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR. S/N S	360.00 /	
2	TO REMOVE AND TRANSFER REAR LID'S CONVENIENCE LOCK SYSTEM, WIRE HARNESS FOR TAIL LIGHTS AND REAR LID WIPER ASSY. S/N S	480.00 /	
3	TO RENEW REAR WINDSCREEN TO FACILITATE RENEWAL OF REAR LID. S/N S	480.00 /	
4	TO CARRY OUT WATER SEEPAGE FOR REAR WINDSCREEN. S/N S	200.00 <i>150</i>	
5	TO INSTALL SOLAR FILM FOR REAR WINDSCREEN AND 1/4 GLASS. S/N S	400.00 /	
6	TO RENEW LHS 1/4 GLASS TO FACILITATE RENEWAL OF LHS REAR FENDER. S/N S	300.00 /	
7	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT. INSPECT FOR DAMAGE AND RENEW WHERE NECESSARY. S/N S	1,800.00 /	<i>(phs)</i>
SUB TOTAL LABOUR CHARGES		: \$ 4,020.00	

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMH 2536 L

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
8	TO REMOVE AND REINSTALL REAR SEAT, BACK REST, HAT TRAY, ABCD PILLAR TRIMS, LUGGAGE COMPARTMENT TRIMS. DISLODGE ROOF LINER AND DISENGAGE CURTAIN AIRBAG ETC.	S/N \$ 1,800.00	✓ (photo)
9	TO SETUP AND PLACE THE VEHICLE IN ALUMINIUM BAY.	S/N \$ 1,800.00	✓ (photo)
10	TO DISMANTLE AND RENEW REAR BUMPER AND REAR LID. TO CUT OUT AND WELD LHS REAR FENDER AND REAR END PANELLING. TO REPAIR RHS REAR FENDER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	S 10,000.00 10 x 600	4200 6000
11	TO RESPRAY REAR BUMPER, REAR LID, HINGES, LHS REAR FENDER, LHS SILL PANEL, DOOR ENTRANCE, DRAIN CHANNEL, ROOF CHANNEL, REAR END PANELLING AND RHS REAR FENDER.	6.5 S 8,000.00 5.5 x 600	3700 3900
12	TO CARRY OUT ALUMINIUM PRIMER WORKS.	S/N \$ 900.00	✓
13	TO RENEW BOTH REAR EXHAUST SILENCER WITH CENTER EXHAUST SILENCER. TO ALIGN TO POSTION.	S/N \$ 480.00	! 280 ✓
14	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 27,192.00	

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMH 2536 L

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
1	REAR BUMPER - UPPER / <i>OK</i>	1	\$	1,451.00	✓ 1160.8
2	REAR BUMPER / <i>CR4</i>	1	\$	1,914.00	✓ 1531.20
3	REAR BUMPER FIXING PARTS ? <i>X NN</i>	1	\$	217.00	
4	REAR BUMPER SPOILER / <i>CR4</i>	1	\$	1,407.00	✓ 1125.60
5	REAR BUMPER SPOILER - LOWER <i>X NN</i>	1	\$	119.00	
6	BOOT LID CONTROL UNIT <i>X NN</i>	1	\$	428.00	
7	TAILGATE SENSOR LINE ? <i>X NN</i>	1	\$	228.00	
8	REAR BUMPER REINFORCEMENT BEAM ? <i>X NN</i>	1	\$	1,506.00	
9	REAR BUMPER HOLDING STRAP ? <i>X NN</i>	1	\$	206.00	
10	REAR BUMPER GUIDE SECTION - CENTER ? <i>X NN</i>	1	\$ BR	159.00	126.80
11	REAR BUMPER GUIDE SECTION - LH / RH ? <i>X NN</i>	2	\$ BR	142.00	56.48
12	REAR PARKING AID SENSOR - INNER / OUTER ? <i>X NN</i>	3		TBC	
13	REAR PARKING AID SENSOR SEAL RING / <i>OK</i>	4	\$	10.00	X NN
14	REAR LID / <i>OK</i>	1	\$	6,480.00	✓ 5184
15	REAR LID ATTACHMENT PARTS <i>X NN</i>	1	\$	359.00	
16	REAR LID HINGE - LH / RH <i>X NN</i>	2	\$	342.00	
17	REAR LID FLAP GASKET <i>X NN</i>	1	\$	325.00	
18	REAR LID LOCK ACTUATOR <i>X NN</i>	1	\$	1,478.00	
19	REAR LID LOCK <i>X NN</i>	1	\$	300.00	
20	REAR LID LOCK FLAP COVER CAP <i>X NN</i>	1	\$	13.00	
SUB TOTAL SPARE PARTS		:	\$	17,084.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMH 2536 L

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	REAR LID LOCK STRIKER X NN	1	\$ 96.00	
22	REAR PACKING ADHESIVE / NC	1	\$ 21.00	16.72
23	AUDI EMBLEM / NC	1	\$ 144.00	114.80
24	"Q7" EMBLEM / NC	1	\$ 104.00	82.80
25	REAR WINDSCREEN / NC	1	\$ 1,307.00	1045.60
26	PRIMER / NC	1	\$ 22.00	17.36
27	REAR SPOILER - LH / RH / NC	2	\$ 514.00	410.40
28	REAR SPOILER FOAM STRIPS / NC	1	\$ 153.00	122
29	REAR SPOILER FIXING PARTS / NC	1	\$ 69.00	54.96
30	REAR BUMPER TAIL LIGHT - LH / RH / CY	12	\$ 804.00	371.60
31	LICENCE PLATE LIGHT - LH / RH X NN	2	\$ 209.00	
32	TAIL LIGHT - LH / RH / BR	12	\$ 4,558.00	1813.70
33	REAR FENDER - LH / RD	1	\$ 7,776.00	6220.80
34	QUARTER WINDOW - LH / NC	1	\$ 1,053.00	842.40
35	PRIMER / NC	1	\$ 22.00	17.36
36	REAR END PANEL 2 X NN	1	\$ 668.00	
37	REAR END PANEL REINFORCEMENT ? X NN	1	\$ 1,506.00	
38	REAR END PANEL TRIM 7 X NN	1	\$ 475.00	
39	REAR WHEEL ARCH COVER - LH / RH / NC	2	\$ 414.00	330.40
40	EXHAUST TAIL PIPE TRIM - LH / RH / CY	21	\$ 712.00	28480
SUB TOTAL SPARE PARTS			\$ 20,627.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMH 2536 L

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
41	REAR SILENCER - CENTER ? X nn	1	\$	2,880.00	
42	DUAL CLIP ? X nn	1	\$	68.00	
43	EXHAUST SILENCER BRACKET - LH / RH ? X nn	2	\$	90.00	
44	WIPER ARM X nn	1	\$	107.00	
45	WIPER BLADE — CUT	1	\$	32.00	25.28
46	WIPER CAP X nn	1	\$	20.00	
47	WATER JET X nn	1	\$	36.00	
48	REAR SILL PANEL TRIM STRIP - LH OUTER — nc	1	\$	182.00	145.60
49	REAR WHEEL SPOILER - LH X nn	1	\$	40.00	
50	REAR WHEEL HOUSING LINER - LH — nc	1	\$	347.00	277.60
51	REAR SILENCER HEAT SHIELD ? X nn	1	\$	171.00	
52	STATIC MIXER — nc	1	\$	12.00	97.60
53	2 PACK SPOXY ADHESIVE — nc	1	\$	122.00	49.12
54	ALUMINIUM POWDER — nc	1	\$	637.00	509.60
55	HARDENER — nc	1	\$	232.00	185.60
56	ALUMINIUM PRIMER — LC	1	\$	233.00	186.40
57	CLEANING BLOCK — nc X nn	1	\$	96.00	
58	ARYLIC SEALANT — nc	S/N	\$	180.00	
59	CAVITY WAX — nc	S/N	\$	140.00	
60	STONE CHIP — nc	S/N	\$	180.00	
SUB TOTAL SPARE PARTS			:	\$	5,805.00

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMH 2536 L

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
61	<i>Aluminum</i> METAL FILLER POWDER <i>nc X nn</i>	S/N	\$	280.00	
62	REAR WIDNSCREEN SEALANT <i>nc</i>	S/N	\$	200.00	/
63	1/4 GLASS SEALANT <i>nc</i>	S/N	\$	100.00	/
64	REAR NO PLATE <i>X nn</i>	S/N	\$	60.00	
65	SUNDRIES <i>? / nec</i>		\$	500.00	<i>50-88 /</i>
TOTAL SPARE PARTS		:	\$	44,656.00	
TOTAL LABOUR CHARGES		:	\$	27,192.00	
GRAND TOTAL		:	\$	71,848.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

Stew (LKK)

19/4/22 3.22p

00-M 11L

Excess?

PIP

17 PM 4

18 10 45

PLEASE NOTE :

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT