

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: [NORA.KHAI@PREMIUMAUTO.COM.SG](mailto:NORA.KHAI@PREMIUMAUTO.COM.SG) / [CLAIMS@PREMIUMAUTO.COM.SG](mailto:CLAIMS@PREMIUMAUTO.COM.SG)

**ESTIMATE** : ACCIDENT REPAIRS  
**WORKSHOP** : UBI ROAD 1  
**CONTACT NO** : 6366 2323  
**FAX NO** : 6841 1183  
**REFERENCE** : PA/OD/0305/2022/JT  
**DATE** : 19-Apr-22  
**WIP** : 20461

**VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE SURVEY 19/4/22**

**AIG ASIA PACIFIC INSURANCE PTE LTD**

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

**Tel: 6880 4602 - Fax: 6880 4838**

**Hi Steve**

**18 days exclude 3 Sundays & 2 PH**

**Johnny Boo 16 Nov 22**

**OWNER'S NAME** : MR WAYNE ALEXANDER PALMER  
**ADDRESS** : 257 HOLLAND ROAD  
SINGAPORE 278606  
**TELEPHONE** : HP +65 97468460  
**TYPE OF CLAIM** : OWN DAMAGED CLAIM  
**POLICY NO** : 1900003623-03  
**VEHICLE NO** : **SMH 2536 L**  
**MODEL CODE** : AUDI Q7 2.0 TFSI QU  
**MODEL YEAR** : 17/1/2019  
**ENGINE NO** : CYR 077756  
**CHASSIS NO** : WAUZZZ4MXKD009618  
**MILEAGE** : -  
**DATE IN** : -  
**ESTIMATED BY** : JOHNNY BOO / ALLAN WU  
**ACCIDENT DATE** : 16-Apr-22  
**PLACE OF ACCIDENT** : U-TURN OF HOLLAND ROAD (OPPOSITE  
TAN BOON CHONG AVE)

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: [NORA.KHAI@PREMIUMAUTO.COM.SG](mailto:NORA.KHAI@PREMIUMAUTO.COM.SG) / [CLAIMS@PREMIUMAUTO.COM.SG](mailto:CLAIMS@PREMIUMAUTO.COM.SG)

### **ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMH 2536 L**

| S/N                             | NATURE OF JOBS                                                                                                                                                               |        | ESTIMATED<br>CHARGES | SURVEYOR'S<br>RECOMMENDATIONS |
|---------------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------|----------------------|-------------------------------|
| 1                               | TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR.                                                                                                            | S/N \$ | 360.00               | \$ <b>360.00</b>              |
| 2                               | TO REMOVE AND TRANSFER REAR LID'S CONVENIENCE LOCK SYSTEM, WIRE HARNESS FOR TAIL LIGHTS AND REAR LID WIPER ASSY.                                                             | S/N \$ | 480.00               | \$ <b>480.00</b>              |
| 3                               | TO RENEW REAR WINDSCREEN TO FACILITATE RENEWAL OF REAR LID.                                                                                                                  | S/N \$ | 480.00               | \$ <b>480.00</b>              |
| 4                               | TO CARRY OUT WATER SEEPAGE FOR REAR WINDSCREEN                                                                                                                               | S/N \$ | 200.00               | \$ <b>150.00</b>              |
| 5                               | TO INSTALL SOLAR FILM FOR REAR WINDSCREEN AND 1/4 GLASS.                                                                                                                     | S/N \$ | 400.00               | \$ <b>400.00</b>              |
| 6                               | TO RENEW LHS 1/4 GLASS TO FACILITATE RENEWAL OF LHS REAR FENDER.                                                                                                             | S/N \$ | 300.00               | \$ <b>300.00</b>              |
| 7                               | TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT. INSPECT FOR DAMAGE AND RENEW WHERE NECESSARY. | S/N \$ | 1,800.00             | \$ <b>1,800.00</b>            |
| <b>SUB TOTAL LABOUR CHARGES</b> |                                                                                                                                                                              | :      | <b>\$ 4,020.00</b>   | <b>\$ 3,970.00</b>            |

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: [NORA.KHAI@PREMIUMAUTO.COM.SG](mailto:NORA.KHAI@PREMIUMAUTO.COM.SG) / [CLAIMS@PREMIUMAUTO.COM.SG](mailto:CLAIMS@PREMIUMAUTO.COM.SG)
**ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMH 2536 L**

| S/N                         | NATURE OF JOBS                                                                                                                                                                                                            |            | ESTIMATED<br>CHARGES | SURVEYOR'S<br>RECOMMENDATIONS |
|-----------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------|----------------------|-------------------------------|
|                             |                                                                                                                                                                                                                           | <b>C/F</b> |                      | <b>\$ 3,970.00</b>            |
| 8                           | TO REMOVE AND REINSTALL REAR SEAT, BACK REST,<br>HAT TRAY, ABCD PILLAR TRIMS, LUGGAGE<br>COMPARTMENT TRIMS. DISLODGE ROOF LINER AND<br>DISENGAGE CURTAIN AIRBAG ETC.                                                      | S/N \$     | 1,800.00             | <b>\$ 1,800.00</b>            |
| 9                           | TO SETUP AND PLACE THE VEHICLE IN ALUMINIUM BAY.                                                                                                                                                                          | S/N \$     | 1,800.00             | <b>\$ 1,800.00</b>            |
| 10                          | TO DISMANTLE AND RENEW REAR BUMPER AND REAR<br>LID. TO CUT OUT AND WELD LHS REAR FENDER AND<br>REAR END PANELLING. TO REPAIR RHS REAR FENDER.<br>RE-ORGANIZE CRASH MANAGEMENT COMPONENTS.<br>REINSTALL ALL PARTS REMOVED. | \$         | 10,000.00            | <b>\$ 6,000.00</b>            |
| 11                          | TO RESPRAY REAR BUMPER, REAR LID, HINGES, LHS<br>REAR FENDER, LHS SILL PANEL, DOOR ENTRANCE,<br>DRAIN CHANNEL, ROOF CHANNEL, <b>REAR END<br/>PANELLING</b> AND RHS REAR FENDER.                                           | \$         | 8,000.00             | <b>\$ 3,900.00</b>            |
| 12                          | TO CARRY OUT ALUMINIUM PRIMER WORKS.                                                                                                                                                                                      | S/N \$     | 900.00               | <b>\$ 900.00</b>              |
| 13                          | TO RENEW BOTH REAR EXHAUST SILENCER WITH<br>CENTER EXHAUST SILENCER. TO ALIGN TO POSTION.<br><i>(Repair &amp; align)</i>                                                                                                  | S/N \$     | 480.00               | <b>\$ 280.00</b>              |
| 14                          | <b>Add labour</b>                                                                                                                                                                                                         | \$         | <b>2,700.00</b>      | <b>\$ 900.00</b>              |
| 15                          | TO CARRY OUT DIAGNOSTIC CHECK.                                                                                                                                                                                            | S/N \$     | 192.00               | <b>\$ 192.00</b>              |
| <b>TOTAL LABOUR CHARGES</b> |                                                                                                                                                                                                                           | <b>:</b>   | <b>\$ 29,892.00</b>  | <b>\$ 19,742.00</b>           |

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMH 2536 L**

|                              |                                         |     | DAMAGED PARTS & PRICES |           |                 |
|------------------------------|-----------------------------------------|-----|------------------------|-----------|-----------------|
| S/N                          | PARTS DESCRIPTION                       | QTY | S/NETT                 | REMARKS   |                 |
| 1                            | REAR BUMPER - UPPER                     | 1   | \$ 1,451.00            | \$        | 1,160.80        |
| 2                            | REAR BUMPER                             | 1   | \$ 1,914.00            | \$        | 1,531.20        |
| 3                            | REAR BUMPER FIXING PARTS                | 1   | \$ 217.00              |           |                 |
| 4                            | REAR BUMPER SPOILER                     | 1   | \$ 1,407.00            | \$        | 1,125.60        |
| 5                            | REAR BUMPER SPOILER - LOWER             | 1   | \$ 119.00              |           |                 |
| 6                            | BOOT LID CONTROL UNIT                   | 1   | \$ 428.00              |           |                 |
| 7                            | TAILGATE SENSOR LINE                    | 1   | \$ 228.00              |           |                 |
| 8                            | REAR BUMPER REINFORCEMENT BEAM          | 1   | \$ 1,506.00            |           |                 |
| 9                            | REAR BUMPER HOLDING STRAP               | 1   | \$ 206.00              |           |                 |
| 10                           | REAR BUMPER GUIDE SECTION - CENTER      | 1   | \$ 159.00              | \$        | 126.80          |
| 11                           | REAR BUMPER GUIDE SECTION - LH / RH     | 2   | \$ 142.00              | \$        | 56.48           |
| 12                           | REAR PARKING AID SENSOR - INNER / OUTER | 3   | TBC                    |           |                 |
| 13                           | REAR PARKING AID SENSOR SEAL RING       | 4   | \$ 10.00               |           |                 |
| 14                           | REAR LID                                | 1   | \$ 6,480.00            | \$        | 5,184.00        |
| 15                           | REAR LID ATTACHMENT PARTS               | 1   | \$ 359.00              |           |                 |
| 16                           | REAR LID HINGE - LH / RH                | 2   | \$ 342.00              |           |                 |
| 17                           | REAR LID FLAP GASKET                    | 1   | \$ 325.00              |           |                 |
| 18                           | REAR LID LOCK ACTUATOR                  | 1   | \$ 1,478.00            |           |                 |
| 19                           | REAR LID LOCK                           | 1   | \$ 300.00              |           |                 |
| 20                           | REAR LID LOCK FLAP COVER CAP            | 1   | \$ 13.00               |           |                 |
| <b>SUB TOTAL SPARE PARTS</b> |                                         |     | <b>\$ 17,084.00</b>    | <b>\$</b> | <b>9,184.88</b> |

ALL CHARGES ARE NOT INCLUSIVE OF GST  
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
 SPARE PARTS ARE SPECIAL NETT.

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMH 2536 L**

|                              |                                  |            | DAMAGED PARTS & PRICES |           |                  |
|------------------------------|----------------------------------|------------|------------------------|-----------|------------------|
| S/N                          | PARTS DESCRIPTION                | QTY        | S/NETT                 | REMARKS   |                  |
|                              |                                  | <b>C/F</b> |                        | <b>\$</b> | <b>9,184.88</b>  |
| 21                           | REAR LID LOCK STRIKER            | 1 \$       | 96.00                  |           |                  |
| 22                           | REAR PACKING ADHESIVE            | 1 \$       | 21.00                  | <b>\$</b> | <b>16.72</b>     |
| 23                           | AUDI EMBLEM                      | 1 \$       | 144.00                 | <b>\$</b> | <b>114.80</b>    |
| 24                           | "Q7" EMBLEM                      | 1 \$       | 104.00                 | <b>\$</b> | <b>82.80</b>     |
| 25                           | REAR WINDSCREEN                  | 1 \$       | 1,307.00               | <b>\$</b> | <b>1,045.60</b>  |
| 26                           | PRIMER                           | 1 \$       | 22.00                  | <b>\$</b> | <b>17.36</b>     |
| 27                           | REAR SPOILER - LH / RH           | 2 \$       | 514.00                 | <b>\$</b> | <b>410.40</b>    |
| 28                           | REAR SPOILER FOAM STRIPS         | 1 \$       | 153.00                 | <b>\$</b> | <b>122.00</b>    |
| 29                           | REAR SPOILER FIXING PARTS        | 1 \$       | 69.00                  | <b>\$</b> | <b>54.96</b>     |
| 30                           | REAR BUMPER TAIL LIGHT - LH / RH | 2 \$       | 804.00                 | <b>\$</b> | <b>321.60</b>    |
| 31                           | LICENCE PLATE LIGHT - LH / RH    | 2 \$       | 209.00                 |           |                  |
| 32                           | TAIL LIGHT - LH / RH             | 2 \$       | 4,558.00               | <b>\$</b> | <b>1,823.20</b>  |
| 33                           | REAR FENDER - LH                 | 1 \$       | 7,776.00               | <b>\$</b> | <b>6,220.80</b>  |
| 34                           | QUARTER WINDOW - LH              | 1 \$       | 1,053.00               | <b>\$</b> | <b>842.40</b>    |
| 35                           | PRIMER                           | 1 \$       | 22.00                  | <b>\$</b> | <b>17.36</b>     |
| 36                           | REAR END PANEL                   | 1 \$       | 668.00                 |           |                  |
| 37                           | REAR END PANEL REINFORCEMENT     | 1 \$       | 1,506.00               |           |                  |
| 38                           | REAR END PANEL TRIM              | 1 \$       | 475.00                 |           |                  |
| 39                           | REAR WHEEL ARCH COVER - LH / RH  | 2 \$       | 414.00                 | <b>\$</b> | <b>330.40</b>    |
| 40                           | EXHAUST TAIL PIPE TRIM - LH / RH | 2 \$       | 712.00                 | <b>\$</b> | <b>284.80</b>    |
| <b>SUB TOTAL SPARE PARTS</b> |                                  | <b>:</b>   | <b>\$ 20,627.00</b>    | <b>\$</b> | <b>20,890.08</b> |

ALL CHARGES ARE NOT INCLUSIVE OF GST  
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
 SPARE PARTS ARE SPECIAL NETT.

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMH 2536 L**

|                              |                                       |            | DAMAGED PARTS & PRICES |           |                  |
|------------------------------|---------------------------------------|------------|------------------------|-----------|------------------|
| S/N                          | PARTS DESCRIPTION                     | QTY        | S/NETT                 | REMARKS   |                  |
|                              |                                       | <b>C/F</b> |                        | <b>\$</b> | <b>20,890.08</b> |
| 41                           | REAR SILENCER - CENTER                | 1          | \$ 2,880.00            |           |                  |
| 42                           | DUAL CLIP                             | 1          | \$ 68.00               |           |                  |
| 43                           | EXHAUST SILENCER BRACKET - LH / RH    | 2          | \$ 90.00               |           |                  |
| 44                           | WIPER ARM                             | 1          | \$ 107.00              |           |                  |
| 45                           | WIPER BLADE                           | 1          | \$ 32.00               | \$        | <b>25.28</b>     |
| 46                           | WIPER CAP                             | 1          | \$ 20.00               |           |                  |
| 47                           | WATER JET                             | 1          | \$ 36.00               |           |                  |
| 48                           | REAR SILL PANEL TRIM STRIP - LH OUTER | 1          | \$ 182.00              | \$        | <b>145.60</b>    |
| 49                           | REAR WHEEL SPOILER - LH               | 1          | \$ 40.00               |           |                  |
| 50                           | REAR WHEEL HOUSING LINER - LH         | 1          | \$ 347.00              | \$        | <b>277.60</b>    |
| 51                           | REAR SILENCER HEAT SHIELD             | 1          | \$ 171.00              |           |                  |
| 52                           | STATIC MIXER                          | 1          | \$ 12.00               | \$        | <b>27.60</b>     |
| 53                           | 2 PACK SPOXY ADHESIVE                 | 1          | \$ 122.00              | \$        | <b>49.12</b>     |
| 54                           | ALUMINIUM POWDER                      | 1          | \$ 637.00              | \$        | <b>509.60</b>    |
| 55                           | HARDENER                              | 1          | \$ 232.00              | \$        | <b>185.60</b>    |
| 56                           | ALUMINIUM PRIMER                      | 1          | \$ 233.00              | \$        | <b>186.40</b>    |
| 57                           | CLEANING BLOCK                        | 1          | \$ 96.00               |           |                  |
| 58                           | ARYLIC SEALANT                        | S/N        | \$ 180.00              | \$        | <b>180.00</b>    |
| 59                           | CAVITY WAX                            | S/N        | \$ 140.00              | \$        | <b>140.00</b>    |
| 60                           | STONE CHIP                            | S/N        | \$ 180.00              | \$        | <b>180.00</b>    |
| <b>SUB TOTAL SPARE PARTS</b> |                                       | :          | <b>\$ 5,805.00</b>     | <b>\$</b> | <b>22,796.88</b> |

ALL CHARGES ARE NOT INCLUSIVE OF GST  
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
 SPARE PARTS ARE SPECIAL NETT.

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMH 2536 L**

|                             |                         |            | DAMAGED PARTS & PRICES |           |                  |
|-----------------------------|-------------------------|------------|------------------------|-----------|------------------|
| S/N                         | PARTS DESCRIPTION       | QTY        | S/NETT                 | REMARKS   |                  |
|                             |                         | <b>C/F</b> |                        | <b>\$</b> | <b>22,796.88</b> |
| 61                          | METAL FILLER POWDER     | S/N        | \$ 280.00              | <b>NN</b> |                  |
| 62                          | REAR WIDNSCREEN SEALANT | S/N        | \$ 200.00              | <b>\$</b> | <b>200.00</b>    |
| 63                          | 1/4 GLASS SEALANT       | S/N        | \$ 100.00              | <b>\$</b> | <b>100.00</b>    |
| 64                          | REAR NO PLATE           | S/N        | \$ 60.00               |           |                  |
| 65                          | <b>Add parts</b>        |            | <b>\$ 905.00</b>       | <b>\$</b> | <b>296.00</b>    |
| 66                          | <b>Add parts</b>        |            | <b>\$ 471.00</b>       | <b>\$</b> | <b>376.08</b>    |
| 67                          | SUNDRIES                |            | \$ 500.00              | <b>\$</b> | <b>50.88</b>     |
| <b>TOTAL SPARE PARTS</b>    |                         | :          | <b>\$ 46,032.00</b>    | <b>\$</b> | <b>23,819.84</b> |
| <b>TOTAL LABOUR CHARGES</b> |                         | :          | <b>\$ 29,892.00</b>    | <b>\$</b> | <b>19,742.00</b> |
| <b>GRAND TOTAL</b>          |                         | :          | <b>\$ 75,924.00</b>    | <b>\$</b> | <b>43,561.84</b> |

ALL CHARGES ARE NOT INCLUSIVE OF GST  
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
 SPARE PARTS ARE SPECIAL NETT.  
 BL-29/08/22



## Supplementary Estimate-1

GST Reg No. 19-9902271-W

| <b>AIG Asia Pacific Insurance Pte Ltd</b><br>78 Shenton Way<br>#07-16 AIG Building<br>Singapore 079120<br>Attn: Mr. Adrian Ling - Motor Claims Dept<br><b>Tel: 6841 0055 / Fax: 6256 4315</b> |                          | <b>Estimate No.</b><br><b>Date</b><br><b>Service Advisor</b><br><b>Pages</b><br><b>Regn No</b><br><b>Model No</b> | PA/OD/0305/2022/JT<br>27-Apr-22<br>CHANG<br>1 of 1<br>SMH 2536 L<br>AUDI Q7 2.0 TFSI |     |
|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------|-------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------|-----|
| Quantity                                                                                                                                                                                      | Description              | Unit Price                                                                                                        | Amount                                                                               |     |
| <b><u>Parts</u></b>                                                                                                                                                                           |                          |                                                                                                                   |                                                                                      |     |
| 1                                                                                                                                                                                             | COUNTERSUNK RIVET (4X8)  | \$ 115.00                                                                                                         | \$ <b>92.00</b>                                                                      | NEC |
| 2                                                                                                                                                                                             | COUNTERSUNK RIVET (4X12) | \$ 225.00                                                                                                         | \$ <b>180.00</b>                                                                     | NEC |
| 3                                                                                                                                                                                             | POP RIVET                | \$ 30.00                                                                                                          | \$ <b>24.00</b>                                                                      | NEC |
| 4                                                                                                                                                                                             | 2-PACK EPOXY ADHESIVE    | \$ 122.00                                                                                                         |                                                                                      |     |
| 5                                                                                                                                                                                             | 2 PK FILL FOAM           | \$ 154.00                                                                                                         |                                                                                      |     |
| 6                                                                                                                                                                                             | SOUND ABSORBER           | \$ 259.00                                                                                                         |                                                                                      |     |
|                                                                                                                                                                                               | <b>GRAND TOTAL</b>       | <b>\$ 905.00</b>                                                                                                  | <b>\$ 296.00</b>                                                                     |     |

For Premium Automobiles Pte Ltd

---

Authorized Signature





## Supplementary Estimate-2

GST Reg No. 19-9902271-W

Get Reg No: 15 000277 W

| <b>AIG Asia Pacific Insurance Pte Ltd</b><br>78 Shenton Way<br>#07-16 AIG Building<br>Singapore 079120<br>Attn: Mr. Adrian Ling - Motor Claims Dept<br><b>Tel: 6841 0055 / Fax: 6256 4315</b> | <b>Estimate No.</b><br><b>Date</b><br><b>Service Advisor</b><br><b>Pages</b><br><b>Regn No</b><br><b>Model No</b> | PA/OD/0305/2022/JT<br>9-May-22<br>CHANG<br>1 of 1<br>SMH 2536 L<br>AUDI Q7 2.0 TFSI |                    |
|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|--------------------|
| Quantity                                                                                                                                                                                      | Description                                                                                                       | Unit Price                                                                          | Amount             |
| <b><u>Labours</u></b>                                                                                                                                                                         |                                                                                                                   |                                                                                     |                    |
| 1                                                                                                                                                                                             | TO CUT OUT AND WELD LHS REAR FENDER CONNECTING PLATE.                                                             | \$ 1,800.00                                                                         | \$ 600.00          |
| 2                                                                                                                                                                                             | TO RESPRAY LHS REAR FENDER CONNECTING PLATE.                                                                      | \$ 900.00                                                                           | \$ 300.00          |
|                                                                                                                                                                                               |                                                                                                                   | \$ 2,700.00                                                                         | \$ 900.00          |
| <b><u>Parts</u></b>                                                                                                                                                                           |                                                                                                                   |                                                                                     |                    |
| 1                                                                                                                                                                                             | SEAL FOR SILL PANEL - LH                                                                                          | 1 \$ 282.00                                                                         | \$ 225.20          |
| 2                                                                                                                                                                                             | REAR FENDER VENT TRIM - LH                                                                                        | 1 \$ 80.00                                                                          | \$ 63.92           |
| 3                                                                                                                                                                                             | REAR FENDER CONNECTING PLATE                                                                                      | 1 \$ 109.00                                                                         | \$ 86.96           |
|                                                                                                                                                                                               |                                                                                                                   | Materials \$ 471.00                                                                 | \$ 376.08          |
|                                                                                                                                                                                               |                                                                                                                   | Labour \$ 2,700.00                                                                  | \$ 900.00          |
|                                                                                                                                                                                               | <b>GRAND TOTAL</b>                                                                                                | <b>\$ 3,171.00</b>                                                                  | <b>\$ 1,276.08</b> |

For Premium Automobiles Pte Ltd

---

Authorized Signature

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: [NORA.KHAI@PREMIUMAUTO.COM.SG](mailto:NORA.KHAI@PREMIUMAUTO.COM.SG) / [CLAIMS@PREMIUMAUTO.COM.SG](mailto:CLAIMS@PREMIUMAUTO.COM.SG)

**NAME** :  
**SURVEYED DATE** :  
**AUTHORISED DATE** :  
**EXCESS COST** :  
**LIABILITY** :  
**REMARKS** :

**PLEASE NOTE** : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.  
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,  
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO  
BODY REPAIR MANAGER

ALLAN WU  
CLAIMS CONSULTANT