

55 Ubi Road 1, Singapore 408699
 Tel : 6366 2323 Fax : 6841 1183
 Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Supplementary Estimate-2

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 / Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0305/2022/JT 9-May-22 CHANG 1 of 1 SMH 2536 L AUDI Q7 2.0 TFSI
Quantity	Description	Unit Price	Amount
Labours			
1	TO CUT OUT AND WELD LHS REAR FENDER CONNECTING PLATE.	\$ 1,800.00	600
2	TO RESPRAY LHS REAR FENDER CONNECTING PLATE.	\$ 900.00	300
Parts			
1	SEAL FOR SILL PANEL - LH 1	\$ 282.00	✓ BT 225.20
2	REAR FENDER VENT TRIM - LH 1	\$ 80.00	✓ BR 63.92
3	REAR FENDER CONNECTING PLATE 1	\$ 109.00	✓ BT 86.96
GRAND TOTAL		\$ 3,171.00	

For Premium Automobiles Pte Ltd

Steve (LKK)
 16/11/22



Authorised Signature