

ASS. REC. BY:

REF:

LPC / 22003601/Kc

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SLA 73724 Yr Regn: 03 16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

BMW 520i c.c. 1994

Colour

M. Grey

A/C: Insured / Std / NI / NA

Sp. Reading

50586

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WBA5A 32020D 829210

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rlm / STD A/Rlm or

Tyre Size:

F:

225/55R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

7 mm

R/Bal.

7 mm

L/Bal.

7 mm

L/Bal.

7 mm

D.O.A.

17/4/22

D.O.I.

19/4/2022

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

5/5 11 Lmp @ 480d

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS. SI

Fees

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$

Tropical Tech Automobile Services

Blk 5030, Ang Mo Kio Avenue 3, #01-201, Industrial Park 2, Singapore 569535

Tel : 6481 7773 / 6481 1403 Fax : 6484 4978

E-mail : tasc303@singnet.com.sg

M/s : **Lonpac Insurance Bhd**
300, Beach Road, #17-04 / 07,
The Concourse,
Singapore 199555

Estimate bill : TT 13 / 22 / TP / WT

Attn : Motor Claims Department
6250 7388
Tel : 6296 3767
Fax :

Registration No : SLA7372H

Make model : BMW 520ia (F10)

NOT Authorised
11 Rmp @ 4800/r
Picking After Rain
4 days


Mileage :

Date : 19 / 04 / 2022

**TRAFFIC ACCIDENT INVOLVING VEHICLE BEARING REGISTRATION NO : YP6714D AND SLA7372H
ALONG NEW BRIDGE ROAD (JUNCTION OF NEW BRIDGE ROAD AND PICKERING STREET) ON 17
APRIL 2022 AT ABOUT 0905HRS.**

2sets	Front seat head-rest repair kit	(Each \$419.00)	\$	1m	838.00	X
1pc	Rear boot <i>1550</i>		\$	2m	2,833.00	✓
1pc	Rear boot emblem <i>49</i>		\$	3m	146.00	✓
2pcs	Rear boot emblem grommet	(Each \$14.00)	\$	4m	28.00	✓
1pc	Rear boot '520i' designation <i>68</i>		\$	5m	141.00	✓
2pcs	Rear boot reflector	(Each \$675.00)	\$	6m	1,350.00	X
1pc	Rear boot outer touch button (Camera)		\$	7m	95.00	✓
1pc	Rear boot upper lock		\$	8m	419.00	X
1pc	Rear boot rubber		\$	9m	230.00	<i>500/r</i>
2pcs	Rear tail lamp	(Each \$1079.00)	\$	10m	2,158.00	X
2pcs	Rear tail lamp side garnish	(Each \$1079.00)	\$	11m	2,158.00	X
1pc	Rear end panel		\$	12m	1,349.00	X
1pc	Rear end panel top garnish		\$	13m	311.00	X
1pc	Rear floor panel		\$	14m	2,698.00	X
1pc	Rear floor panel under dust covering (small)		\$	15m	149.00	X
1pc	Rear floor panel under dust covering (Big)		\$	16m	149.00	X
1pc	Rear bumper <i>1495</i>		\$	17m	2,563.00	✓
Sub A total :			\$		17,615.00	
Less 10% discount :			\$		1,761.50	
A total :			\$		15,853.50	
Total amount of Page 1 :			\$		15,853.50	

Tropical Tech Automobile Services


(Authorised Signature)
William Tan

**LKK Auto Consultants hence notify
the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tropical Tech Automobile Services

Blk 5030, Ang Mo Kio Avenue 3, #01-201, Industrial Park 2, Singapore 569535

Tel : 6481 7773 / 6481 1403 Fax : 6484 4978

E-mail : tasc303@singnet.com.sg

./s : **Lonpac Insurance Bhd**
300, Beach Road, #17-04 / 07,
The Concourse,
Singapore 199555

Estimate bill : TT 13 / 22 / TP / WT

Registration No : SLA7372H

Attn : Motor Claims Department
6250 7388
Tel : 6296 3767
Fax :

Make model : BMW 520ia (F10)

Mileage :

Date :

19 / 04 / 2022

**TRAFFIC ACCIDENT INVOLVING VEHICLE BEARING REGISTRATION NO : YP6714D AND SLA7372H
ALONG NEW BRIDGE ROAD (JUNCTION OF NEW BRIDGE ROAD AND PICKERING STREET) ON 17
APRIL 2022 AT ABOUT 0905HRS.**

4pcs	Rear bumper parktronic sensor	<i>C 198</i>	(Each \$419.00)	\$	<i>per</i>	1,676.00	<i>4-198</i>
4pcs	Rear bumper parktronic sensor seal ring		(Each \$14.00)	\$	<i>in</i>	56.00	<i>—</i>
1set	Rear bumper parktronic sensor wire harness			\$	<i>in</i>	243.00	<i>—</i>
1pc	Rear bumper parking sensor module			\$	<i>in</i>	1,066.00	<i>X</i>
1pc	Rear bumper towing cover			\$	<i>in</i>	87.00	<i>—</i>
2pcs	Rear bumper reflector	<i>M 152X</i>	(Each \$87.00)	\$	<i>cl 5 in</i>	174.00	<i>X</i>
2pcs	Rear bumper side bracket		(Each \$365.00)	\$	<i>in</i>	730.00	<i>X</i>
1pc	Rear bumper frame (Top)			\$	<i>CM</i>	176.00	<i>—</i>
1pc	Rear bumper frame (Bottom)			\$	<i>CM</i>	149.00	<i>—</i>
1pc	Rear bumper reinforcement	<i>671.</i>		\$	<i>in</i>	1,025.00	<i>—</i>
Sub A total :				\$		5,382.00	
Less 10% discount :				\$		538.20	
B total :				\$		4,843.80	

Special net items :

1pc	Rear license smart plate		\$	<i>in</i>	35.00	<i>X</i>
1pc	Rear license smart plate casing		\$		35.00	
C total :			\$			

Total amount of Page 2 :

\$ 4,878.80

Tropical Tech Automobile Services


(Authorised Signature)
William Tan

Tropical Tech Automobile Services

Blk 5030, Ang Mo Kio Avenue 3, #01-201, Industrial Park 2, Singapore 569535

Tel : 6481 7773 / 6481 1403 Fax : 6484 4978

E-mail : tasc303@singnet.com.sg

/ s : **Lonpac Insurance Bhd**
300, Beach Road, #17-04 / 07,
The Concourse,
Singapore 199555

Estimate bill : TT 13 / 22 / TP / WT

Registration No : SLA7372H

Attn : Motor Claims Department
6250 7388

Make model : BMW 520ia (F10)

Tel : 6296 3767

Fax :

Mileage :

Date :

19 / 04 / 2022

**TRAFFIC ACCIDENT INVOLVING VEHICLE BEARING REGISTRATION NO : YP6714D AND SLA7372H
ALONG NEW BRIDGE ROAD (JUNCTION OF NEW BRIDGE ROAD AND PICKERING STREET) ON 17
APRIL 2022 AT ABOUT 0905HRS.**

Remove and transfer rear boot necessary attachment spart part items.

Remove and transfer rear bumper necessary attachment spart part items.

Remove and refit front seat head rest repair kit, rear boot, rear boot emblem, rear boot '520i' designation, rear boot reflectors, rear boot outer touch button (Camera), rear boot upper lock, rear boot rubber, rear tail lamps, rear tail lamp side garnishes, rear end panel top garnish, rear floor panel under dust covering (Small), rear floor panel under dust covering (Big), rear bumper, rear bumper parktronic sensors, rear bumper parktronic sensor seal rings, rear bumper parktronic sensor wire harness, rear bumper parktronic sensor module, rear bumper towing cover, rear bumper reflectors, rear bumper side brackets, rear bumper frame (Top), rear bumper frame (Bottom), rear bumper reinforcement.

Heat / weld / cut / renew rear end panel, heat weld / cut / renew rear floor panel,
heat / weld / beating / pull / straighten / align rear chassis alignment jack.

Rear chassis frame by Chassis Aligment jack.

Programming rear bumper parktronic sensor module.

Total amount of Page 3 :

\$	1,800.00	8506
\$	450.00	22 X
\$	800.00	801
\$	3,050.00	

Tropical Tech Automobile Services

(Authorised Signature)
William Tan

Tropical Tech Automobile Services

Blk 5030, Ang Mo Kio Avenue 3, #01-201, Industrial Park 2, Singapore 569535

Tel : 6481 7773 / 6481 1403 Fax : 6484 4978

E-mail : tasc303@singnet.com.sg

Lonpac Insurance Bhd

300, Beach Road, #17-04 / 07,
The Concourse,
Singapore 199555

Estimate bill : TT 13 / 22 / TP / WT

Registration No : SLA7372H

Attn : Motor Claims Department
6250 7388
Tel : 6296 3767
Fax :

Make model : BMW 520ia (F10)

Mileage :

Date : 19 / 04 / 2022

**TRAFFIC ACCIDENT INVOLVING VEHICLE BEARING REGISTRATION NO : YP6714D AND SLA7372H
ALONG NEW BRIDGE ROAD (JUNCTION OF NEW BRIDGE ROAD AND PICKERING STREET) ON 17
APRIL 2022 AT ABOUT 0905HRS.**

To check & refit rear tail-lamp wiring harness.	\$	80.00	201
Under coating on rear damaged portion.	\$	150.00	601
Putty / primer application, spray painting rear boot, rear end panel, rear floor panel, rear bumper, rear bumper towing cover, rear bumper parktronic sensors.	\$	1,800.00	750
Balance amount brought from Page 1 :	\$	15,853.50	
Balance amount brought from Page 2 :	\$	4,878.80	
Balance amount brought from Page 3 :	\$	3,050.00	
Grand final amount :	\$	25,812.30	

Tropical Tech Automobile Services

(Authorised Signature)
William Tan