

ASS. REC. BY:

REF:

INC / 220036021K nyz

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

Consistent? : Yes or No

Consistent? : Yes or No

Res.: Yes or No

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rlm / STD A/Rlm or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

22/4 8320.20 Cahn (Red, #129, 29%)

Date/Time, File Pass to?

3/8/22

Date/Time, File Return to?

2)

Report Format:

Lump Sum / I.B.I. (\$

TP
320.20

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

Site Insp (\$

Interview (\$

Tech Invs (\$

Weekend (\$

Survey Fee:

Transportation:

S + RS \$

Fines

Others

TOTAL

SG 98 MOTOR PTE LTD

4001, Ang Mo Kio Industrial Park 1 #01-21 SINGAPORE 569622

Tel: 6452 4898 Fax: 6452 4868

Email: sg_motor_enterprise@yahoo.com.sg

Date: 18 April 2022

To : NTUC

Attn :

Tel:

VEHICLE NO : FBS 2114T

ACCIDENT DATE: 16 April 2022

FORSA 300

Description	Qty	Quotation \$
1 Rear Mudguard 210	1	CMA 280.00 ✓
2 Number Plate Holder	1	B1 68.00 385 ✓
Sub-Total		338.00
Less 10%		33.80
Sub-Total		304.20

Nett items

1 Rear number plate	B1 25.00 201m
2 Labour to remove/replace above parts	120.00 50L
Sub-Total	145.00
Nett Total	449.20

NB: This estimate was made from a visual inspection only, any other damage parts or labour require when repair commences, we will advise you and submit supplementary item to you accordingly.

Kindly revert upon completion. Thank you

SG 98 MOTOR PTE LTD

Not withered
Penny After Rain

Q320.20 1 day

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: