



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
ALLIANZ INSURANCE SINGAPORE PTE LTD 79 ROBINSON ROAD #09-01 SINGAPORE 068897			Ref: CS/AIS22003605/Uqy3n2 Date: 17/05/2022 Code: AIS	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	GBB 2767Z	Veh. Inspected	GBL 7526S
	Policy No.		Coverage (\$)	0.00
	Claim No.	2022 22004572FR	Excess (\$)	0.00
	Assign From	FLORA QUEK	Assign Date	19/04/2022
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA HIACE 2.O DX (A)	c.c	1998
	Engine No.	HIDDEN	Year of Reg.	2022
	Chassis No.	TRH2005049209	Colour	SILVER
	Odometer	2844 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195 R15	BRIDGESTONE	8 mm
	L/H Front Tyre	195 R15	BRIDGESTONE	8 mm
	R/H Rear Tyre	195 R15	BRIDGESTONE	8 mm
	L/H Rear Tyre	195 R15	BRIDGESTONE	8 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	16/04/2022	Inspection Date	20/04/2022
	Survey held at	Z-ONE AUTOMOTIVE PTE LTD 1 KAKI BUKIT AVENUE 6 #01-87 AUTOBAY@KAKI BUKIT SINGAPORE 417883		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	