

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Reg. No: 199607198R GST Reg. No. 19-9607198-R				
Affiliated to Federation Internationale Des Experts En Automobile					
	AUTO & GENERA	L INSURANCE (S) PL	Ref:	CS/AGI22003606/Acy3q2	
	(BUDGET DIRECT 190 CLEMENCEA SINGAPORE SHO 239924		Date:	19/08/2022	
			Code:	AGI	
1.	Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SMK 6995C	Veh. Inspected	SMA 5772M	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	C10014799/CD	Excess (\$)	0.00	
	Assign From	SHAFAWATI MD RABU	Assign Date	19/04/2022	
2.	2. Vehicle Particulars & Condition				
	Make & Model	HONDA SHUTTLE HYBRID	c.c	1496	
	Engine No.	HIDDEN	Year of Reg.	2018	
	Chassis No.	GP71211223	Colour	WHITE	
	Odometer	278637 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	NIL	
	General	GOOD			
3.	Conditions of Tyres				
		Size	Make	Balance	
	R/H Front Tyre	195/60 R15	HABILEAD	6 mm	
	L/H Front Tyre	195/60 R15	HABILEAD	6 mm	
	R/H Rear Tyre	195/60 R15	HABILEAD	6 mm	
	L/H Rear Tyre	195/60 R15	HABILEAD	6 mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	16/04/2022	Inspection Date	29/06/2022	
	Survey held at	N-51 AUTOMOTIVE PL			
		2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921			
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				

4 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: