



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Ref: CS/FCI22003607/Uvy3e2	
			Date: 01/07/2022	
			Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	YQ 5648M	Veh. Inspected	SND 7283S
	Policy No.		Coverage (\$)	0.00
	Claim No.	D22001114MFCV	Excess (\$)	0.00
	Assign From	HARMINDER KAUR	Assign Date	19/04/2022
2. Vehicle Particulars & Condition				
	Make & Model	HONDA SHUTTLE (A)	c.c	1496
	Engine No.	HIDDEN	Year of Reg.	2022
	Chassis No.	GK82201904	Colour	WHITE
	Odometer	1583 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	185/60 R15	YOKOHAMA	9 mm
	L/H Front Tyre	185/60 R15	YOKOHAMA	9 mm
	R/H Rear Tyre	185/60 R15	YOKOHAMA	9 mm
	L/H Rear Tyre	185/60 R15	YOKOHAMA	9 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	13/04/2022	Inspection Date	20/04/2022
	Survey held at	PRECISE AUTO SERVICE NO.1 KAKI BUKIT AVE 6 #02-34/36 SINGAPORE 417883		
5a. Remarks				
	A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	