



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### Affiliated to Federation Internationale Des Experts En Automobile

ALLIANZ INSURANCE SINGAPORE PTE LTD  
79 ROBINSON ROAD #09-01 SINGAPORE 068897

Ref: CS3/AIS22003608/Gqy3e2

Date: 06/05/2022

Code: AIS

#### 1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	SLD 3409Y	Veh. Inspected	SME 5837P
Policy No.		Coverage (\$)	0.00
Claim No.	NTAISCL2021-00009	Excess (\$)	0.00
Assign From	FLORA QUEK	Assign Date	19/04/2022

#### 2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

#### 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/60 R16	DUNLOP	6 mm
L/H Front Tyre	215/60 R16	DUNLOP	6 mm
R/H Rear Tyre	215/60 R16	DUNLOP	6 mm
L/H Rear Tyre	215/60 R16	DUNLOP	6 mm

#### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
--

#### 5. General Information

Accident Date	14/04/2022	Inspection Date	19/04/2022
Survey held at	APEX MOTORING 25 KAKI BUKIT ROAD 4 #01-55 SYNERGY @ KB SINGAPORE 417800.		

#### 5a. Remarks

<p>A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.</p> <p>B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.</p> <p>C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.</p> <p>D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,000-\$5,000</p>
---