

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/EG122003609/KTY3N2**Date:** 17/05/2022REFERENCE

Handling Insurer: ERGO Insurance Pte. Ltd. Policy No:

Claimant Vehicle No : SHB7793T **Insured Vehicle No :** YQ4790R

Date of Loss: 07/04/2022 Nature of Claim: TP Claim No: CDMCG22000648

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SHB7793T**

Make & Model: TOYOTA PRIUS, 1.8 5DR HATCHBACK (A) Engine No: 2ZR2C43488

Reg. Date: 16/08/2019 (Man. Year: 2018) Chassis No: JTDKB3FU703082712

Colour: Metallic Pearl White/Red Odometer: 373569 km

Engine Capacity: 1798 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65R15 Rear Tyre Size: 195/65R15

Front Left Side: Sailun 7 mm Rear Left Side: Sailun 7 mm

Front Right Side: Sailun 7 mm Rear Right Side: Sailun 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,077.45	1,077.45	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,600.00	140.00	2,460.00	94.62
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	3,677.45	1,217.45	2,460.00	66.89
+ GST 7.00/7.00% (S\$)	257.42	85.22	172.20	66.89
Nett Amount (S\$)	3,934.87	1,302.67	2,632.20	66.89

INSPECTION

Date of Assignment: 11/04/2022

Date Inspected: 08/04/2022 Inspected At: Trans-cab Auto Services Pte Ltd
No 2 Ang Mo Kio Street 63
Singapore 569111

Estimated Period of Repair: 1.0 days

Adjuster: KENNETH KONG**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 16 May 2022)
Parts:	144	TOYOTA PRIUS 1.8 5DR HATCHBACK (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHB7793T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*MIRROR ASSY,OUTER REAR VIEW,RH	Broken	1,436.60 FL	*1,436.60 FL
						F=Franchise part. L=ListItemDisc.
					Sub Total (\$\$)	1,436.60 1,436.60
					- List Item Discount on L Items 25.00/25.00% (\$\$)	359.15 359.15
					Total Parts (\$\$)	1,077.45 1,077.45

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO RUST-PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREAS	New	250.00	0.00
2	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	1,800.00	60.00
3	TO REMOVE AND REFIT DOOR MIRROR	New	380.00	60.00
4	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	20.00
Gross Labour Cost (\$\$)			2,600.00	140.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >