

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/AIG22003610/EPA3Q2**Date:** 25/07/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7210086950
Claimant Vehicle No :	SG5959P	Insured Vehicle No :	SNC1199Y
Date of Loss:	04/04/2022	Nature of Claim:	TP
		Claim No:	9969018566SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SG5959P	Engine No:	50350752335076
Make & Model:	MAN A95, 10.5 D (A)	Chassis No:	WMAA95ZZ6JF007545
Reg. Date:	20/09/2018 (Man. Year: 2018)	Odometer:	209355 km
Colour:	Multi-colour		
Engine Capacity:	10518 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	295/80 R22.5	Rear Tyre Size:	295/80 R22.5
Front Left Side:	Bridgestone 4 mm	Rear Left Side:	Bridgestone 4 mm
Front Right Side:	Bridgestone 4 mm	Rear Right Side:	Bridgestone 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,388.28	5,503.89	884.39	13.84
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,022.00	1,322.00	700.00	34.62
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,410.28	6,825.89	1,584.39	18.84
Approved Total (Overridden) (S\$)		5,750.00		
Nett Amount (S\$)	8,410.28	5,750.00	2,660.28	31.63
+ Loss of Use (3.0 x S\$350.00/day) (S\$)		1,050.00		
+ Doc/Search Fee (S\$)		7.00		
Nett Liability (S\$)		6,807.00		

INSPECTION

Date of Assignment:	18/04/2022	
Date Inspected:	18/04/2022	Inspected At: Strides Automotive Services Pte Ltd (Woodlands) 60 Woodlands Industrial Park E4 Singapore 757705
Estimated Period of Repair:	3.0 days	

Adjuster: CHEN TSUE YEE**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BELT AIR-CON :FOR MAN A95	Serviceable	272.85 F	*- FL
2	1		*FRP REAR BUMPER	Dented	1,875.00 F	*1,875.00 FL
3	1		*TAIL PIPE	Bent	3,525.68 F	*3,525.68 FL
4	1		*CABLE ROLLER 74X34	Broken	212.05 F	*212.05 FL
5	1		*BRACKET	Bent	475.70 F	*475.70 FL
6	1		*BELT ,V:RIBBED ,6PK 1880/21.16, MAN A22 BUS	Torn	27.00 F	*27.00 FL
					Sub Total (S\$)	6,388.28 6,115.43
					- List Item Discount on L Items 0.00/10.00% (S\$)	0.00 611.54
					Total Parts (S\$)	6,388.28 5,503.89

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS	New	1,590.00	1,060.00
2	PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	New	432.00	262.00
Gross Labour Cost (\$\$)			2,022.00	1,322.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >