



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 13/06/2022

User ID : CatherineLee

Section A - Accident Details	
Registration Number	SG5959P
Case Reference Number	BUS/04/22/5008
Registration Date	20/9/2018
Company Type	SMRT Buses Ltd
Make	MAN
Model	A95 MAN E6
Name of Driver	Zhang Ruifa
Type of Accident	Head to Rear
Accident Date and Time	4/4/2022 6:18 PM
Accident Reported Date and Time	14/4/2022 2:35 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24114629
Special Instruction to ARC,if any	SG5959P - Rear bumper dented. (Chain collision) SNC1199Y (TP) - INSURED WITH AIG
Prepared Date and Time	14/4/2022 3:32 PM
Chassis Number	WMAA95ZZ6JF007545
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates		
Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,590.00	\$1,060.00
Total Spray Cost	\$432.00	\$262.00
Total Spare Part Cost	\$4,599.57	\$4,403.11
Total Other Cost	\$0.00	\$0.00
TOTAL COST	\$6,621.57	\$5,725.11
Lump Sum Total	\$0.00	\$5,750.00
Number of Repair Days	4.0	3.0
Prepared / Adjusted By	Jeong Choon Hwee	STEVE CHEN
ARC / Surveyor Sign Off Date	14/04/2022 7:16 PM	18/04/2022 2:25 PM
Signature		
Remarks		

Section C - Quotation and Accident Invoice Details			
Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	

**SMRT Accident Vehicle Repair Estimates**

<b>SMRT Automotive Services Pte Ltd</b>
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 13/06/2022

User ID : CatherineLee

Section D - Details of Repair Estimates									
Part 1 - Labour Works									
Job Scope				Quotation from AR				Adjusted by Surveyor, if applicable	
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.				\$1,590.00				\$1,060.00✓	
Total Labour				\$1,590.00				\$1,060.00	
Part 2 - Spray Painting & Panel Beating Related Works									
Job Scope				Quotation from ARC				Adjusted by Surveyor, if applicable	
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS				\$432.00				\$262.00✓	
Total Spray Painting & Panel Beating				\$432.00				\$262.00	
Part 3 - Other Costs - Accident and Accident Repair Related Expense									
Job Scope				Quotation from ARC				Adjusted by Surveyor, if applicable	
Total Other Costs									
Part 4 - Spare Parts / Material Usage									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
6013696			BELT,AIR-CON:FOR MAN A95	1.00	\$272.85	100.00	\$0.00 ✗	Replace SVC	Not Given
6013481	Body	124-2-2-009-011	FRP REAR BUMPER	1.00	\$1,875.00	10.00	\$1,687.50 ✓	Replace DD	Replace
Total					\$2,147.85		\$1,687.50		
Added Spare Parts / Material Usage After Surveyor Signed off									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
		36-15201-5208	TAIL PIPE	1.00	\$3,525.68	10.00	\$3,173.11	Replace	Replace✓ BT
		51-95800-6111	CABLE ROLLER 74X34	1.00	\$212.05	10.00	\$190.85	Replace	Replace✓ BR
		51-95840-0315	BRACKET	1.00	\$475.70	10.00	\$428.13	Replace	Replace✓ BT
6010393			BELT,V:RIBBED,6PK 1880/21.16,MAN A22 BUS	1.00	\$27.00	10.00	\$24.30	Replace	Replace✓ TN
Total					4,240.43		3,816.39		

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date: