



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0285/2022/JT
DATE : 11-Apr-22
WIP : 19249

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 14/4/22

AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120
Attn: Motor Claims Dept
Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR TAN SIAN LIP
ADDRESS : BLK 6 ANGKLONG LANE
#06-04
SINGAPORE 579980
TELEPHONE : HP +65 91500205
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1800011575-04
VEHICLE NO : SLW 3784 M
MODEL CODE : AUDI A3 SEDAN 1.0 TFSI 8V
MODEL YEAR : 8/2/2018
ENGINE NO : CHZ 642950
CHASSIS NO : WAUZZZ8V0J1044087
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 9-Apr-22
PLACE OF ACCIDENT : ACROSS ROAD INSIDE FABER GARDEN CONDO

 PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLW 3784 M

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	S/N \$ 360.00 XNW	
2	TO REMOVE AND TRANSFER LHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 350.00 / 250	
3	TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER AND LHS HEADLIGHT. TO REPAIR BONNET. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 2,500.00 500 ✓	
4	TO RESPRAY FRONT BUMPER, BONNET AND LHS FRONT FENDER.	\$ 3,000.00 1100 ✓	
5	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00 / ✓	
TOTAL LABOUR CHARGES		: \$ 6,402.00	

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
 TEL 6366 2323 FAX 6361 1183
 EMAIL: MODA.PHAT@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLW 3784 M

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
1	FRONT BUMPER	1	\$ 2,433.00		Cur 1946.40
2	FRONT BUMPER FIXING PARTS	1	\$ 195.00		XNN
3	FRONT BUMPER GUIDE SECTION - LH	1	\$ 43.00		XSV
4	FRONT BUMPER GRILLE - CENTER	1	\$ 179.00		XNN
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTER	1	\$ 571.00		XNN
6	FRONT BUMPER CLOSING ELEMENT - LH	1	\$ 318.00		XSV
7	FRONT BUMPER TRIM COVER - LH	1	\$ 182.00		Scr 145.20
8	FRONT BUMPER ADAPTER - LH	1	\$ 42.00		XSV
9	RADIATOR GRILLE	1	\$ 1,578.00		XNN
10	RADIATOR GRILLE CLOSING ELEMENT	1	\$ 210.00		XSV
11	FRONT BUMPER AIR GUIDE GRILLE - LH	1	\$ 210.00		Scr 168
12	FRONT BUMPER FOAM FILLER PIECE	1	\$ 211.00		XSV
13	FRONT BUMPER REINFORCEMENT BEAM COVER	1	\$ 136.00		XSV
14	FRONT BUMPER REINFORCEMENT BEAM	1	\$ 847.00		XSV
15	AIR COND STICKER	1	\$ 9.00		XSV
16	"CAUTION" STICKER	1	\$ 16.00		XSV
17	HORN - LH	1	\$ 213.00		XSV
18	FRONT FENDER - LH	1	\$ 954.00		XV
19	FRONT FENDER POP RIVET	5	\$ 19.00		XSV
20	FRONT FENDER ATTACHMENT PARTS	1	\$ 75.00		XSV
SUB TOTAL SPARE PARTS		:	\$ 8,441.00		

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6041 1183
 EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLW 3784 M

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
21	FRONT FENDER BRACKET - LH	1	\$	46.00	X SVC
22	FRONT FENDER BRACE	1	\$	107.00	X SVC
23	FRONT WHEEL HOUSING LINER - LH	1	\$	183.00	X SVC
24	HEADLIGHT - LH	1	\$	5,879.00	/Scr 4,703.20
25	LIFT CYLINDER - LH	1	\$	156.00	Xc
26	LIFT CYLINDER HOSE - LH	1	\$	78.00	X SVC
27	OUTSIDE TEMPERATURE SENSOR BRACKET	1	\$	21.00	X SVC
28	RADIATOR AIR GUIDE - LH	1	\$	28.00	X SVC
29	RADIATOR AIR GUIDE - UPPER CENTER	1	\$	14.00	X SVC
30	BONNET CATCH HOOK	1	\$	71.00	X SVC
31	FRONT NO PLATE	S/N	\$	80.00	X SVC
32	SUNDRIES		\$	300.00	by 1, X SVC
TOTAL SPARE PARTS		:	\$	15,404.00	
TOTAL LABOUR CHARGES		:	\$	6,402.00	
GRAND TOTAL		:	\$	21,806.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

◆ PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

Thuan
14/4/22 1045
PIP 4 days

PLEASE NOTE :

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE
AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER
LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF
REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO
MS. NORA KHAI AT TEL: 6768 9828 / 6768 9911 FOR
APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT