

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0285/2022/JT
DATE : 11-Apr-22
WIP : 19249

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 14/4/22

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

Hi Thevan
4 days - ok -Johnn
22-Jun-22

OWNER'S NAME : MR TAN SIAN LIP
ADDRESS : BLK 6 ANGKLONG LANE
#06-04
SINGAPORE 579980
TELEPHONE : HP +65 91500205
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1800011575-04
VEHICLE NO : **SLW 3784 M**
MODEL CODE : AUDI A3 SEDAN 1.0 TFSI 8V
MODEL YEAR : 8/2/2018
ENGINE NO : CHZ 642950
CHASSIS NO : WAUZZZ8V0J1044087
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 9-Apr-22
PLACE OF ACCIDENT : ACROSS ROAD INSIDE FABER GARDEN CONDO



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLW 3784 M

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS	
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	S/N \$	360.00		
2	TO REMOVE AND TRANSFER LHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$	350.00	\$	250.00
3	TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER AND LHS HEADLIGHT. TO REPAIR BONNET. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	2,500.00	\$	500.00
4	TO RESPRAY FRONT BUMPER, BONNET AND LHS FRONT FENDER.	\$	3,000.00	\$	1,100.00
5	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	\$	192.00
TOTAL LABOUR CHARGES		:	\$ 6,402.00	\$	2,042.00

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLW 3784 M

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER	1	\$ 2,433.00	\$ 1,946.40
2	FRONT BUMPER FIXING PARTS	1	\$ 195.00	
3	FRONT BUMPER GUIDE SECTION - LH	1	\$ 43.00	
4	FRONT BUMPER GRILLE - CENTER	1	\$ 179.00	
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTER	1	\$ 571.00	
6	FRONT BUMPER CLOSING ELEMENT - LH	1	\$ 318.00	
7	FRONT BUMPER TRIM COVER - LH	1	\$ 182.00	\$ 145.20
8	FRONT BUMPER ADAPTER - LH	1	\$ 42.00	
9	RADIATOR GRILLE	1	\$ 1,578.00	
10	RADIATOR GRILLE CLOSING ELEMENT	1	\$ 210.00	
11	FRONT BUMPER AIR GUIDE GRILLE - LH	1	\$ 210.00	\$ 168.00
12	FRONT BUMPER FOAM FILLER PIECE	1	\$ 211.00	
13	FRONT BUMPER REINFORCEMENT BEAM COVER	1	\$ 136.00	
14	FRONT BUMPER REINFORCEMENT BEAM	1	\$ 847.00	
15	AIR COND STICKER	1	\$ 9.00	
16	"CAUTION" STICKER	1	\$ 16.00	
17	HORN - LH	1	\$ 213.00	
18	FRONT FENDER - LH	1	\$ 954.00	
19	FRONT FENDER POP RIVET	5	\$ 19.00	
20	FRONT FENDER ATTACHMENT PARTS	1	\$ 75.00	
SUB TOTAL SPARE PARTS			\$ 8,441.00	\$ 2,259.60

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLW 3784 M

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
		<i>c/f</i>		<i>\$ 1,159.60</i>
21	FRONT FENDER BRACKET - LH	1	\$ 46.00	
22	FRONT FENDER BRACE	1	\$ 107.00	
23	FRONT WHEEL HOUSING LINER - LH	1	\$ 183.00	
24	HEADLIGHT - LH	1	\$ 5,879.00	<i>\$ 4,703.20</i>
25	LIFT CYLINDER - LH	1	\$ 156.00	
26	LIFT CYLINDER HOSE - LH	1	\$ 78.00	
27	OUTSIDE TEMPERATURE SENSOR BRACKET	1	\$ 21.00	
28	RADIATOR AIR GUIDE - LH	1	\$ 28.00	
29	RADIATOR AIR GUIDE - UPPER CENTER	1	\$ 14.00	
30	BONNET CATCH HOOK	1	\$ 71.00	
31	FRONT NO PLATE	S/N	\$ 80.00	
32	SUNDRIES		\$ 300.00	
TOTAL SPARE PARTS			\$ 15,404.00	\$ 6,962.80
TOTAL LABOUR CHARGES			\$ 6,402.00	\$ 2,042.00
GRAND TOTAL			\$ 21,806.00	\$ 9,004.80

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

SPARE PARTS ARE SPECIAL NETT.

bl-27/05/22

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT