

COMFORTDELGRO ENGINEERING PTE LTD
#205 Braddell Road
Blk C Ext 1 3rd Level
Singapore 579701



VICOM LTD
385 Sin Ming Drive Singapore 575718

Mainline (65) 6458 4555
Facsimile (65) 6458 1040

www.vicom.com.sg
Company Registration No: 100100320K

SURVEY REPORT

GENERAL INFORMATION			
VAC Ref. No.	: 525563	Claim No.	: 305143026
Accident Date	: 17/04/2018	Claim Type	: THIRD PARTY
Assignment Date	: 18/04/2018	Policy No.	:
Survey Date	: 18/04/2018	Finalised Dt.:	:
Survey Report Date	: 25/04/2018		

VEHICLE PARTICULARS			
Vehicle No.	: SH7927M	Chassis No.	: KMLB41UMEU053704
Registration Date	: 30/04/2014	Engine No.	: OBSCURED
Make	: HYUNDAI	Engine Cap.	: 1685 CC
Model	: I-40	Transmission	: AUTO
		Colour	: BLUE

CONDITION OF VEHICLE DURING SURVEY (VISUAL and STATIC TEST ONLY)			
Foot Brake	: SERVICEABLE	Steering	: SERVICEABLE
Hand Brake	: SERVICEABLE	Modification	: NONE
Mileage	: 560606KM		

<u>TYRES</u>	<u>SIZE</u>	<u>MAKE</u>	<u>BALANCE (mm)</u>
FRONT RH	205/60R16	WESTLAKE	6
FRONT LH	205/60R16	WESTLAKE	6
REAR RH	205/60R16	WESTLAKE	6
REAR LH	205/60R16	WESTLAKE	6

SURVEY CONDUCTED AT	
ComfortDelGro Engineering Pte Ltd, 59 Loyang Drive Singapore 508969. Assignment given by: MVA Jumari (C.D.G.E.)	

REMARKS	
[1] Workshop Estimate : S\$ 16,989.12	
[2] Our Adjustment : S\$ 7,000.00	
[3] Repair Period : 4 days ✓	
[4] We have not authorised repairs. This survey was carried out on without prejudice basis.	

Sin Ming
385 Sin Ming Drive Singapore 575718

Bukit Batok
511 Bukit Batok St 23 Singapore 659545

Kaki Bukit
23 Kaki Bukit Ave 4 Singapore 415933

VICOM LTD

SH7927M @ 17/04/2018

SURVEY REPORT

Annex A: Adjustment on Spare Parts

#	Qty	Vehicle Parts Description	Condition	Workshop Estimate (S\$)	VAC Adjustment (S\$)
1	1	Radiator Grille	Reuse	294.35	0.00
2	1	Radiator Grille H Emblem	Reuse	113.65	0.00
3	1	Front Bumper	Deformed	562.30	562.30
4	1	Front Bumper Sponge	Reuse	142.30	0.00
5	1	Front Bumper Reinforcement	Dented	526.10	526.10
6	1	Front Bumper Grille Lh	Missing	40.30	40.30
7	1	Front Bumper Centre Grille	Reuse	176.90	0.00
8	2	Front Bumper Bracket Top Rh/Lh	Distorted	44.80	44.80
9	2	Front Bumper Bracket Rh/Lh	Distorted	49.20	49.20
10	1	Headlamp Support Top Cover	Snapped	398.00	398.00
11	1	Headlamp Support Panel	Snapped	1067.50	1067.50
12	2	Headlamp Rh/Lh	Snapped	2776.00	2276.00
13	1	Front Fender Lh	Bent	619.00	619.00
14	1	Front Fender Apron Panel Lh	Repair	1575.50	0.00
15	1	Front Fender Shield Lh	Deformed	169.80	169.80
16	1	Front Fender Retainer	Necessary	9.20	9.20
17	2	Front Wheel Rim Lh/Rh	Dented	594.20	594.20
18	2	Front Wheel Hub Cap Rh/Lh	Snapped	301.40	301.40
19	1	Front Wheel Bearing	Reuse	258.50	0.00
20	2	Front S/Absorber Lh/Rh	Distorted	684.40	684.40
21	2	Front S/Absorber Mounting Lh/Rh	Distorted	150.20	150.20
22	1	Front Driveshaft Lh	Reuse	1069.55	0.00
23	1	Rack & Pinion Assy	Reuse	2184.00	0.00
24	2	Steering Tie End Lh/Rh	Bent	139.00	139.00
25	1	Stabilizer Bar	Reuse	222.50	0.00
26	1	Stabilizer Bar Bush Lh	Reuse	13.50	0.00
27	1	Stabilizer Bar Link	Reuse	81.70	0.00
28	1	Stabilizer Bar Bracket	Reuse	24.00	0.00
29	1	Front Suspension Lower Arm Lh	Distorted	715.10	715.10
30	1	Front Chassis Member Lh	Repair	1575.85	0.00
31	1	Knuckle Arm Lh	Reuse	582.95	0.00
32	1	Air Cleaner Assy	Snapped	128.40	128.40
Subtotal				17290.15	8474.90
Less 20 %				3458.03	1694.98
TOTAL				13832.12	6779.92

#	Qty	Vehicle Parts Description	Condition	Workshop Estimate (S\$)	VAC Adjustment (S\$)
SPECIAL NETT ITEM					
1	1	Front Number Plate	Reuse	25.00	0.00
2	1	Front Number Plate	Reuse	30.00	0.00
3	2	Front Tyre Rh/Lh - Depreciation 40 %	Cut/ Abraded	432.00	259.20
TOTAL				487.00	259.20
TOTAL FOR SPARE PARTS				14319.12	7039.12

LONPAC INTERNAL-CONFIDENTIAL

VICOM LTD

SURVEY REPORT

Annex B: Adjustment on Labour and Spray Painting

#	Job Description	Workshop Estimate (S\$)	VAC Adjustment (S\$)	
1	Panel beating	1000.00	600.00	
2	Spray painting	750.00	540.00	
3	Wiring charges	50.00	30.00	2ol
4	Tuff kote	50.00	40.00	3ol
5	Towing charge - crane up	150.00	150.00	
6	Remove/ refix aircon & refill gas	150.00	60.00	
7	Remove/ refix undercarriage front	400.00	200.00	
8	Front wheel alignment	120.00	80.00	6ol
TOTAL FOR LABOUR AND SPRAY PAINTING		2670.00	1700.00	

Summary

Description	Workshop Estimate (S\$)	VAC Adjustment (S\$)
TOTAL FOR SPARE PARTS	14319.12	7039.12
TOTAL FOR LABOUR AND SPRAY PAINTING	2670.00	1700.00
TOTAL REPAIR COST	16989.12	8739.12

VICOM LTD
SURVEY REPORT
Annex C: Conclusion

SH7927M @ 17/04/2018

ASSESSOR'S REPORT

At the place of inspection, we saw this vehicle sustained front damage.

The damages seen during our survey were at front bumper, both headlamps, headlamp support panel, front n/s fender, front n/s apron panel, both front tyres, front undercarriage and surrounding areas. A fuller detailed description of the damages is in Annex A of this survey report.

ASSESSOR'S RECOMMENDATION

Comfortdelgro Engineering Pte Ltd (Loyang) estimated a repair cost of S\$16,989.12. We adjusted it to S\$8,739.12.

Accordingly, we recommend repairs to this vehicle be carried out on a lumpsum basis at S\$7,000.00.

The repairs would require a period of 4 working days.



Kamarudin Abdul Kadir
for VICOM Ltd

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Company
Owner ID: 3821R

Vehicle Details

Vehicle No.: SH7927M
Vehicle to be Exported: No
Intended De-registration Date: 04 May 2018
Vehicle Make: HYUNDAI
Vehicle Model: I40 1.7L CRDI AT ABS AIRBAG 4DR

Primary Colour: Blue
Manufacturing Year: 2014
Engine No.: D4FDEU410267
Chassis No.: KMHLB41UMEU053704
Maximum Power Output: 100.0 kW (134 bhp)
Open Market Value: \$18,610.00
Original Registration Date: 30 Apr 2014
First Registration Date: 30 Apr 2014
Transfer Count: 0
Actual ARF Paid: \$11,110.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 29 Apr 2022
PARF Rebate Amount: \$8,332.00

Intended COE Rebate Details

COE Expiry Date: 29 Apr 2022
COE Category: A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years): 8
PQP Paid: \$59,871.00
COE Rebate Amount: \$29,831.00
Total Rebate Amount: \$38,163.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.
The information contained herein is correct as at 04 May 2018

OK

Enquire Road Tax Expiry Date (Details)

Vehicle Particulars

Vehicle No.:	SH7927M
Road Tax Expiry Date:	29 Oct 2018
Vehicle Make:	HYUNDAI
Vehicle Model:	I40 1.7L CRDI AT ABS AIRBAG 4DR
Please note:	

The information contained herein is correct as at 04 May 2018 / 11:05.

OK

Save as PDF

LONPAC INTERNAL-CONFIDENTIAL