



# National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 4019R

| Qty  | Description of Parts                                      | Condition            | Estimate By Workshop (\$) | Our Adjusted (\$) |
|--|---|----------------------|---------------------------|-------------------|
|  | <b><u>REPLACEMENT OF PARTS</u></b>                        |                      |                           |                   |
| 1  | COVER-RR BUMPER   | TO REPAIR SEE LABOUR | 459.40                    | -                 |
| 10   | BUMPER COVER CLIP REAR                                    | NOT NECESSARY        | 22.00                     | -                 |
|  | LESS 20% DISCOUNT   |                      | -96.28                    | -                 |
|  |   |                      | 385.12                    | -                 |
|  | <b><u>SPECIAL NETT ITEMS</u></b>                          |                      |                           |                   |
| 1  | PROTECTOR MAT (SN)  | NOT NECESSARY        | 50.00                     | -                 |
|  |   |                      | 50.00                     | -                 |
|  | <b><u>LABOUR</u></b>                                      |                      |                           |                   |
|  | PANEL BEATING.INCLUSIVE OF THE REPAIR OF COVER-RR BUMPER. |                      | 600.00                    | 350.00            |
|  | SPRAYPAINT CHARGE.  |                      | 600.00                    | 250.00            |
|  | REMOVE/REFIX REVERSE SENSOR.                              | NOT NECESSARY        | 50.00                     | -                 |
|  |   |                      | 1,250.00                  | 600.00            |
|  | <b>GRAND TOTAL</b>  |                      | <b>1,685.12</b>           | <b>600.00</b>     |
| <b>RECOMMENDED COST OF REPAIRS (CONFIRMED)</b> |   |                      |                           | <b>600.00</b>     |

Report Ref No. NS/INC22003647/Gvcn2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,  
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.