

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0303/2022/NK
DATE : 18-Apr-22
WIP : 19897

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 19/4/2022

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR RICHARD KOH CHOON CHYE
ADDRESS : 33 SOO CHOW WAY
SINGAPORE 575326
TELEPHONE : HP +65 96391708
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 2100482584-05
VEHICLE NO : **SDS 3882 D**
MODEL CODE : AUDI A3 SEDAN 1.4 TFSI
MODEL YEAR : 16/9/2016
ENGINE NO : CZC 556088
CHASSIS NO : WAUZZZ8V0G1098689
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 13-Apr-22
PLACE OF ACCIDENT : 795 UPPER SERANGOON ROAD
OPPOSITE CALTEX STATION

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SDS 3882 D

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	S/N \$ 360.00	X
2	TO REMOVE AND TRANSFER BOTH HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 350.00	X
3	TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER AND LHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	\$ 2,100.00	1000 ✓
4	TO RESPRAY FRONT BUMPER AND LHS FRONT FENDER.	\$ 2,000.00	1100 ✓
5	TO RENEW LHS FRONT RIM. TO CARRY OUT PRE/POST WHEEL ALIGNMENT.	S/N \$ 520.00	280 ✓
6	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓ ✓
TOTAL LABOUR CHARGES		: \$ 5,522.00	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SDS 3882 D

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER <i>Dehnd</i>	1	\$ 2,377.00 ✓	1901.60
2	FRONT BUMPER FIXING PARTS <i>Not n</i>	1	\$ 195.00 +	
3	FRONT BUMPER COVER TRIM LH <i>Not n</i>	1	\$ 182.00 +	
4	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>Not n</i>	1	\$ 175.00 +	
5	FRONT BUMPER PULL STRAP - LOWER <i>Not n</i>	4	\$ 231.00 +	
6	FRONT BUMPER GUIDE SECTION LH ?	1	\$ 43.00 ?	X nn
7	FRONT BUMPER AIR GUIDE GRILLE - LH <i>Not n</i>	1	\$ 122.00 +	
8	FRONT FENDER - LH <i>Dented</i>	1	\$ 954.00 ✓	763.20
9	FRONT FENDER ATTACHMENTS PARTS <i>Not n</i>	1	\$ 75.00 +	
10	FRONT FENDER BRACKET ?	1	\$ 46.00 X	nn
11	FRONT FENDER BRACE ?	1	\$ 107.00 X	nn
12	WHEEL HOUSING LINER LH <i>Not n</i>	1	\$ 183.00 +	
13	WHEEL HOUSING LINER ATTACHMENT PARTS <i>Not n</i>	1	\$ 93.00 +	
14	HEADLIGHT- LH <i>Not n</i>	1	\$ 2,810.00 +	
15	HEADLIGHT LIFT CYLINDER LH ?	1	\$ 211.00 +	
16	LIFT CYLINDER HOSE } <i>Not n</i>	1	\$ 204.00 +	
17	WATER RESERVOIR TANK }	1	\$ 225.00 +	
18	ALUMINIUM RIM - FRONT LH <i>Not</i>	1	\$ 1,303.00 ✓	1042.4
19	ALUMINIUM RIM RUBBER VALVE <i>Not n</i>	4	\$ 15.00 +	
20	SUNDRIES ?	1	\$ 300.00 ✓	23.76 nec
TOTAL SPARE PARTS		:	\$ 9,851.00	
TOTAL LABOUR CHARGES		:	\$ 5,522.00	
GRAND TOTAL		:	\$ 15,373.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian L*
SURVEYED DATE : *19/04/22*
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : *are Authorised, 05 Days*

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE
AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER
LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF
REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO
MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR
APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT