



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
ALLIANZ INSURANCE SINGAPORE PTE LTD 79 ROBINSON ROAD #09-01 SINGAPORE 068897			Ref: CS/AIS22003662/Gvy3m4 Date: 03/01/2023 Code: AIS	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SMJ 9095K	Veh. Inspected	SLV 4709E	
Policy No.		Coverage (\$)	0.00	
Claim No.	BISAI SCL2022-00468FQ	Excess (\$)	0.00	
Assign From	SHANTI	Assign Date	20/04/2022	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA COROLLA AXIO HYBRID 1.5	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	NKE1657144256	Colour	BEIGE	
Odometer	453571 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/60R15	TOYO	6 mm	
L/H Front Tyre	185/60R15	TOYO	6 mm	
R/H Rear Tyre	185/60R15	TOYO	6 mm	
L/H Rear Tyre	185/60R15	TOYO	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	23/03/2022	Inspection Date	20/04/2022	
Survey held at	TRIDENT AUTO SERVICE CENTRE PTE LTD 8 KAKI BUKIT AVENUE 4, #02-42, PREMIER @ KAKI BUKIT, SINGAPORE 415875			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	