

**Trident Auto Service Centre Pte Ltd**  
 8 Kaki Bukit Ave 4, #02-42  
 Premier @ Kaki Bukit (Gate 1)  
 Singapore 415875  
 Tel: 6344 1918

**Allianz Insurance Singapore Pte Ltd**  
 12 Marina View #14-01 Asia Square Tower 2  
 Singapore 018961

**LKK Auto Consultants** hence notify  
 the Repairer of the following:  
 Date of survey: 24/03/2022  
 Vehicle: SLV4709E during resurvey  
 Make/Model: TOYOTA AXIO-HYBRID  
 Year: 2017  
 Chassis: NKE1657144256  
 ACC Date: 23/03/2022  
 Signature: \_\_\_\_\_  
 Date: \_\_\_\_\_

| S/N | Qty | Description & Specification | Estimate | Amount S\$ |
|-----|-----|-----------------------------|----------|------------|
|-----|-----|-----------------------------|----------|------------|

| <u>List Items</u> |   |                                  |                      |                   |
|-------------------|---|----------------------------------|----------------------|-------------------|
| 1                 | 1 | Rear boot lid                    | Q5                   | \$798.50          |
| 3                 | 1 | Rear boot lock                   |                      | \$185.15          |
| 4                 | 1 | Rear boot rubber                 | Cut                  | \$211.50          |
| 5                 | 1 | Rear boot "AXIO" emblem          |                      | \$68.50           |
| 6                 | 1 | Rear boot "CAROLLA" emblem       | MC                   | \$62.60           |
| 7                 | 1 | Rear boot "HYBRID" emblem        | NN                   | \$78.00           |
| 8                 | 1 | Rear boot outer moulding         | X                    | \$240.00          |
| 9                 | 1 | Rear left taillamp               | Cut                  | \$481.30          |
| 10                | 1 | Rear left taillamp lower bracket | X <del>BR</del> ✓ BR | \$95.00           |
| 12                | 1 | Rear end panel                   | Repair X             | \$608.80          |
| 13                | 1 | Rear end panel inner garnish     | ✓ / BR               | \$195.00          |
| 14                | 1 | Rear bumper                      | ✓ RE                 | \$1,014.30        |
| 15                | 1 | Rear bumper top brackets LH      | X NN                 | \$87.90           |
| 16                | 1 | Rear bumper reflectors LH        | ✓ <del>BR</del>      | \$82.00           |
| 17                | 1 | Rear bumper side retainers LH    | ✓ Cut                | \$71.90           |
| 18                | 1 | Rear fender LH                   | X Repair             | \$987.50          |
| 19                | 1 | Rear fender inner cowling LH     | X NN                 | \$125.00          |
| 20                | 1 | Rear fender inner trim           | X                    | \$475.00          |
| <b>Total</b>      |   |                                  |                      | <b>\$5,867.95</b> |
| <b>Less 25%</b>   |   |                                  |                      | <b>\$1,466.99</b> |
| <b>List Total</b> |   |                                  |                      | <b>\$4,400.96</b> |

| <u>S/Nett Items</u> |       |                  |      |                 |
|---------------------|-------|------------------|------|-----------------|
| 1                   | 1 set | Rear bumper clip | ✓ MC | \$80.00         |
| 2                   | 1 set | Reverse sensor   | X NN | \$350.00        |
| <b>S/Nett Total</b> |       |                  |      | <b>\$430.00</b> |

| <u>Labour</u>       |  |                                                      |  |                   |
|---------------------|--|------------------------------------------------------|--|-------------------|
| 1                   |  | To panel beating, removal and replacing parts        |  | \$800.00 400      |
| 2                   |  | Remove and refix reverse sensor and distance setting |  | \$80.00 40        |
| 3                   |  | To putty and respray on accident portion             |  | \$800.00 600      |
| 4                   |  | To check wiring                                      |  | \$80.00 30        |
| 5                   |  | To apply anti-rust corrosion on affected areas       |  | \$60.00 X NN      |
| <b>Labour Total</b> |  |                                                      |  | <b>\$1,820.00</b> |
| <b>Grand Total</b>  |  |                                                      |  | <b>\$6,650.96</b> |

Trident Auto Service Centre Pte Ltd

4 Days  
 45 After repair photos.  
 Gino Riano  
 20/4/22